

PREPARED BY
TorqueMech QA
Mechanic: QA Tech
Phone: 555-0199

VEHICLE
2020 Lexus GS350
Estimate prepared for customer review and approval.

Repair Services (1)

Professional estimate line items with status, notes, and totals

**Extremely Long Front Suspension Control Arm
Bushing and Ball Joint Diagnostic Replacement
Package With Alignment Verification**

Status: Diagnosed

Labor \$504 | Parts \$225 | 4.8 labor hrs

\$729

ESTIMATE SUMMARY

Estimated Total

Includes quoted services, labor, parts, travel, and selected PDF details.
1 quoted service ready for customer review.

\$729
Customer estimate total

Customer Reviewed Estimate
Customer reviewed the estimate details. No signature was captured.
No payment is collected or recorded on this PDF.
Customer: QA Customer
Phone: 555-0100