

PREPARED BY

TorqueMech QA

Mechanic: QA Tech
Phone: 555-0199
Spacing QA for repair rows and signature card.

VEHICLE

2016 Lexus GX470

Estimate prepared for customer review and approval.

Repair Services (3)

Professional estimate line items with status, notes, and totals

Front Brake Pads Replacement

Status: Urgent

Labor \$200 | Parts \$96 | Travel \$25 | 1.6 labor hrs | \$125/hr

Estimate note
Brake job price may vary if guide pins are seized, rotor screws are stuck, hardware is rusted, calipers need service, or rotors require extra removal time.

Inspection notes
Pads are worn low and braking noise is present. Confirm rotor thickness before final repair.

Labor breakdown

- Lift vehicle and remove wheels (0.2 hr)
- Inspect pads, caliper slides, and hardware (0.3 hr)
- Replace pads and service contact points (0.6 hr)
- Reassemble, torque wheels, and verify pedal feel (0.4 hr)

\$321

Alternator Replacement and Charging System Verification

Status: Diagnosed

Labor \$275 | Parts \$285 | 2.2 labor hrs | \$125/hr

Estimate note
Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required.

Inspection notes
Charging voltage is below specification under load. Battery test should be repeated after repair.

Labor breakdown

- Disconnect battery and inspect belt routing (0.3 hr)
- Access alternator and electrical connections (0.6 hr)
- Replace alternator and set belt tension path (0.8 hr)
- Verify charging output and warning lights (0.6 hr)

\$560

2016 Lexus GX470

Services (continued)

Timing Chain Tensioner Replacement With Startup Rattle Diagnosis and Oil Leak Inspection

Status: Recommended

Labor \$600 | Parts \$265 | Travel \$35 | 4.8 labor hrs | \$125/hr

Estimate note

Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required.

Inspection notes

Startup rattle is present after overnight cold soak. Confirm oil level, timing cover seepage, and tensioner access before final repair.

Labor breakdown

- Component access (1.2 hr)

- Disconnect surrounding parts (1.0 hr)

- Remove and install parts (1.7 hr)

- Reassembly and verification (1.0 hr)

\$900

ESTIMATE SUMMARY

Estimated Total

Includes quoted services, labor, parts, travel, and selected PDF details.
3 quoted services ready for customer review.

\$1,781

Customer estimate total

Final price may vary based on vehicle condition, seized hardware, rust, additional diagnostics, or unseen issues discovered during repair.

Signed Customer Approval

Customer signed after reviewing the estimate details.
Estimate approval only. No payment is collected or recorded on this PDF.
Customer: Signed QA Customer
Phone: 555-0100

Customer-facing notes
Customer requested approval-ready estimate after inspection. Confirm parts availability before scheduling.

Signed Customer Approval

Signature confirms the customer reviewed the estimate details above and approves the estimate.

Signature could not be rendered

Estimate approval only. No payment is collected or recorded on this PDF.

Generated with TorqueMech