

PREPARED BY

TorqueMech QA

Mechanic: QA Tech | Phone: 555-0199

Spacing QA for repair rows and signature card.

Vehicle: 2016 Lexus GX470

Estimate prepared for customer review and approval.

Repair Services • 3 quoted services

Labor, parts, travel, and repair status by line

Service	Labor	Parts	Line Total
Front Brake Pads Replacement	\$200	\$96	\$321
Status: Urgent Labor Hours: 1.6h Rate: \$125/hr Labor \$200 Parts \$96 Travel \$25 Estimate note Brake job price may vary if guide pins are seized, rotor screws are stuck, hardware is rusted, calipers need service, or rotors require extra removal time. Inspection notes Pads are worn low and braking noise is present. Confirm rotor thickness before final repair. Labor breakdown - Lift vehicle and remove wheels - Inspect pads, caliper slides, and hardware - Replace pads and service contact points - Reassemble, torque wheels, and verify pedal feel			
Alternator Replacement and Charging System Verification	\$275	\$285	\$560
Status: Diagnosed Labor Hours: 2.2h Rate: \$125/hr Labor \$275 Parts \$285 Estimate note Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required. Inspection notes Charging voltage is below specification under load. Battery test should be repeated after repair. Labor breakdown - Disconnect battery and inspect belt routing - Access alternator and electrical connections - Replace alternator and set belt tension path - Verify charging output and warning lights			

Repair Estimate

Generated: 2026-05-22 19:46



2016 Lexus GX470

Services (continued)

Service	Labor	Parts	Line Total
Timing Chain Tensioner Replacement With Startup Rattle Diagnosis and Oil Leak	\$600	\$265	\$900
Status: Recommended Labor Hours: 4.8h Rate: \$125/hr Labor \$600 Parts \$265 Travel \$35			
Estimate note Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required.			
Inspection notes Startup rattle is present after overnight cold soak. Confirm oil level, timing cover seepage, and tensioner access before final repair.			
Labor breakdown			
- Component access			1.2 hr
- Disconnect surrounding parts			1.0 hr
- Remove and install parts			1.7 hr
- Reassembly and verification			1.0 hr

CUSTOMER QUOTE TOTAL
Services, labor, parts, travel, and selected PDF details included
3 quoted services ready for customer review

\$1,781
Estimated total

Final price may vary based on vehicle condition, seized hardware, rust, additional diagnostics, or unseen issues discovered during repair.

Signed Customer Approval
Customer signed after reviewing the estimate details.
Estimate approval only. No payment is collected or recorded on this PDF.
Customer: Signed QA Customer
Phone: 555-0100

Customer-facing notes

Customer requested approval-ready estimate after inspection. Confirm parts availability before scheduling.

Signed Customer Approval
Signature confirms the customer reviewed the estimate details above and approves the estimate.

Signature could not be rendered

Estimate approval only. No payment is collected or recorded on this PDF.