

Kevin Ndizihiwe <k.ndizihiwe@ea-africaexchange.com>

Additional D-Link Wi-Fi Range Extender Installed During Starlink Deployment

4 messages

Kevin Ndizihiwe <k.ndizihiwe@ea-africaexchange.com>

Tue, Apr 29, 2025 at 4:34 PM

To: Kellen Kayitesi <k.kayitesi@ea-africaexchange.com>, Harriet Mutoni <h.mutoni@ea-africaexchange.com>

Dear Kellen,

I hope you are doing well.

This is to inform you that during the installation of **Starlink internet** at the **Head Office** and **Bugesera Silo**, we added an extra **D-Link Wi-Fi range extender** at each site to ensure optimal wireless coverage expansion.

Thanks.

--

Kevin NDIZIHIWE

Head of ICT and Market Data
East Africa Exchange | EAX
Silverback Mall Building, Roof Top Floor
Sonatube | KK 15 Rd

Kigali, Kicukiro

Tel: +250 785280956

email:k.ndizihiwe@ea-africaexchange.com

skype:kevin.ndizihiwe

Kellen Kayitesi <k.kayitesi@ea-africaexchange.com>

To: Kevin Ndizihiwe <k.ndizihiwe@ea-africaexchange.com>

Cc: Harriet Mutoni <h.mutoni@ea-africaexchange.com>

Dear Kevin,

Does this have any implications on prices? If so, by how much?

Thanks

[Quoted text hidden]

Kevin Ndizihiwe <k.ndizihiwe@ea-africaexchange.com>

Tue, Apr 29, 2025 at 4:50 PM

Tue, Apr 29, 2025 at 4:38 PM

To: Kellen Kayitesi <k.kayitesi@ea-africaexchange.com> Cc: Harriet Mutoni <h.mutoni@ea-africaexchange.com>

Dear Kellen,

Yes, the addition of the two D-Link Wi-Fi range extenders has a minor cost implication. We are filling on a request form and the proforma invoice will be attached for your reference, which includes the unit price and total amount.

Thanks.

[Quoted text hidden]

Kevin Ndizihiwe <k.ndizihiwe@ea-africaexchange.com>
To: Kellen Kayitesi <k.kayitesi@ea-africaexchange.com>
Cc: Harriet Mutoni <h.mutoni@ea-africaexchange.com>

Wed, Apr 30, 2025 at 11:20 AM

Dear Kellen,

I'd like to clarify the reason for installing additional WiFi extenders at both the Head Office and Bugesera Silo.

At the Head Office, the current router's signal coverage only reaches from the IT Office up to the Finance Office. However, areas such as the CFO's office, CEO's office, and Reception Office do not receive a stable connection, necessitating the addition of an extender to ensure seamless connectivity across all offices.

Similarly, at the Bugesera Silo, the existing WiFi signal only covers the Manager's Office and the Weighbridge Office but does not reach the Control Room. An extender is required to bridge this gap and provide reliable network access in the Control Room as well.

Thanks.

[Quoted text hidden]