

Document Details:

Document Title:

Document Type

SOP

Document Number

EAX/OP/SOP/004

Document Location

QUALITY CONTROL

Page

Page 1 of 4

Author				
Name	Department	Function / Role	Signature	Date
Jules Cesar Harorimana	Quality Control	Quality Control Associate	244	1-08.21
Evidence of Review	93			
Name	Department	Function / Role	Signature	Date
Katabazi Innocent	Operations	Deputy CQO	Attential!	01.08.21
Approval to Release		100	9	
Name	Department	Function Role	Signature	Date
Kayitakire Clement	Operations	C00	रितिस्व विकार्श	01.08.21

Document Change History					
Version #	Date	Author	Section	Nature of Change	
001	01.08.2021	Jules Cesar Harorimana	NA	New	



Document details	与光学的是大学的人名 在一种一种产品的 1000 (1000 1000 1000 1000 1000 1000 10		
Document title	OFFLOADING GRAINS		
Page	Page 2 of 4		

### 1 Purpose

The purpose of this document is to provide guidance for operators on how to offload grains inside the intake at the EAX silos plant.

### 2 Scope

This document describes the offloading procedure at the intake in accordance with Good Manufacturing Practices. These procedures are intended to provide an injury free and incident free workplace.

All activities shall be conducted in Safe, Healthy and Environmentally (SHE) responsible manner.

### 3 PPE requirements

Gum boots
Dust masks
Hand gloves (cut resistant)
Overall
Safety glasses
Hair nets

### 4 Safety procedures

- All Required PPE shall be worn
- During offloading, operators shall be supervised and no one is allowed to offload without the presence of a quality team member.
- Before offloading, every truck must pass through the weighbridge

LSR # 1 No drugs while working; only smoke in designated areas; no alcohol at Work



LSR # 2 Work with a valid permit when required



Document details			
Document title		OFFLOADING GRAINS	
Page	F	age 3 of 4	

# 5 Required equipments during offloading

Knives for cutting sacs Sample spears.

## 6 Offloading procedures

- Truck must wait for approval from quality team member, before leaving the weighbridge
- Trucks are directed towards the intake hall of the hopper (One by One) for grains to be physically checked.
- III. During offloading each and every bag is opened using a knife and a sample is taken using sampling spears to ensure the quality of grains.
- IV. Good grains are taken directed into the hopper.
- V. Grains that are not meeting standards (which are not good) are taken back to the truck.
- VI. After offloading, each truck takes its empty sacs.

#### 7 Documentation

Offloaded truck in Log Book shall be filled

#### 8 Record

- 8.1 Work permit (AIF/SHE/SOP/006-FA)
- 8.2 Offloading order



OFFLOADING GRAINS
Page 4 of 4

# 9 Related documents

- 9.1 Good Received Note
- 9.2 Grading Certificate
- 9.3 Rejection Form