## STRESSES TABLE

## CARTER RHEA

## 1. Stresses

Mesh Sizing (mm)	Max Stress (MPa)	Minimum Stress (MPa)
2	52264	37.278
1	57750	33.149
0.5	68298	46.014