
## **Telemetered**



Level	Deployment	StartTime	EndTime	Annotation	Status	Redmine#
GA03FLMB	D00001	2015-03-21T02:30:00Z	2015-11-18T11:20:00Z	Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.		12365
GA03FLMB	D00001	2015-03-21T02:30:00Z	2015-11-18T11:20:00Z	Platform was deployed 5m shallower than intended.		
ctdmo_ghqr_sio_mule_instrument	D00001	2015-03-21T04:00:01Z	2015-07-15T00:00:01Z	Beginning on 2015-06-20, data are sparse due to issues in telemetry.	AVAILABLE	
GA03FLMB	D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.		12365
GA03FLMB	D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Platform was deployed 10m deeper than intended.		
GA03FLMB	D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Due to glider failures, only a few telemetered data points are available for this deployment.		
ctdmo_ghqr_sio_mule_instrument	D00002	2015-11-22T00:00:01Z	2015-12-08T00:00:01Z	Sparse data available	AVAILABLE	
ctdmo_ghqr_sio_mule_instrument	D00002	2015-12-08T00:00:01Z	2016-11-01T10:10:00Z	Due to glider failures, no telemetered data available for the remainder of the deployment.	NOT_AVAILABLE	
GA03FLMB	D00003	2016-10-31T22:37:00Z	2017-08-17T00:00:00Z	No telemetered data are available for this deployment.		

Apr 2016

Jul 2016

Oct 2016

Jan 2017

Apr 2017

Jul 2017

NOT\_AVAILABLE

Jan 2016

Apr 2015

ctdmo\_ghqr\_sio\_mule\_instrument D00003

Jul 2015


Oct 2015

## Recovered-host

2016-10-31T22:37:00Z 2017-08-17T00:00Z No telemetered data are available for this deployment.

Level	Deployment	StartTime	EndTime	Annotation	Status	Redmine#
ctdmo_ghqr_sio_mule_instrument	D00001	2015-03-21T02:30:00Z	2015-11-18T11:20:00Z		PENDING_INGEST	12191
ctdmo_ghqr_sio_mule_instrument	D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z		PENDING_INGEST	12191
					_	

## Recovered-Inst



Deployment	StartTime	EndTime	Annotation	Status	Redmine#
D00001	2015-03-21T02:30:00Z	2015-11-18T11:20:00Z	Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.		12365
D00001	2015-03-21T02:30:00Z	2015-11-18T11:20:00Z	Platform was deployed 5m shallower than intended.		
D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.		12365
D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Platform was deployed 10m deeper than intended.		
D00002	2015-11-21T21:51:00Z	2016-11-01T10:10:00Z	Due to glider failures, only a few telemetered data points are available for this deployment.		
D00003	2016-10-31T22:37:00Z	2017-08-17T00:00:00Z	No telemetered data are available for this deployment.		
D D D	000001 000001 000002 000002	2015-03-21T02:30:00Z 2000002 2015-11-21T21:51:00Z 2000002 2015-11-21T21:51:00Z 2000002 2015-11-21T21:51:00Z	2015-03-21T02:30:00Z 2015-11-18T11:20:00Z 2000001 2015-03-21T02:30:00Z 2015-11-18T11:20:00Z 2000002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z 2000002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z 2000002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z 2000002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z	2015-03-21T02:30:00Z 2015-11-18T11:20:00Z Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.  200001 2015-03-21T02:30:00Z 2015-11-18T11:20:00Z Platform was deployed 5m shallower than intended.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Platform was deployed 10m deeper than intended.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Due to glider failures, only a few telemetered data points are available for this deployment.	2015-03-21T02:30:00Z 2015-11-18T11:20:00Z Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.  200001 2015-03-21T02:30:00Z 2015-11-18T11:20:00Z Platform was deployed 5m shallower than intended.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Flanking Moorings are periodically knocked down by strong currents several tens (and in some cases hundreds) of meters.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Platform was deployed 10m deeper than intended.  200002 2015-11-21T21:51:00Z 2016-11-01T10:10:00Z Due to glider failures, only a few telemetered data points are available for this deployment.