

2016-05-19T00:00:03Z

2016-08-18T00:00:00Z

2016-09-06T00:00:00Z

2016-10-02T00:26:00Z

2016-10-22T00:00:00Z

2016-10-01T09:05:46Z

2016-08-23T00:00:00Z

2016-09-30T00:00:00Z

2017-05-09T00:00:00Z

2017-03-19T15:29:05Z

Profiler stuck at the top of its range probably related to fouling of the line

Profiler stuck at the top of its range probably related to fouling of the line

Instrument not recovered from the water.

Profiler stuck at the top of its range.

PENDING_INGEST

NOT_AVAILABLE

11960

11226

11226

D00007

D00007

D00007

D00008

D00008

CP02PMUO-WFP01-03-CTDPFK000

Deployments CP02PMUO

CP02PMUO-WFP01

ctdpf_ckl_wfp_instrument_recovered

ctdpf_ckl_wfp_instrument_recovered

CP02PMUO-WFP01

CP02PMUO-WFP01

CP02PMUO-WFP01