

PRODUCT INFORMATION

Product Bulletin No.: 81745999 Rev. 0

Motion Compensation

Date: 24-Sep-2014

Subject: HP Fluid Filtration Unit now available as a part of NOV drilling packages.

Product Model: NOV N-Line Tensioner Systems: NRT-1800, NRT-3600 and NRT-4200

Affected

Assemblies: Cylinders and accumulators, as well as other equipment negatively affected

by high number of particles in the hydraulic fluid.

Objective: Information on new equipment available for filtering hydraulic fluid in High

Pressure systems.

Issue: Keeping hydraulic fluid clean has always been a major concern for rig-

operators worldwide. It has been shown several times how fluid particle contamination can drop life expectancy on seals, gaskets, wear bands and cylinders. All NOV hydraulic equipment are delivered with cleanliness class ISO 4406:99 17/15/12 (NAS 6) and cleanliness during operation should not drop below ISO 4406:99 19/17/14 (NAS 8). Experience has shown that this requirement is hard to obtain and in many situations today the equipment must be shut down in order to perform a full particle filtration of the hydraulic fluid. This is not only time consuming, but also dramatically reduces the


number of operating days, with subsequent loss of profit.

Solution: NOV has designed a solution for filtering hydraulic fluid that does not require

shutdown of any components as the filtering is done continuously inside the high pressure loop. Installing this fluid filtration unit will reduce downtime because of maintenance. Also the hydraulic fluid will be less prone to particle

contamination, thus reducing the risk of equipment malfunction.

© 2014 National Oilw ell Varco



Prototype of Fluid Filtration Unit

Ordering Information/ **Contact Information:**

Please contact your local National Oilwell Varco (NOV) Service Center, with

reference to PB 81745999 for further assistance.

Economical and Cost Issues: Contact your nearest NOV Sales representative to get a quote on this unit

with all required installation-/hook-up parts and documentation.

Failure to follow the recommendations and/or guidance in NOV Product Bulletins may result in death, bodily injury or property damage.

Please contact your local National Oilwell Varco (NOV) Service Center if you have any questions regarding this bulletin.

© 2014 National Oilw ell Varco 81745999