APPLIANCE ID	APPLIANCE DESCRIPTION	APPLIANCE LOCATION	CLASS	VISUAL	EARTH Ohms	INSULATION MOhms	FUNCTIONAL	NEXT TEST	PASS/FAIL	COMMENTS
LGT01	Light, table	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	
LGT02	Light, table	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	
TV_01	Television	Room 1 - Old Harry	II	OK	0.044	>20	Yes	+2yrs	PASS	Electronic start
KET01	Kettle	Room 1 - Old Harry	1	OK	0.044	>20	Yes	+2yrs	PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.
DRY01 CLK01	Dryer, hair Clock, alarm	Room 1 - Old Harry Room 1 - Old Harry	II II	OK OK		>20 >20	Yes Yes	+2yrs	PASS PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
LGT03	Light, table	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs +2yrs	PASS	
LGT03	Light, table	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	
TV_02	Television	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	Electronic start
KET02	Kettle	Room 3 - Durlston Room	I	OK	0.078	>20	Yes	+2yrs	PASS	All-plastic construction with no visible or touchable metal parts besides element.
DRY02	Dryer, hair	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
CLK02	Clock, alarm	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	
EXT01	Extension, fixed socket	Room 3 - Durlston Room	I	OK	0.067	>20	Yes	+2yrs	PASS	
EXT02	Extension, fixed socket	Room 3 - Durlston Room	I	OK	0.049	>20	Yes	+2yrs	PASS	
LGT05	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS	
LGT06	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS	
LGT07	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS	
TV_03	Television Kettle	Room 8 - Tyneham	II T	OK	0.047	>20	Yes	+2yrs	PASS PASS	Electronic start  All-plastic construction with no visible or touchable metal parts besides element.
KET03 DRY03	Dryer, hair	Room 8 - Tyneham Room 8 - Tyneham	1	OK OK	0.047	>20 >20	Yes Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
CLK03	Clock, alarm	Room 8 - Tyneham	11	OK		>20	Yes	+2yrs +2yrs	PASS	two fatting plate of fillo in instructions. An-plastic construction indicates class if.
LGT08	Light, table	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS	
LGT09	Light, table	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS	
TV_04	Television	Room 2 - Brownsea Island	I	OK	0.065	>20	Yes	+2yrs	PASS	Electronic start
KET04	Kettle	Room 2 - Brownsea Island	I	OK	0.071	>20	Yes	+2yrs	PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.
DRY04	Dryer, hair	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
CLK04	Clock, alarm	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS	
EXT03	Extension, IEC	Room 2 - Brownsea Island	I	OK	0.049	>20	Yes	+2yrs	PASS	
LGT10	Light, table	Room 4 - Purbeck Suite	II	OK		>20	Yes	+2yrs	PASS	
LGT11	Light, table	Room 4 - Purbeck Suite	II	OK	0.110	>20	Yes	+2yrs	PASS	
TV_05	Television	Room 4 - Purbeck Suite	l T	OK	0.110	>20	Yes	+2yrs	PASS	Electronic start. Worst earth rating on RCA connectors at left side.
KET05 DRY05	Kettle	Room 4 - Purbeck Suite Room 4 - Purbeck Suite	I TT	OK	0.062	>20 >20	Yes	+2yrs	PASS PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.  No rating plate or info in instructions. All-plastic construction indicates Class II.
LGT12	Dryer, hair Light, table	Room 5 - Kimmeridge	11	OK OK		>20	Yes Yes	+2yrs +2yrs	PASS	two fatting plate of fillo in histractions. An-plastic construction indicates class if.
LGT12 LGT13	Light, table	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS	
TV_06	Television	Room 5 - Kimmeridge	I	OK	0.029	>20	Yes	+2yrs	PASS	Electronic start. Worst earth rating on RCA connectors at left side.
EXT03	Extension, IEC	Room 5 - Kimmeridge	Ī	OK	0.052	>20	Yes	+2yrs	PASS	2200 one sum was one a real commentation at the same
KET06	Kettle	Room 5 - Kimmeridge	I	OK	0.071	>20	Yes	+2yrs	PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.
DRY06	Dryer, hair	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
CLK06	Clock, alarm	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS	
LGT14	Light, table	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS	
LGT15	Light, table	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS	
TV_07	Television	Room 6 - Lulworth Cove	II	OK	0.050	>20	Yes	+2yrs	PASS	Electronic start
KET07	Kettle	Room 6 - Lulworth Cove	l	OK	0.059	>20	Yes	+2yrs	PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.
DRY07 CLK07	Dryer, hair	Room 6 - Lulworth Cove Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
LGT16	Clock, alarm Light, table	Room 7 - Old Harry	II	OK OK		>20 >20	Yes Yes	+2yrs	PASS PASS	
LGT10 LGT17	Light, table	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs +2yrs	PASS	
TV_08	Television	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	Electronic start
KET08	Kettle	Room 7 - Old Harry	I	OK	0.067	>20	Yes	+2yrs	PASS	Fixing bolt of element exposed in base due to missing cover. Otherwise all-plastic construction with no visible or touchable metal parts besides element.
DRY08	Dryer, hair	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.
CLK08	Clock, alarm	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	
VAC01	Cleaner, vacuum, DC33	Cleaning cupboard	II	OK		>20	Yes	+2yrs	PASS	
LGT18	Light, table	Landing	II	OK		>20	Yes	+2yrs	PASS	
LGT19	Light, table	Hall	II	OK		>20	Yes	+2yrs	PASS	
IRN01	Press, steam	Hall	I	OK	0.106	>20	Yes	+2yrs	PASS	Earth taken from metal shell. Heating plate is isolated.
VAC02	Cleaner, vacuum, DC14	Downstairs	II	OK		>20	Yes	+2yrs	PASS	
FAN01	Fan, floor, upright	Downstairs	II	OK		>20	Yes	+2yrs	PASS	
FAN02	Fan, floor, upright	Downstairs	II T	OK	0.160	>20	Yes	+2yrs	PASS	
FAN03	Fan, floor	Downstairs	l T	OK	0.169	>20	Yes	+2yrs	PASS	Condisco Fouth shook is four hose unit. Otherwise all plantic construction with an elicible anti- 1,11, and 1, 1,1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
KET09 TOA01	Kettle Toaster	Kitchen Kitchen	I T	OK OK	0.056 0.056	>20 >20	Yes Yes	+2yrs +2yrs	PASS PASS	Cordless. Earth check is for base unit. Otherwise all-plastic construction with no visible or touchable metal parts besides element and top trim. Cordless. Earth check is for base unit. Otherwise all-plastic construction with no visible or touchable metal parts besides element and top trim.
10401	TOASICI	Kitchell	1	OK	0.030	<b>/</b> 20	105	F2y18	1700	Cordicas. Latin check is for base unit. Otherwise an-plastic constituction with no visible of touchable metal parts besides element and top tilli.