



Jim Whaley Tires - West Enterprise

1161 Geneva Hwy

Enterprise, AL 36330

Phone: (334) 347-0946

Website: JimWhaleyTires.com

Invoice

Bill To DANA, PHILLIP
208 WEST SAND CREEK ROAD
ENTERPRISE, AL 36330
USA

Mobile (334) 447-8295
Email philipdana007@gmail.com

Invoice # 709006573
Work Order # 709007288
Service Advisor Andrew Roberds
Technician Zachery Grotheer

Plate AL A0EMWT3
Description Black 2013 Chevrolet Captiva Sport LT L4 2.4L
2384CC 145CID VIN K
VIN 3GNAL3EK5DS560271
Odometer 102,303

Invoice Date 8/25/2026 9:17 AM

Concern

Customer Requests / Comments / Notes

Customer Comments: DROP OFF - 334 447 8295
EVALUATE EXHAUST LEAK AND POSSIBLE COOLING SYSTEM LEAK
HAS ADDED A TOTAL OF 1/2 GAL OVER THE COURSE OF ABOUT 1-2 WEEKS. SEEMS TO BE HOLDING NOW.
HIS SON TOLD HIM HE CAN HEAR AN EXHAUST LEAK - BELIEVES IT TO BE BEFORE THE CAT. CONVERTER

Inspection Comments

Pulled engine oil dipstick as part of general inspection and found oil to only be barely touching the bottom of the dipstick. (About 1 qt. low of oil) Mechanic recommends performing a bottom-end engine flush to help reverse engine oil consumption that appears to be taking place.

Coolant and brake fluids both recommended to service based on mileage of the vehicle.

Fuel induction service strongly recommended to be performed on these engines after 30,000 miles to clean the top end of the motor of carbon buildup.

Service

Cooling System Evaluation

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Diagnostic Charge

\$62.50 E2

Sub \$62.50

Diagnostic Results

Pressure tested the cooling system and inspected for leaks top to bottom over the course of about 30-40 minutes with the system held under pressure. Did not find any active coolant leak happening at this time and did not find any evidence of a coolant leak that may have happened recently.

Exhaust System Evaluation

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Diagnostic Charge

\$25.00 E2

Sub \$25.00

Diagnostic Results

Confirmed exhaust leak to be coming from between the flange after the catalytic converter. Recommend taking vehicle to an exhaust shop to have this section of the exhaust repaired or a new gasket in that section to be installed.

Total Parts	\$0.00
Total Labor	\$87.50
Total Before Taxes & Miscellaneous Charges	\$87.50
(E2) Shop Supplies - Jim Whaley Tires	\$8.75
Grand Total	\$96.25

Thank you for your business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.


DANA, PHILLIP paid \$96.25 by MASTERCARD

8/25/2026 9:17 AM Card #: XXXXXXXXXXXXX7940 Entry Method: Contactless Type: Sale Amount: 96.25

Terminal: 99723 Transaction: 1d3b75d9-f28f-49f6-93fe-960b205812bc Authorization: 239677 Result: Approved

Surcharge Fee: \$0.00

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

A handwritten signature in black ink, appearing to be a stylized '2' or similar character, followed by a horizontal line.

Invoice Signature. Signed on 8/25/2026 9:17 AM

Customer Signature: _____

Deferred Service

•Oil Change - Full Synthetic

Change oil, replace filter, lube steering, suspension, door and hood hinges, check tire pressures and tread depths, check fluids and top off transmission, differential, power steering, washer, and battery fluids as applicable.

CITGO FULL SYNTHETIC	5 Unit	\$11.89 / Unit	\$59.45
Engine Oil Filter - Oil Filter	1 Unit	\$5.80 / Unit	\$5.80 E2U7Y5
Labor			\$34.70 E2
		Sub	\$99.95

BG Engine Performance Restoration

Removes all sludge and varnish from engine increasing performance and compression and reduces emissions

BG Engine EPR (Engine Performance Restoration) Service Kit	1 Unit	\$41.25 / Unit	\$41.25 Y5
Labor			\$28.70 E2
		Sub	\$69.95

BG Extended Life MOA Service

Life time engine oil additive superior engine protection and lubrication.

BG Cooling System Fluid Exchange Service

Cleaning of entire cooling system to remove all contaminants, exchanged with fresh coolant and conditioned for long life and extended performance.

BG Cooling System Service Kit 540/546	1 Unit	\$65.01 / Unit	\$65.01 Y5
Engine Coolant / Antifreeze	2 Unit	\$19.99 / Unit	\$39.98 Y5
Labor			\$125.00 E2
		Sub	\$229.99

BG Fuel Induction Service

Top end engine cleaning (throttle body, intake manifold, intake valves, combustion chamber and entire fuel system) optimal mpg, increases performance and reduces emissions.

Fuel Induction GDI Maintenance Service	1 Unit	\$95.64 / Unit	\$95.64 Y5
Labor			\$125.00 E2
		Sub	\$220.64

BG Brake Fluid Service

Full brake fluid exchange removing moisture contaminated fluid from the rear calipers to the master cylinder.

Brake Fluid Exchange 32oz	1 Unit	\$50.14 / Unit	\$50.14 Y5
Labor			\$125.00 E2
		Sub	\$175.14

Total Parts		\$357.27
Total Labor		\$438.40
Total Before Taxes & Miscellaneous Charges		\$795.67
(E2) Shop Supplies - Jim Whaley Tires		\$44.42
(U7) Waste Oil Disposal - Whaley		\$1.00
(Y5) State Sales Tax - West Enterprise	9 %	\$26.80
Grand Total		\$867.89