## 3Com Switch 3870 Family Software Version 3.00 Release Notes – P07 Supplement

Please use this document in conjunction with the document entitled 3Com SuperStack© 3 Switch 3870 Family Software Version 3.00 Release Notes.

Patch 07 (P07) is an updated version of Switch 3870 Version 3.00 software. It is being generally made available to facilitate customers to have the latest software across all Switch 3870 units in their network.

The software supports the following products:

- Switch 3870-24 (3CR17450-91)
- Switch 3870-48 (3CR17451-91)

P07 builds off of Version 3.00 software. All details in the Version 3.00 Release Notes are relevant. In addition, P07 addresses makes these changes:

- Fixes a CLI command missing default case at checking a user's login privileges.
- Changes behavior so a 10-Gigabit XENPAK is displayed as supported and not un-supported.
- Updates MIBs for the 3870 switches.
- Fixes an issue that would stop management after the use of the getting started wizard.
- Adds SNMP getNext in priolpDscpTable, priolpDscpTable, dot1dTpPortOverflowTable, ifMauTable, ifMauAutoNegTable and dot1dStaticT
- Fixes an issue that would temporarily stop the 3870 from responding to SNMP V1 MIB walks.

Copyright © 2008, 3Com Corporation. All rights reserved.
Unless otherwise indicated, 3Com registered trademarks are registered in the
United States and may or may not be registered in other countries.
3Com, SuperStack, and the 3Com logo are registered trademarks of 3Com Corporation.