

SAFETY REQUIREMENTS FOR ALL JOBS



	MAPP HSE POLICY AND PROCEDURES MANUAL		SAFETY OBSERVATION REPORTS (SORS) shall be
	Hardcopy and/or available Online at: www.mappconstruction.com/mappsafety		filled out twice per week by all supervisors. Turn into safety department for reporting purposes.
	PHSEP — Generated for the Project by Safety		TASK SAFETY ANALYSIS (TSA) shall be completed
	SSSP — For EACH Subcontractor, completed by each Subcontractor, and returned to Safety.		prior to start of ANY work on the jobsite. The Supervisor (or foreman) shall complete with input from the crew, all shall sign, and if any work changes during the day, it must be added to the TSA, or on a new TSA. MAPP Superintendent shall review and sign before any work may begin.
	PWAs – PRE-WORK ASSESSMENTS from EACH Subcontractor prior to start of work for methods, tools, risk evaluation for particular scopes of work (i.e. framing, concrete, tilt wall, etc.), and returned to Safety.		
	SAFETY DATA SHEETS (SDS) BINDER shall be kept onsite for duration of project. All subs shall submit SDSs prior to start of work.		HOUSEKEEPING is everyone's responsibility. MAPP adheres to the "Clean as you go" campaign. Throughout the work day (not week) workers are responsible for cleaning their work
	ALL SIGNAGE & SUPPLIES TO BE IN PLACE before any work is performed on site.		area. MAPP does NOT provide housekeeping for the site. Each contractor is responsible for his own waste and debris.
	Jobsite Sign		INCIDENTS, ACCIDENTS and NEAR MISSES are to
	Required PPE Sign(s) at Jobsite Entrance		be reported immediately to your Supervisor,
	Visitor PPE		and to the Project Manager. MAPP HSE is also to be notified:
	Visitor Orientation/Sign-in		McKinley Bailey (225) 200-7264
	Federal & State Labor Posters		Lydia Blanchard (504) 495-7891
	Fire Extinguishers		MAPP WEEKLY HSE INSPECTION CHECKLIST is to
	First Aid Stations		be completed, one per week, and uploaded to
	Eye Wash Station/bottles		the project drive.
	First Aid Station & Eye Wash Signs		REQUIRED PPE SHALL BE WORN ON ALL SITES:
	Spill Kit Clean-Up Materials		NO EXCEPTIONS
	Spill Kit Signage		Hard Hats
			Safety Glasses
	WEEKLY SAFETY MEETINGS by Site Superintendent shall be attended by all site workers and employees. Meeting and Attendance is to be documented. Any person not signing the Meeting Sign-in Sheet "did not attend".		Hi-Vis Vest or Shirt (min 4" sleeve)
			Leather Work Boots
			Long Work Pants
			When Required:
			Gloves when handling materials
			Hearing Protection (noise above 85 db)
			Specialized PPF when required