Customer Complaint 8D Report - Bracket Assembly

Manufacturing Knowledge Hub | Quality Assurance

Owner: Linda Park | Last updated: October 30, 2026

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure.

Key Points

- D3 containment: all finished goods inventory of the affected lot was quarantined.
- D4 root cause: weld penetration depth fell below spec on a subset of fixtures.
- D5 corrective action: fixture rework and weld parameter revalidation completed.
- D8 closure confirmed after 60 days of clean field performance data.

Source: Manufacturing Knowledge Hub knowledge base | SharePoint Online