

PRODUCT/ PROCESS CHANGE NOTIFICATION

QPCN11026					
TO-220 package,					
UL marking on the device as well as in the data					
sheet was incorrect and must be removed					
All Sales					
Owen Wang					
11 th Oct., '11					
16 th Jan., '12					
7. Affected Product Identification					
TO-220AC & TO-220AB package, more details please see appendix A					
8. Change Description : (OLD Vs. NEW Comparison)					
New:					
Remove TSC UL logo on product.					
Remove TSC UL recognized number on					
datasheet.					
It was a TSC mistake. TO-220 package product do not applying with standard UL1557 because					
devices are without isolation / insulation system between live parts and the heat sink and					
n between live parts and the heat sink and					
n between live parts and the heat sink and at means they don't fulfill the UL1557.					
at means they don't fulfill the UL1557.					
•					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
at means they don't fulfill the UL1557. ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number. 26 th Sep., '11 26 th Sep., '11					
ality or reliability) ne UL recognized file number.					
ality or reliability) ne UL recognized file number. 26 th Sep., '11 26 th Sep., '11					
ality or reliability) ne UL recognized file number. 26 th Sep., '11 26 th Sep., '11					
r					



PRODUCT/ PROCESS CHANGE NOTIFICATION CUSTOMER APPROVAL FORM_QPCN11026

(Please tick the field what is valid for you!)

		(1 16036 1161 11	ie lielu Wilat is valiu ioi yo	u:)		
	We agree with this proposed change and its schedule.					
	We have object	tions				
	We need more information:					
	M/o wood oowe					
	We need sample	ie:				
	mpany:					
Nan	ne:					
Add	lress:					
Sign	nature:		Date:			



PRODUCT/ PROCESS CHANGE NOTIFICATION Appendix

A (Affected Product Identification):

A (Affected Product Identification).			
TO-220AC Schottky Barrier Rectifiers	TO-220AB Schottky Barrier Rectifiers		
MBR735 thru MBR7150	MBR1035CT thru MBR10200CT		
SRA820 thru SRA8150	MBR10H100CT thru MBR10H200CT		
MBR1035 thru MBR10200	MBR10L100CT		
SRA1020 thru SRA10150	SR1020 thru SR10150		
MBR1635 thru MBR16150	MBR1535CT thru MBR15150CT		
SRA1620 thru SRA16100	SR1620 thru SR16150		
SRA2020 thru SRA20100	MBR2035CT thru MBR20200CT		
	MBR20H100CT thru MBR20H200CT		
	MBR20L100CT thru MBR20L120CT		
	SR2020 thru SR20150		
	MBR2535CT thru MBR25150CT		
	MBR3035CT thru MBR30150CT		
	MBR30H100CT		
	MBR30L45CT thru MBR30L100CT		
	MBR30L120CT		
TO-220AC Super Fast Rectifiers	TO-220AB Super Fast Rectifiers		
UG5J	SF801G thru SF808G		
UG8J	SF1001G thru SF1008G		
MUR820 thru MUR860	SF1601G thru SF1608G		
SFA801G thru SFA808G	MUR1620CT thru MUR1660CT		
SFA1001G thru SFA1008G	SF2001G thru SF2008G		
SFA1601G thru SF1608G			
TO-220AC High Efficient Rectifiers	TO-220AB High Efficient Rectifiers		
HERA801G thru HERA808G	HER1001G thru HER1008G		
HERA1601G thru HERA1608G	HER1601G thru HER1608G		
TO-220AC Glass Passivated Rectifiers	TO-220AB Glass Passivated Rectifiers		
GPA801 thru GPA807	GP1001 thru GP1007		
GPA1601 thru GPA1607	GP1601 thru GP1607		