

Pitster Central Workshop

Pitster Service Organisation
Strada Atelierului 12, Cluj-Napoca | +40 700 123 456 | workshop@example.com

APPOINTMENT AND ASSIGNMENT

APPOINTMENT	ESTIMATED DURATION	STATUS
17/08/2026, 11:30:00	120 minutes	CHECKED IN

STRUCTURED CALENDAR RESOURCES
mechanic: Mechanic team A | bay: Station 2

PRINTED MECHANIC OVERRIDE
Alex Ionescu
Calendar resources remain authoritative for capacity and conflicts.

CUSTOMER AND VEHICLE

CUSTOMER	VEHICLE
Andrei Popescu	Volkswagen Golf (2021)
+40 700 555 111 andrei@example.com	Registration: CJ-12-ABC
	VIN: WVVZZZ1JZXW000001
	Mileage: 68420 km

CUSTOMER REQUEST

Diagnose

Intermittent engine warning light and reduced power when accelerating uphill.

VEHICLE RECEPTION CONDITION

Small scratch on left rear door. Fuel level approximately one half. Warning light visible at arrival.

DIAGNOSIS AND APPROVED WORK

Stored boost-pressure fault. Inspect intake hoses and actuator operation.

Estimate: approved | EUR 185.00

PARTS AND CONSUMABLES

DESCRIPTION	PART / OEM	QTY	WARRANTY
Intake pressure hose	5Q0-145-838	1	2027-08-17

WORK PERFORMED AND MECHANIC NOTES

Customer requested a call before any work outside the approved estimate.

START TIME

COMPLETION TIME

MILEAGE OUT

QUALITY CONTROL AND TEST DRIVE

- ☐ Fluid levels
- ☐ Leaks
- ☐ Fasteners
- ☐ Warning lights
- ☐ Road / function test
- ☐ Vehicle cleanliness

RECOMMENDATIONS AND NEXT SERVICE

Annual engine service - 2027-08-01 / 82000 km

HANDOVER AND SIGNATURES

MECHANIC

WORKSHOP MANAGER

CUSTOMER / VEHICLE HANDOVER

Date: _____

Date: _____

Date: _____