

CS710S Firmware and Demo App Software Release Notes

2024 September 05

Firmware Release Notes:

- 1. Atmel IC Firmware
- 2. Bluetooth IC Firmware
- 3. RFID Firmware

Demo App Software Github Site Links (Release Notes and Source Codes for Download)

Contents

Contents	2
Atmel IC Firmware	
Bluetooth IC Firmware:	
RFID Firmware (from Impinj)	7
GitHub Site for CSL Demo Apps	

Atmel IC Firmware

There are 2 firmware release history tracks, one is compatible with Impinj RFID Firmware V1.2, one is compatible with Impinj RFID Firmware V2.0.

1) Impinj RFID Firmware V2.0 compatible:

Atmel Image App Compatible with RFID Firmware V2.0 Release Notes		
Release version	Changes	Date
2.0.8	 Modify the Taiwan frequency to new NCC regulation 	2024-08-20
2.0.7	Modify the MultibankReadConfig register.	2024-06-13
2.0.6	Fix CW frequency channel incorrect	2024-04-26
2.0.5	Fix hopping frequency channel incorrect	2024-04-25
2.0.4	 Change Tx On time to 1000ms for ETSI lower and upper band. 	2024-04-17
2.0.3	 Multibank inventory will return epc even if read failed 	2024-04-15
2.0.1	Fix no access reply when kill command succeeds	2023-10-19
2.0.0	 Initial Release Compatible with the Impinj RFID Firmware 2.0 framework From this version and higher, Can only work with RFID Firmware 2.0 or after, NOT compatible with RFID Firmware 1.2 	2023-09-04

2) Impinj RFID Firmware V1.2 compatible:

Atmel Image App Compatible with RFID Firmware V1.2 Release Notes		
Release version	Changes	Date
0.2.20	 Change Tx On time to 1000ms for ETSI lower and upper band. Multibank inventory will return epc even if read failed Fix no access reply when kill command succeeds 	2024-04-26
0.2.19	 Multibank inventory will return epc even if read failed 	2023-07-31
0.2.18	 Add access inventory commands 0x1A07 and 0x1A08. (Protected mode inventory) 	2023-07-03
0.2.17	Fix no access reply when kill command succeeds	2023-05-31
0.2.16	Add 16 antenna ports support	2023-05-30
0.2.15	Fix multiple bank inventory wrong return data	2023-05-08
0.2.14	Add RSSI filter for multi-bank inventory	2023-05-03
0.2.13	Add ETSI burst test.	2023-04-28
0.2.12	Modify country Philippines frequency band.	2023-02-23
0.2.11	Modify country India frequency band.	2023-02-20
0.2.10	Add country enum 160 (Vietnam3).	2023-02-16
0.2.9	Fix country -7 frequency.	2023-01-27
0.2.8	Fix vibrator off bug.	2022-12-23
0.2.7	Fix fastid in compact mode.	2022-11-04
0.2.6	Fix CW ON test hang	2022-10-28
0.2.5	Add register 0x3946 ReversePowerADC.	2022-10-26
0.2.4	Add Authenticate command support.	2022-10-13
0.2.3	Fix RX gain default values.	2022-09-21
0.2.2	Fix trigger button initial state.	2022-09-13
0.2.1	Fix multibank inventory hang.	2022-06-17
0.2.0	Support E710 1.02 firmware. Initial Release	2022-06-16

Atmel Bootloader Release Notes		
Release version	Changes	Date
0.1.2	Initial version	2022-02-28

Bluetooth IC Firmware:

For Texas Instruments CC2652 R74 Bluetooth IC (9th character of product serial number must be "B") Release version Changes Date • Fix BT button off function does not fully stop BT 1.0.8 2024-09-05 1.0.7 • Add 2442MHz for BT test. 2024-06-11 1.0.6 • Fix inventory auto stop 2023-07-07 1.0.5 • Fix device name problem in C# android. 2023-06-30 1.0.4 Add BLE PER Test support. 2023-06-29 1.0.3 Fix iOS device name problem 2023-06-06 2022-09-05 1.0.2 Initial version

For CC2652R7 or R74, Initial Programming HEX Release Notes		
Release version	Changes	Date
1.0.2	Initial version	2022-10-03

RFID Firmware (from Impinj)

RFID Application: E710 RFID Firmware (from Impinj) Release Notes		
Release version	Changes	Date
2.0	New RFID Firmware from Impinj, can only work with Atmel firmware V2.x.x; NOT compatible with Atmel firmware V0.x.x	2023-09-04
1.2	Miscellaneous	2022-06-11
1.1	Miscellaneous	2021-12-02
1.0	Initial version	2021-09-17

GitHub Site for CSL Demo Apps

Please go to the following GitHub site for demo app release notes and their corresponding source codes download:

Convergence Systems Limited · GitHub