NTPL

NLC TAMILNADU POWER LIMITED

SAFETY DIVISION STANDARD OPRATING PROCEDURE

TITLE:- SOP- FORHOUSE KEEPING WORK		NTPL//SOP-11	

SOP FOR HOUSEKEEPING WORK:

- 1. The contractor shall be primarily responsible for maintaining Good housekeeping and safety standards in the workplace;
- 2. Loose materials that are not required for use shall not be placed or left behind so dangerously as to obstruct workplaces or passageways;
- 3. All projecting nails shall be removed or bent to prevent injury;
- 4. Equipment, tools and small objects shall not be left lying unattended or unsecured from where they could fall or cause a person to trip;
- Scrap, waste or rubbish shall not be allowed to accumulate in the site as these combustibles cancreate serious fire hazards and affect safe working;
- 6. Workplaces and passageways that become slippery owing to spillage of oil or other causes shall be cleaned up or strewn with sand, ash or the like:
- 7. Portable equipment shall be returned after use to their designated storage place.
- 8. Ensure caution board, require tools availability for worker.
- 9. Means of access and egress hall consist of
 - a. Adequate and safe means of access and egress shall be provided in all workplaces;
- b. The means of access and egress shall be maintained in a safe condition;