NTPL

NLC TAMILNADU POWER LIMITED

SAFETY DIVISION STANDARD OPRATING PROCEDURE

TITLE:- SOP- ELECTRICAL WORKS			NTPL//SOP-05

SOP FOR ELECTRICAL WORKS: -

The following points should be checked and complied with before start of work involving electrical power supply.

- 1. Electrical equipment /tools are in sound condition and inspected /tested for its healthiness.
- 2. Body earthing is provided to machine / electrical hand tool.
- 3. The switches / Fuses/ Plug top used are of appropriate rating.
- 4. The power cable is having three cores in case of single phase and four cores in case of 3 phase supply.
- 5. The joints in power cables are properly insulated.
- 6. For Welding cable , job earth and joints are proper.
- 7. Electrical machine/tools cables are free from obstruction, contact with water and hot sparks.
- 8. ELCB is provided in the supply system.
- 9. Use of 24 volts hand lamp in confined space /vessel.
- 10. Permit to work has been taken.
- 11. Proper access and illumination are available to switch boards and work location

NTPL

NLC TAMILNADU POWER LIMITED

SAFETY DIVISION STANDARD OPRATING PROCEDURE

TITLE:- SOP- ELECTRICAL WORKS			NTPL//SOP-05

- 12. Safety tags are provided.
- 13. Engagement of experienced and authorised workers for doing the work.
- 14. Workers are briefed on safety precautions to be taken.
- 15. Use of Helmet, Shoes, Gloves, Face shield and Safety belt (height work) by worker. Use Arc Flash suit wherever required.
- 16. Worker is not exposed to rain and not standing on wet /water logged location.
- 17. Second person is available with the engaged worker.
- 18. Tag the lock with a DANGER, DO NOT OPERATE TAG-LOTO
- 19. Agency supervisor deployed.