# NTPL

#### NLC TAMILNADU POWER LIMITED

# SAFETY DIVISION STANDARD OPRATING PROCEDURE

TITLE:- SOP- HANDLING OF GAS CYLINDER			NTPL//SOP-04

#### I.HANDLING OF CYLINDERS: -

- 1. Secure protective caps on all cylinders not in use.
- 2. Properly secure cylinders in an upright position during movement.
- 3. Do not use slings or ropes for moving cylinders.
- 4. All cylinders shall be properly labelled.
- 5. Do not strike cylinders together.
- 6. Keep valves on empty cylinders closed at all times.
- 7. Use cylinders trolleys, material baskets, cylinder racks, and other proper types of equipment to transport cylinders.
- 8. Only rely on the supplier's tag to determine the contents of a compressed gas cylinder.

#### II. USING OF CYLINDERS.

- 1.Use approved pressure reducing regulators with a check valve connected to the cylinder valve on all cylinders.
- 2. Always close the cylinder valve before attempting to stop leaks.
- 3. Do not use oil or grease as a lubricant on valves or attachments.
- 4. Threads on fittings shall correspond to cylinder valve outlets.
- 5. Inspect cylinders for safe condition before use.
- 6. Protect cylinders from direct flame, sunlight, and other heat sources.
- 7. Inspect all gauges, regulators, hoses, and cylindersfor damage and current hydrotest date.
- 8. Place flashback arrestors at oxygen/acetylene cylinder regulators for



## **NLC TAMILNADU POWER LIMITED**

# SAFETY DIVISION STANDARD OPRATING PROCEDURE

TITLE:- SOP- HANDLING OF GAS CYLINDER			NTPL//SOP-04

cutting, welding and Brazing.

### **III. STORING OFCYLINDERS.**

- 1.Store cylinders in an upright, secured position, and cylinder racks wherever possible.
- 2.Keep stored O<sub>2</sub> cylinders separated from fuel gas cylinders suitable distance on non-combustible barrier.
- 3. Keep cylinders awayfrom direct flame, sunlight, and other heat sources.
- 4. Do not store cylinders at temperatures exceeding 540C.
- 5. properly identify empty and full cylinders.