UNIT TRIPPING/SHUTDOWN REPORT

UNIT No:1

STATION: NTPL, TUTICORIN.

OUTAGE: NO: 78

REPORT NO: 78

1. Date of tripping : 10/06/2023

2. Time of tripping : 22:00HRS

3. Status before tripping

a) Unit load : 320 MW

b) Mills in service : C, D,E,F, G

c) Oil guns in service : NIL

d) Boiler feed pumps in service : A & B

e) CEPs in service : A & C

f) ID fans in service : A & B

g) FD fans in service : A & B

h) PA fans in service : A & B

i) CWP in service : A & B

4. Analysis of Shut down:

In Unit 1, water wall tube leak near door resulted noise from local. To avoid secondary damage unit load was reduced below 200 mw and hand tripped the unit at 22:00hrs.

5. Root cause:

The reason for failure will conclude after detailed analysis of the specimen.

6. Remedial measures taken/to be taken:

a) Thickness survey to be done during major overhaul to avoid such instance in future.

7. Time / Date of boiler light up and synchronization:

Light Up: 08:15Hrs. on 12/06/2023

Sync: 14:14 Hrs. on 12/06/2023.

8. Delay for light up/synchronising

1. Delay in synchronising due to EHTC problem (EHC converter stuck at 100% and not responding to EHC demand). The EHC converter cable fault identified and rectified by C&I and taken back the unit into service.

9. Any specific learning / feedback

nil

EE/OS

ACM/OS

DGM/C&I

DGM/BM

DGM/ELEC

DGM/MTP

OGM/OS

Copy submitted to CEO / NTPL Copy submitted to GM/O&M