




DHT11 bekötés

SENSOR1 → Arduino PIN4

SENSOR2 → Arduino 3.3V

SENSOR3 → Arduino GND

Raspberry Pi Zero SDA (Bal 2) → Arduino SDA

Raspberry Pi Zero SCL (Bal 3) → Arduino SCL

Raspberry Pi Zero GND (Jobb 3) → Arduino GND