
$\sigma_{x,j}$ [mm]
$\sigma_{x',j}$ [mrad]
found range, configured exit
found range, $D = D' = 0$
Exit jitter (rms)
0.8
0.6
0.4
0.2
160
180
200
220
240
260
Horizontal phase advance m1 → m4 [deg]