

Exit Phase Space Distribution
Uncorrected (3x Jitter)
Corrected (Knob Tuning)
Horizontal Angle ^\prime$ [mrad]
Horizontal Position $ [mm]
0.5
0.4
0.3
0.2
0.1
0.0
−0.1
−2
−1
0
1
2
3
Held-Out Transport Transmission vs Stress Level
Physical Transmission [%]
Centroid Jitter Multiplier
Uncorrected Transmission
Corrected Transmission
Design Jitter (.0\times$)
100
90
80
70
60
50
40
0
2
4
6
8
10