# 563 Processor May Store Incorrect Resume Flag in VMCB

## **Description**

A processor core may incorrectly store rFLAGS.RF = 1 in the VMCB when the processor is performing an SVM interception on a CLI instruction, including an intercept on an exception that occurred during execution of the CLI instruction.

#### **Potential Effect on System**

None expected under normal conditions. Instruction breakpoints on CLI instructions may not be received for programs running under a hypervisor.

### **Suggested Workaround**

None required.

#### **Fix Planned**

No