578 Branch Prediction May Cause Incorrect Processor Behavior

Description

Under a highly specific and detailed set of internal timing conditions involving multiple events occurring within a small window of time, the processor branch prediction logic may cause the processor core to decode incorrect instruction bytes.

Potential Effect on System

Unpredictable program behavior, generally leading to a program exception.

Suggested Workaround

None.

Fix Planned

Yes