Report for: Job Name:

CertaSite VFW 18878038 Job Number: 110022

Matt Wilkinson 500 VFW PARKWAY Number of Sprinklers 4

4620 Crystal Parkway KENT OH 44240 US Date Received: 07/09/2020

Report Date: 07/14/2020

For Service Call: (330) 673-3600 Page: 1 of 4

Sprinkler Information

Temp Rating (°F/°C):

Kent OH 44240

Year Marking: 1992 Location: VFW

Manufacturer: Viking
Series, Model or SIN: M

155 / 68

Response Type: Standard Response

Dry Sprinkler: Yes

Releasing Mechanism: Frangible Bulb Water Seal Config: Belleville Spring

Test Results

Sprinkler Number: 1

Test	Method	Test Value	Specification	Test Result
Response Time, Sec.	LBTR-3404	41.4	0 - 123.1	Pass
Water Seal Release (7 PSI)	LBTR-3404	Full Release	Full Release	Pass

Comments:

This sample was tested as required by NFPA 25 2020 Ed. 5.3.1.1. Pictures of this sprinkler, including an image of the waterway post testing, were made available via a link (active for 90 days) in the results email and are also available upon request. Dyne does NOT evaluate if any narrowing of the waterway is detrimental.

According to the 2020 Edition of NFPA 25 Section 5.3.1.3, "Where one sprinkler within a representative sample fails to meet the test requirement, all sprinklers within the area represented by that sample shall be replaced." Should the product(s) represented by this sample remain in service, it shall be listed for use in your system/application and must be resampled and tested in 5 or 10 years in accordance with NFPA 25 2020 Ed. 5.3.1.

Roberto Gonzalez, Lab Analyst

Allo Ne Borre



Report for: Job Name:

CertaSite VFW 18878038 Job Number: 110022

Matt Wilkinson 500 VFW PARKWAY Number of Sprinklers 4

4620 Crystal Parkway KENT OH 44240 US Date Received: 07/09/2020

Report Date: 07/14/2020

For Service Call: (330) 673-3600 Page: 2 of 4

Sprinkler Information

Kent OH 44240

Year Marking: 1996 Location: VFW

Manufacturer: Viking
Series, Model or SIN: M

Temp Rating (°F/°C): 155 / 68

Response Type: Standard Response

Dry Sprinkler: Yes

Releasing Mechanism: Frangible Bulb Water Seal Config: Belleville Spring

Test Results

Sprinkler Number: 2

Test	Method	Test Value	Specification	Test Result
Response Time, Sec.	LBTR-3404	40.6	0 - 123.1	Pass
Water Seal Release (7 PSI)	LBTR-3404	Full Release	Full Release	Pass

Comments:

This sample was tested as required by NFPA 25 2020 Ed. 5.3.1.1. Pictures of this sprinkler, including an image of the waterway post testing, were made available via a link (active for 90 days) in the results email and are also available upon request. Dyne does NOT evaluate if any narrowing of the waterway is detrimental.

According to the 2020 Edition of NFPA 25 Section 5.3.1.3, "Where one sprinkler within a representative sample fails to meet the test requirement, all sprinklers within the area represented by that sample shall be replaced." Should the product(s) represented by this sample remain in service, it shall be listed for use in your system/application and must be resampled and tested in 5 or 10 years in accordance with NFPA 25 2020 Ed. 5.3.1.

Roberto Gonzalez, Lab Analyst

Allo No Borre



Report for: Job Name:

CertaSite VFW 18878038 Job Number: 110022

Matt Wilkinson 500 VFW PARKWAY Number of Sprinklers 4

4620 Crystal Parkway KENT OH 44240 US Date Received: 07/09/2020

Report Date: 07/14/2020

For Service Call: (330) 673-3600 Page: 3 of 4

Sprinkler Information

Kent OH 44240

Year Marking: 1992 Location: VFW

Manufacturer: Viking
Series, Model or SIN: M

Temp Rating (°F/°C): 155 / 68

Response Type: Standard Response

Dry Sprinkler: Yes

Releasing Mechanism: Frangible Bulb Water Seal Config: Belleville Spring

Test Results

Sprinkler Number: 3

Test	Method	Test Value	Specification	Test Result
Response Time, Sec.	LBTR-3404	43.7	0 - 123.1	Pass
Water Seal Release (7 PSI)	LBTR-3404	Partial Release	Full Release	Fail

Comments:

This sample was tested as required by NFPA 25 2020 Ed. 5.3.1.1. Pictures of this sprinkler, including an image of the waterway post testing, were made available via a link (active for 90 days) in the results email and are also available upon request. Dyne does NOT evaluate if any narrowing of the waterway is detrimental.

According to the 2020 Edition of NFPA 25 Section 5.3.1.3, "Where one sprinkler within a representative sample fails to meet the test requirement, all sprinklers within the area represented by that sample shall be replaced." Should the product(s) represented by this sample remain in service, it shall be listed for use in your system/application and must be resampled and tested in 5 or 10 years in accordance with NFPA 25 2020 Ed. 5.3.1.

Roberto Gonzalez, Lab Analyst

Allo Ne Borre



Report for: Job Name:

CertaSite VFW 18878038 Job Number: 110022

Matt Wilkinson 500 VFW PARKWAY Number of Sprinklers 4

4620 Crystal Parkway KENT OH 44240 US Date Received: 07/09/2020

Report Date: 07/14/2020

For Service Call: (330) 673-3600 Page: 4 of 4

Sprinkler Information

Kent OH 44240

Year Marking: 1992 Location: VFW

Manufacturer: Viking
Series, Model or SIN: M

Temp Rating (°F/°C): 155 / 68

Response Type: Standard Response

Dry Sprinkler: Yes

Releasing Mechanism: Frangible Bulb Water Seal Config: Belleville Spring

Test Results

Sprinkler Number: 4

Test	Method	Test Value	Specification	Test Result
Response Time, Sec.	LBTR-3404	Did Not Activate	0 - 123.1	Fail
Water Seal Release (7 PSI)	LBTR-3404	Did Not Release	Full Release	Fail

Comments:

This sample was tested as required by NFPA 25 2020 Ed. 5.3.1.1. Pictures of this sprinkler, including an image of the waterway post testing, were made available via a link (active for 90 days) in the results email and are also available upon request. Dyne does NOT evaluate if any narrowing of the waterway is detrimental.

According to the 2020 Edition of NFPA 25 Section 5.3.1.3, "Where one sprinkler within a representative sample fails to meet the test requirement, all sprinklers within the area represented by that sample shall be replaced." Should the product(s) represented by this sample remain in service, it shall be listed for use in your system/application and must be resampled and tested in 5 or 10 years in accordance with NFPA 25 2020 Ed. 5.3.1.

Roberto Gonzalez, Lab Analyst

Allo Ne Borre

