EOSI ASSIGNMENT 1

Sushant Trivedi: 1213366971

Ravi Kumar Bhushan: 1214347783

COMMANDS TO EXECUTED THE DRIVERS

HASH DRIVER

- 1. Copy all the files to same location and run the makefile in the respective folders
- 2. Run the make file to compile the driver file (Hash_Driver.c)
- 3. Copy stuff to Galileo via Ethernet

```
scp hashtester root@192.168.1.10:/home/
```

scp Hash Driver.ko root@192.168.1.10:/home/

4. In galileo board, execute the following command:

cd /home/ insmod Hash_Driver.ko ./hashtester

KPROBE DRIVER

- 1. Copy all the files to same location and run the makefile in the respective folders
- 2. Run the make file to compile the driver file (Mprobe.c)
- 3. Copy stuff to Galileo via Ethernet

scp kprobetester root@192.168.1.10:/home/ scp Hash_Driver.ko root@192.168.1.10:/home/ scp Mprobe.ko root@192.168.1.10:/home/

4. In galileo board, execute the following command:

cd /home/ insmod Hash_Driver.ko insmod Mprobe.ko ./kprobetester 1

To Check Output

to check kernel output: dmesg|grep "Mprobe"|grep "HT530"