

PREMIUM IMPORT IGNITION WIRE SETS

INCLUDING COIL-ON-PLUG BOOTS

APPLICATION & ILLUSTRATED
PARTS GUIDE



Intermotor™
Genuine Import Parts



THE ULTIMATE IMPORT WIRE

FIT

MATCHING BOOTS

Intermotor™ wire sets feature OE style import spark plug and distributor boots that look, fit, and perform like the original components. Engineered for extra-durability, long service life and a smooth installation, Intermotor™ premium import boots provide the right fit and a tight weatherproof seal.



PROTECTION & POWER

WIRE CORE & JACKET

Power can't flow if the wire jacket is compromised. That's why Intermotor™ developed a patented hi-gloss clear coat layer that's permanently bonded to our hi-temp silicone jacket. This combination provides powerful protection from engine heat and the potential damage found in today's import engines.

Intermotor™ wire conductors feature precision-matched resistance values to ensure maximum voltage delivery and spark duration while meeting all noise suppression requirements that shield sensitive electronic computers and sensors from interference. The result is clean energy flow for ultimate performance and import power.



EXTRAS

CLIPS • TRAYS • LOOM

NUMBERED LEADS

We've gone to great lengths to build an import wire set that guards against damage and creates a clear path for power.

Intermotor™ factory-installed separator clips, anchors, loom channels and trays* keep wires sorted properly and safely to protect against arcing, cross-fire, electromagnetic interference, and damage. Convoluted loom and spiral wrap* protect against abrasion that can cause premature wire failure.

We've even individually numbered each wire lead by cylinder to ensure Intermotor™ import wire sets provide a flawless installation with genuine import performance.



Intermotor™
Genuine Import Parts
PREMIUM IMPORT IGNITION WIRE SETS

* Factory installed upgrades are specific to vehicle make and model

TABLE OF CONTENTS

| Content | Page |
|---|--------------------|
| The Ultimate Import Wire | Inside front Cover |
| Table of Contents | I |
| Application Guide Index | II |
| Illustrated Parts Guide Numerical Index | III - IV |
| Application Guide..... | 1 - 32 |
| Illustrated Parts Guide | 33 – 55 |
| Warranty | Inside Back Cover |

TABLE DES MATIÈRES

| Contenu | Page |
|--|-----------------------------------|
| Le fil d'importation Ultimate | Deuxième de couverture |
| Table des Matières | I |
| Index de l'application | II |
| Index Guide Illustré des Pièces Numériques | III - IV |
| Guide d'application | 1 - 32 |
| Guide illustré des Pièces Garantie | 33 – 55 |
| Garantie | Intérieur Quatrième de couverture |

CONTENIDO

| Contenido | Página |
|---|------------------------|
| Los cables de Importación Ultimo | Portada interior |
| Tabla De Contenido | I |
| Índice de Aplicaciones | II |
| Índice Guía Ilustrada de Piezas Numéricas | III – IV |
| Guía de Aplicación | 1 – 32 |
| Guía Ilustrada de Piezas | 33 – 55 |
| Garantía | Contraportada interior |

APPLICATION INDEX

| | |
|--------------------------|-------|
| ACURA | |
| SPARK PLUG WIRE SET..... | 1 |
| ALFA ROMEO | |
| SPARK PLUG WIRE SET..... | 1 |
| ASUNA | |
| SPARK PLUG WIRE SET..... | 1 |
| AUDI | |
| COIL ON PLUG BOOT..... | 2 |
| SPARK PLUG WIRE SET..... | 2-3 |
| AUSTIN | |
| SPARK PLUG WIRE SET..... | 3 |
| BERTONE | |
| SPARK PLUG WIRE SET..... | 3 |
| BMW | |
| COIL ON PLUG BOOT..... | 3-4 |
| SPARK PLUG WIRE SET..... | 4-5 |
| DAEWOO | |
| SPARK PLUG WIRE SET..... | 5 |
| DAIHATSU | |
| SPARK PLUG WIRE SET..... | 5 |
| DODGE | |
| SPARK PLUG WIRE SET..... | 6 |
| EAGLE | |
| SPARK PLUG WIRE SET..... | 6 |
| FIAT | |
| SPARK PLUG WIRE SET..... | 6 |
| GEO | |
| SPARK PLUG WIRE SET..... | 6 |
| HONDA | |
| COIL ON PLUG BOOT..... | 7 |
| SPARK PLUG WIRE SET..... | 7 |
| HYUNDAI | |
| COIL ON PLUG BOOT..... | 8 |
| SPARK PLUG WIRE SET..... | 8 |
| INFINTI | |
| COIL ON PLUG BOOT..... | 8-9 |
| SPARK PLUG WIRE SET..... | 9 |
| ISUZU | |
| COIL ON PLUG BOOT..... | 9 |
| SPARK PLUG WIRE SET..... | 9-10 |
| JAGUAR | |
| COIL ON PLUG BOOT..... | 10 |
| SPARK PLUG WIRE SET..... | 10-11 |
| KIA | |
| COIL ON PLUG BOOT..... | 11 |
| SPARK PLUG WIRE SET..... | 11 |
| LADA | |
| SPARK PLUG WIRE SET..... | 12 |
| LAND ROVER | |
| COIL ON PLUG BOOT..... | 12 |
| SPARK PLUG WIRE SET..... | 12 |
| LEXUS | |
| COIL ON PLUG BOOT..... | 12 |
| SPARK PLUG WIRE SET..... | 12 |
| MAZDA | |
| COIL ON PLUG BOOT..... | 13 |
| SPARK PLUG WIRE SET..... | 13-14 |
| MERCEDES-BENZ | |
| COIL ON PLUG BOOT..... | 14 |
| SPARK PLUG WIRE SET..... | 14-17 |
| MG | |
| COIL ON PLUG BOOT..... | 17 |
| MINI | |
| SPARK PLUG WIRE SET..... | 18 |

| | |
|--------------------------|-------|
| MITSUBISHI | |
| COIL ON PLUG BOOT..... | 18 |
| SPARK PLUG WIRE SET..... | 18-19 |
| MORRIS | |
| SPARK PLUG WIRE SET..... | 19 |
| NISSAN | |
| COIL ON PLUG BOOT..... | 19-20 |
| SPARK PLUG WIRE SET..... | 20-21 |
| OPEL | |
| SPARK PLUG WIRE SET..... | 21 |
| PEUGEOT | |
| SPARK PLUG WIRE SET..... | 22 |
| PLYMOUTH | |
| SPARK PLUG WIRE SET..... | 22 |
| PORSCHE | |
| COIL ON PLUG BOOT..... | 22 |
| SPARK PLUG WIRE SET..... | 22-23 |
| RENAULT | |
| SPARK PLUG WIRE SET..... | 23 |
| ROVER | |
| SPARK PLUG WIRE SET..... | 24 |
| SAAB | |
| SPARK PLUG WIRE SET..... | 24 |
| STERLING | |
| SPARK PLUG WIRE SET..... | 24 |
| SUBARU | |
| COIL ON PLUG BOOT..... | 24 |
| SPARK PLUG WIRE SET..... | 25-26 |
| SUZUKI | |
| COIL ON PLUG BOOT..... | 26 |
| SPARK PLUG WIRE SET..... | 26 |
| TOYOTA | |
| COIL ON PLUG BOOT..... | 27 |
| SPARK PLUG WIRE SET..... | 27-29 |
| TRIUMPH | |
| SPARK PLUG WIRE SET..... | 29 |
| VOLKSWAGEN | |
| COIL ON PLUG BOOT..... | 29 |
| SPARK PLUG WIRE SET..... | 29-31 |
| VOLVO | |
| COIL ON PLUG BOOT..... | 31 |
| SPARK PLUG WIRE SET..... | 31-32 |
| YUGO | |
| SPARK PLUG WIRE SET..... | 32 |

NUMERICAL INDEX

| Part No | Page No. | Part No | Page No. | Part No | Page No. | Part No | Page No. |
|---------------|----------|---------------|----------|-------------|----------|-------------|----------|
| SPP42 | 33 | SPP118E | 35 | 55125 | 38 | 55323 | 41 |
| SPP48 | 33 | SPP121E | 35 | 55126 | 38 | 55324 | 41 |
| SPP49 | 33 | SPP122E | 35 | 55127 | 38 | 55325 | 41 |
| SPP50 | 33 | 55000 | 35 | 55128 | 38 | 55326 | 41 |
| SPP51 | 33 | 55001 | 35 | 55129 | 38 | 55327 | 41 |
| SPP52 | 33 | 55002 | 35 | 55130 | 38 | 55328 | 41 |
| SPP53 | 33 | 55003 | 35 | 55131 | 38 | 55329 | 41 |
| SPP54 | 33 | 55004 | 35 | 55132 | 38 | 55330 | 41 |
| SPP55 | 33 | 55005 | 35 | 55133 | 38 | 55331 | 42 |
| SPP56 | 33 | 55006 | 36 | 55200 | 39 | 55332 | 42 |
| SPP57 | 33 | 55007 | 36 | 55201 | 39 | 55333 | 42 |
| SPP58 | 33 | 55008 | 36 | 55202 | 39 | 55334 | 42 |
| SPP60 | 33 | 55009 | 36 | 55203 | 39 | 55335 | 42 |
| SPP61 | 33 | 55010 | 36 | 55204 | 39 | 55337 | 42 |
| SPP62 | 33 | 55011 | 36 | 55205 | 39 | 55338 | 42 |
| SPP63 | 33 | 55012 | 36 | 55206 | 39 | 55339 | 42 |
| SPP67 | 33 | 55013 | 36 | 55207 | 39 | 55400 | 42 |
| SPP69 | 33 | 55014 | 36 | 55208 | 39 | 55401 | 42 |
| SPP70 | 33 | 55015 | 36 | 55209 | 39 | 55402 | 42 |
| SPP71 | 33 | 55016 | 36 | 55210 | 39 | 55403 | 42 |
| SPP72 | 33 | 55017 | 36 | 55211 | 39 | 55404 | 42 |
| SPP73 | 33 | 55018 | 36 | 55212 | 39 | 55405 | 42 |
| SPP74 | 33 | 55019 | 36 | 55213 | 39 | 55406 | 42 |
| SPP75 | 33 | 55020 | 36 | 55214 | 39 | 55407 | 42 |
| SPP76 | 34 | 55021 | 36 | 55215 | 39 | 55408 | 42 |
| SPP77 | 34 | 55022 | 36 | 55216 | 39 | 55409 | 42 |
| SPP78 | 34 | 55023 | 36 | 55217 | 39 | 55410 | 42 |
| SPP79 | 34 | 55024 | 36 | 55218 | 39 | 55411 | 42 |
| SPP80 | 34 | 55025 | 36 | 55219 | 40 | 55412 | 43 |
| SPP81 | 34 | 55026 | 37 | 55220 | 40 | 55413 | 43 |
| SPP82 | 34 | 55027 | 37 | 55221 | 40 | 55414 | 43 |
| SPP83 | 34 | 55028 | 37 | 55222 | 40 | 55415 | 43 |
| SPP84 | 34 | 55029 | 37 | 55223 | 40 | 55416 | 43 |
| SPP85 | 34 | 55030 | 37 | 55224 | 40 | 55417 | 43 |
| SPP86 | 34 | 55100 | 37 | 55225 | 40 | 55418 | 43 |
| SPP88 | 34 | 55101 | 37 | 55226 | 40 | 55419 | 43 |
| SPP89 | 34 | 55102 | 37 | 55300 | 40 | 55420 | 43 |
| SPP91 | 34 | 55103 | 37 | 55301 | 40 | 55421 | 43 |
| SPP92 | 34 | 55104 | 37 | 55302 | 40 | 55422 | 43 |
| SPP93 | 34 | 55105 | 37 | 55303 | 40 | 55423 | 43 |
| SPP94 | 34 | 55106 | 37 | 55304 | 40 | 55424 | 43 |
| SPP95 | 34 | 55107 | 37 | 55305 | 40 | 55425 | 43 |
| SPP96 | 34 | 55108 | 37 | 55306 | 40 | 55426 | 43 |
| SPP97 | 34 | 55109 | 37 | 55307 | 40 | 55427 | 43 |
| SPP98 | 34 | 55110 | 37 | 55308 | 40 | 55428 | 43 |
| SPP99 | 34 | 55111 | 37 | 55309 | 40 | 55429 | 43 |
| SPP100 | 34 | 55112 | 37 | 55310 | 40 | 55430 | 43 |
| SPP101 | 35 | 55113 | 37 | 55311 | 41 | 55431 | 44 |
| SPP102 | 35 | 55114 | 37 | 55312 | 41 | 55432 | 44 |
| SPP104 | 35 | 55115 | 38 | 55313 | 41 | 55433 | 44 |
| SPP105 | 35 | 55116 | 38 | 55314 | 41 | 55434 | 44 |
| SPP106 | 35 | 55117 | 38 | 55315 | 41 | 55435 | 44 |
| SPP108 | 35 | 55118 | 38 | 55316 | 41 | 55436 | 44 |
| SPP109 | 35 | 55119 | 38 | 55317 | 41 | 55437 | 44 |
| SPP110 | 35 | 55120 | 38 | 55318 | 41 | 55438 | 44 |
| SPP111E | 35 | 55121 | 38 | 55319 | 41 | 55439 | 44 |
| SPP112E | 35 | 55122 | 38 | 55320 | 41 | 55440 | 44 |
| SPP114E | 35 | 55123 | 38 | 55321 | 41 | 55441 | 44 |
| SPP115E | 35 | 55124 | 38 | 55322 | 41 | | |

NUMERICAL INDEX

| Part No | Page No. |
|-------------|----------|-------------|----------|-------------|----------|-------------|----------|
| 55442 | 44 | 55610 | 47 | 55764 | 50 | 55928 | 53 |
| 55443 | 44 | 55611 | 47 | 55765 | 50 | 55929 | 53 |
| 55444 | 44 | 55612 | 47 | 55766 | 50 | 55930 | 53 |
| 55445 | 44 | 55613 | 47 | 55767 | 50 | 55931 | 54 |
| 55446 | 44 | 55614 | 47 | 55768 | 50 | 55932 | 54 |
| 55447 | 44 | 55615 | 47 | 55769 | 51 | 55933 | 54 |
| 55448 | 44 | 55616 | 47 | 55770 | 51 | 55934 | 54 |
| 55449 | 44 | 55617 | 48 | 55771 | 51 | 55935 | 54 |
| 55450 | 45 | 55618 | 48 | 55772 | 51 | 55936 | 54 |
| 55451 | 45 | 55619 | 48 | 55773 | 51 | 55937 | 54 |
| 55452 | 45 | 55620 | 48 | 55774 | 51 | 55938 | 54 |
| 55453 | 45 | 55621 | 48 | 55775 | 51 | 55939 | 54 |
| 55454 | 45 | 55622 | 48 | 55776 | 51 | 55940 | 54 |
| 55455 | 45 | 55623 | 48 | 55777 | 51 | 55941 | 54 |
| 55456 | 45 | 55624 | 48 | 55778 | 51 | 55942 | 54 |
| 55457 | 45 | 55625 | 48 | 55800 | 51 | 55943 | 54 |
| 55458 | 45 | 55626 | 48 | 55801 | 51 | 55944 | 54 |
| 55459 | 45 | 55627 | 48 | 55802 | 51 | 55945 | 54 |
| 55460 | 45 | 55628 | 48 | 55803 | 51 | 55946 | 54 |
| 55461 | 45 | 55629 | 48 | 55804 | 51 | 55947 | 54 |
| 55500 | 45 | 55631 | 48 | 55805 | 51 | 55948 | 54 |
| 55501 | 45 | 55632 | 48 | 55806 | 51 | 55949 | 54 |
| 55502 | 45 | 55633 | 48 | 55807 | 51 | 55950 | 55 |
| 55503 | 45 | 55634 | 48 | 55808 | 51 | 55951 | 55 |
| 55504 | 45 | 55635 | 48 | 55809 | 52 | 55952 | 55 |
| 55505 | 45 | 55636 | 48 | 55810 | 52 | 55953 | 55 |
| 55506 | 45 | 55637 | 49 | 55811 | 52 | 55954 | 55 |
| 55507 | 46 | 55638 | 49 | 55812 | 52 | 55955 | 55 |
| 55508 | 46 | 55639 | 49 | 55813 | 52 | 55956 | 55 |
| 55509 | 46 | 55640 | 49 | 55814 | 52 | 55957 | 55 |
| 55510 | 46 | 55641 | 49 | 55815 | 52 | 55958 | 55 |
| 55511 | 46 | 55642 | 49 | 55900 | 52 | | |
| 55512 | 46 | 55643 | 49 | 55901 | 52 | | |
| 55513 | 46 | 55644 | 49 | 55902 | 52 | | |
| 55514 | 46 | 55700 | 49 | 55903 | 52 | | |
| 55515 | 46 | 55701 | 49 | 55904 | 52 | | |
| 55516 | 46 | 55702 | 49 | 55905 | 52 | | |
| 55550 | 46 | 55703 | 49 | 55906 | 52 | | |
| 55551 | 46 | 55704 | 49 | 55907 | 52 | | |
| 55552 | 46 | 55705 | 49 | 55908 | 52 | | |
| 55553 | 46 | 55706 | 49 | 55909 | 52 | | |
| 55554 | 46 | 55707 | 49 | 55910 | 52 | | |
| 55555 | 46 | 55708 | 49 | 55911 | 52 | | |
| 55556 | 46 | 55709 | 49 | 55912 | 53 | | |
| 55557 | 46 | 55710 | 49 | 55913 | 53 | | |
| 55558 | 46 | 55711 | 49 | 55914 | 53 | | |
| 55559 | 46 | 55712 | 50 | 55915 | 53 | | |
| 55560 | 47 | 55713 | 50 | 55916 | 53 | | |
| 55561 | 47 | 55714 | 50 | 55917 | 53 | | |
| 55600 | 47 | 55715 | 50 | 55918 | 53 | | |
| 55601 | 47 | 55716 | 50 | 55919 | 53 | | |
| 55602 | 47 | 55717 | 50 | 55920 | 53 | | |
| 55603 | 47 | 55718 | 50 | 55921 | 53 | | |
| 55604 | 47 | 55719 | 50 | 55922 | 53 | | |
| 55605 | 47 | 55720 | 50 | 55923 | 53 | | |
| 55606 | 47 | 55760 | 50 | 55924 | 53 | | |
| 55607 | 47 | 55761 | 50 | 55925 | 53 | | |
| 55608 | 47 | 55762 | 50 | 55926 | 53 | | |
| 55609 | 47 | 55763 | 50 | 55927 | 53 | | |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|--------------------------------|--------------|
| CL | | |
| 99-98 | 4 Cyl. 2.3 Eng..... | 55000 |
| 99-98 | 6 Cyl. 3.0 Eng..... | 55012 |
| 97 | 4 Cyl. 2.2 Eng..... | 55000 |
| 97 | 6 Cyl. 3.0 Eng..... | 55012 |
| EL | | |
| 00-97 | 4 Cyl. 1.6 Eng..... | 55001 |
| INTEGRA | | |
| 01-96 | 4 Cyl. 1.8 Eng.; VTEC..... | 55013 |
| 01-96 | 4 Cyl. 1.8 Eng.; Exc. VTEC.... | 55004 |
| 95-94 | 4 Cyl. 1.8 Eng.; VTEC..... | 55013 |
| 95-94 | 4 Cyl. 1.8 Eng.; Exc. VTEC.... | 55006 |
| 93-92 | 4 Cyl. 1.7 Eng..... | 55013 |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55005 |
| 91-90 | 4 Cyl. 1.8 Eng..... | 55005 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|---------------------|--------------|
| INTEGRA | | |
| 89-86 | 4 Cyl. 1.6 Eng..... | 55020 |
| LEGEND | | |
| 90-88 | 6 Cyl. 2.7 Eng..... | 55018 |
| 87 | 6 Cyl. 2.5 Eng..... | 55018 |
| 87 | 6 Cyl. 2.7 Eng..... | 55018 |
| 86 | 6 Cyl. 2.5 Eng..... | 55018 |
| TL | | |
| 98-95 | 5 Cyl. 2.5 Eng..... | 55019 |
| VIGOR | | |
| 94-92 | 5 Cyl. 2.5 Eng..... | 55019 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------------|---------------------|--------------|
| 1900 | | |
| 58-55 | 4 Cyl. 2.0 Eng..... | 55461 |
| 1900C | | |
| 57-55 | 4 Cyl. 2.0 Eng..... | 55461 |
| 2000 | | |
| 62-58 | 4 Cyl. 2.0 Eng..... | 55461 |
| ALFETTA | | |
| 77-75 | 4 Cyl. 2.0 Eng..... | 55461 |
| BERLINA | | |
| 74-73 | 4 Cyl. 2.0 Eng..... | 55461 |
| 72-70 | 4 Cyl. 1.8 Eng..... | 55461 |
| 72-70 | 4 Cyl. 2.0 Eng..... | 55461 |
| 69 | 4 Cyl. 1.8 Eng..... | 55461 |
| DUETTO | | |
| 68-66 | 4 Cyl. 1.6 Eng..... | 55461 |
| GIULIA | | |
| 68-62 | 4 Cyl. 1.6 Eng..... | 55461 |
| GIULIA SPRINT | | |
| 68-62 | 4 Cyl. 1.6 Eng..... | 55461 |
| GIULIETTA | | |
| 63-55 | 4 Cyl. 1.3 Eng..... | 55461 |
| GT VELOCE | | |
| 74-72 | 4 Cyl. 2.0 Eng..... | 55461 |
| 71-69 | 4 Cyl. 1.8 Eng..... | 55461 |

Continued on Next Column

ALFA ROMEO**SPARK PLUG WIRE SET**

| Year | Model | Part No. |
|--------------------|---------------------|--------------|
| GTA | | |
| 65 | 4 Cyl. 1.6 Eng..... | 55461 |
| GTV / GTV-6 | | |
| 68-67 | 4 Cyl. 1.6 Eng..... | 55461 |
| 65 | 4 Cyl. 1.6 Eng..... | 55461 |
| GTZ | | |
| 64 | 4 Cyl. 1.6 Eng..... | 55461 |
| SPIDER | | |
| 94-82 | 4 Cyl. 2.0 Eng..... | 55443 |
| 81-72 | 4 Cyl. 2.0 Eng..... | 55461 |
| 71-70 | 4 Cyl. 1.8 Eng..... | 55461 |
| 71-70 | 4 Cyl. 2.0 Eng..... | 55461 |
| 69 | 4 Cyl. 1.8 Eng..... | 55461 |
| SPORT | | |
| 79-78 | 4 Cyl. 2.0 Eng..... | 55461 |
| SPRINT | | |
| 79-77 | 4 Cyl. 2.0 Eng..... | 55461 |
| TZ | | |
| 67 | 4 Cyl. 1.6 Eng..... | 55461 |
| TZ 2 | | |
| 65 | 4 Cyl. 1.6 Eng..... | 55461 |

ASUNA**SPARK PLUG WIRE SET**

| Year | Model | Part No. |
|------------------|---------------------|--------------|
| SUNFIRE | | |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55405 |
| SUNRUNNER | | |
| 94-92 | 4 Cyl. 1.6 Eng..... | 55425 |

AUDI

COIL ON PLUG BOOT

| Year | Model | | Part No. |
|-------|---------------------|-------------------|--------------|
| 99-97 | 4 Cyl. 1.8 Eng..... | A4 | SPP56 |
| 00-97 | 4 Cyl. 1.8 Eng..... | A4 QUATTRO | SPP56 |
| 99-97 | 8 Cyl. 3.7 Eng..... | A8 | SPP57 |
| 99-97 | 8 Cyl. 4.2 Eng..... | A8 QUATTRO | SPP57 |
| 94-92 | 5 Cyl. 2.2 Eng..... | S4 | SPP58 |
| 97-95 | 5 Cyl. 2.2 Eng..... | S6 | SPP58 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|--------------|
| | 100 | |
| 94-92 | 6 Cyl. 2.8 Eng..... | 55617 |
| 91-89 | 5 Cyl. 2.3 Eng..... | 55624 |
| | 100 QUATTRO | |
| 94-92 | 6 Cyl. 2.8 Eng..... | 55617 |
| 91-89 | 5 Cyl. 2.3 Eng..... | 55624 |
| | 100 SERIES | |
| 77 | 4 Cyl. 1.9 Eng..... | 55618 |
| 76-75 | 4 Cyl. 1.9 Eng.; Exc. Electronic Ignition..... | 55618 |
| 74-72 | 4 Cyl. 1.9 Eng..... | 55618 |
| 71-69 | 4 Cyl. 1.8 Eng..... | 55618 |
| | 200 | |
| 91 | 5 Cyl. 2.2 Eng..... | 55605 |
| 90-89 | 5 Cyl. 2.2 Eng..... | 55632 |
| | 200 QUATTRO | |
| 91 | 5 Cyl. 2.2 Eng..... | 55605 |
| 90-89 | 5 Cyl. 2.2 Eng..... | 55632 |
| | 4000 | |
| 87 | 4 Cyl. 1.8 Eng..... | 55609 |
| 86 | 4 Cyl. 1.8 Eng..... | 55609 |
| 86 | 5 Cyl. 2.2 Eng..... | 55625 |
| 85 | 4 Cyl. 1.8 Eng..... | 55609 |
| 85 | 5 Cyl. 2.2 Eng..... | 55620 |
| 84 | 4 Cyl. 1.8 Eng..... | 55637 |
| 84 | 5 Cyl. 2.2 Eng..... | 55632 |
| 83-82 | 4 Cyl. 1.6 Eng..... | 55637 |
| 83-82 | 4 Cyl. 1.7 Eng..... | 55637 |
| 83-82 | 5 Cyl. 2.2 Eng..... | 55632 |
| 81 | 4 Cyl. 1.7 Eng..... | 55637 |
| 81 | 5 Cyl. 2.2 Eng..... | 55632 |
| 80 | 4 Cyl. 1.6 Eng..... | 55637 |
| 80 | 5 Cyl. 2.2 Eng..... | 55625 |
| | 4000 QUATTRO | |
| 87-86 | 5 Cyl. 2.2 Eng..... | 55625 |
| 85 | 5 Cyl. 2.2 Eng..... | 55620 |
| 84 | 5 Cyl. 2.2 Eng..... | 55632 |
| | 4000S | |
| 84 | 4 Cyl. 1.8 Eng..... | 55637 |
| 84 | 5 Cyl. 2.2 Eng..... | 55632 |
| | 4000S QUATTRO | |
| 84 | 5 Cyl. 2.2 Eng..... | 55632 |
| | 5000 | |
| 88 | 5 Cyl. 2.2 Eng..... | 55625 |
| 88 | 5 Cyl. 2.3 Eng..... | 55625 |
| 87 | 5 Cyl. 2.2 Eng..... | 55625 |
| 87 | 5 Cyl. 2.3 Eng..... | 55632 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | 5000 | |
| 86 | 5 Cyl. 2.2 Eng..... | 55625 |
| 85 | 5 Cyl. 2.0 Eng..... | 55625 |
| 85 | 5 Cyl. 2.2 Eng.; w/o Turbo.... | 55632 |
| 85 | 5 Cyl. 2.2 Eng.; w/ Turbo.... | 55625 |
| 84-82 | 5 Cyl. 2.0 Eng..... | 55625 |
| 84-82 | 5 Cyl. 2.2 Eng..... | 55625 |
| 81-78 | 5 Cyl. 2.2 Eng..... | 55625 |
| | 5000 QUATTRO | |
| 88 | 5 Cyl. 2.2 Eng..... | 55625 |
| 88 | 5 Cyl. 2.3 Eng..... | 55625 |
| 87 | 5 Cyl. 2.2 Eng..... | 55625 |
| 87 | 5 Cyl. 2.3 Eng..... | 55632 |
| 86 | 5 Cyl. 2.2 Eng..... | 55625 |
| | 5000S QUATTRO | |
| 88 | 5 Cyl. 2.3 Eng..... | 55632 |
| | 80 | |
| 92-91 | 5 Cyl. 2.3 Eng..... | 55624 |
| 90-88 | 4 Cyl. 2.0 Eng..... | 55609 |
| | 80 QUATTRO | |
| 92-88 | 5 Cyl. 2.3 Eng..... | 55624 |
| | 90 | |
| 95-93 | 6 Cyl. 2.8 Eng..... | 55617 |
| 91-89 | 5 Cyl. 2.3 Eng..... | 55624 |
| 88 | 4 Cyl. 2.0 Eng..... | 55609 |
| 88 | 5 Cyl. 2.3 Eng..... | 55624 |
| | 90 QUATTRO | |
| 95-93 | 6 Cyl. 2.8 Eng..... | 55617 |
| 91-90 | 5 Cyl. 2.3 Eng..... | 55604 |
| 89-88 | 5 Cyl. 2.3 Eng..... | 55624 |
| | A4 | |
| 01-98 | 6 Cyl. 2.8 Eng..... | 55603 |
| 97 | 6 Cyl. 2.8 Eng.; AHA Eng..... | 55603 |
| 97 | 6 Cyl. 2.8 Eng.; AFC Eng..... | 55617 |
| 96 | 6 Cyl. 2.8 Eng..... | 55617 |
| | A4 QUATTRO | |
| 01-98 | 6 Cyl. 2.8 Eng..... | 55603 |
| 97-96 | 6 Cyl. 2.8 Eng..... | 55617 |
| | A6 | |
| 01-99 | 6 Cyl. 2.8 Eng..... | 55603 |
| 98 | 6 Cyl. 2.8 Eng.; AHA Eng..... | 55603 |
| 98 | 6 Cyl. 2.8 Eng.; AFC Eng..... | 55617 |
| 97-95 | 6 Cyl. 2.8 Eng..... | 55617 |
| | A6 QUATTRO | |
| 01-99 | 6 Cyl. 2.8 Eng..... | 55603 |
| 98 | 6 Cyl. 2.8 Eng.; AHA Eng..... | 55603 |
| 98 | 6 Cyl. 2.8 Eng.; AFC Eng..... | 55617 |

Continued on Next Page

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | A6 QUATTRO | |
| 97-95 | 6 Cyl. 2.8 Eng..... | 55617 |
| | CABRIOLET | |
| 98-94 | 6 Cyl. 2.8 Eng..... | 55617 |
| | COUPE | |
| 87 | 5 Cyl. 2.2 Eng..... | 55632 |
| 87 | 5 Cyl. 2.3 Eng..... | 55625 |
| 86-81 | 5 Cyl. 2.2 Eng..... | 55625 |
| | COUPE QUATTRO | |
| 91-90 | 5 Cyl. 2.3 Eng..... | 55604 |
| | FOX | |
| 79-75 | 4 Cyl. 1.6 Eng..... | 55611 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | FOX | |
| 74-73 | 4 Cyl. 1.5 Eng..... | 55611 |
| | QUATTRO | |
| 86-83 | 5 Cyl. 2.2 Eng..... | 55625 |
| | SUPER 90 | |
| 72-69 | 4 Cyl. 1.8 Eng..... | 55618 |
| | V8 QUATTRO | |
| 94-92 | 8 Cyl. 4.2 Eng..... | 55643 |
| 91-90 | 8 Cyl. 3.6 Eng..... | 55643 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | AMERICA | |
| 72-68 | 4 Cyl. 1.3 Eng..... | 55429 |
| | AUSTIN HEALEY | |
| 69 | 4 Cyl. 1.3 Eng..... | 55429 |
| 68-67 | 4 Cyl. 1.3 Eng..... | 55459 |
| 66 | 4 Cyl. 1.1 Eng..... | 55459 |
| 66 | 4 Cyl. 1.3 Eng..... | 55459 |
| 65-63 | 4 Cyl. 1.1 Eng..... | 55459 |
| 62 | 4 Cyl. 1.0 Eng..... | 55459 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | AUSTIN HEALEY | |
| 62 | 4 Cyl. 1.1 Eng..... | 55459 |
| | MARINA | |
| 75-73 | 4 Cyl. 1.8 Eng..... | 55429 |
| | MINI COOPER | |
| 69-68 | 4 Cyl. 1.3 Eng..... | 55429 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | | X-1/9 |
| 89-86 | 4 Cyl. 1.5 Eng..... | 55439 |
| 85-84 | 4 Cyl. 1.5 Eng..... | 55439 |

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|---------------------|----------|
| | 320I | |
| 05 | 6 Cyl. 2.2 Eng..... | SPP69 |
| 04-01 | 6 Cyl. 2.0 Eng..... | SPP69 |
| 04-01 | 6 Cyl. 2.2 Eng..... | SPP69 |
| 95-94 | 6 Cyl. 2.0 Eng..... | SPP67 |
| 92 | 6 Cyl. 2.0 Eng..... | SPP67 |
| | 323CI | |
| 00 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 323I | |
| 00-99 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 323IC | |
| 99-98 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 323IS | |
| 99-98 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 325CI | |
| 02-01 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 325I | |
| 02-01 | 6 Cyl. 2.5 Eng..... | SPP69 |
| 95-92 | 6 Cyl. 2.5 Eng..... | SPP67 |
| | 325IC | |
| 95-92 | 6 Cyl. 2.5 Eng..... | SPP67 |

Continued on Next Column

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|---------------------|----------|
| | 325IS | |
| 95-92 | 6 Cyl. 2.5 Eng..... | SPP67 |
| | 325XI | |
| 02-01 | 6 Cyl. 2.5 Eng..... | SPP69 |
| | 328CI | |
| 00 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 328I | |
| 00-96 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 328IC | |
| 99-96 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 328IS | |
| 99-96 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 330CI | |
| 02-01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| | 330I | |
| 02-01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| | 330XI | |
| 02-01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| | 525I | |
| 03-01 | 6 Cyl. 2.5 Eng..... | SPP69 |
| 95-91 | 6 Cyl. 2.5 Eng..... | SPP67 |

Continued on Next Page

BMW

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|------------------------|--------------|
| | 525IT | |
| 95-93 | 6 Cyl. 2.5 Eng..... | SPP67 |
| | 528I | |
| 00-97 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 528IT | |
| 00-99 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | 530I | |
| 03-01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| 95-94 | 8 Cyl. 3.0 Eng..... | SPP67 |
| | 530IT | |
| 95-94 | 8 Cyl. 3.0 Eng..... | SPP67 |
| | 540I | |
| 03-97 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 95-94 | 8 Cyl. 4.0 Eng..... | SPP67 |
| | 540IT | |
| 00-99 | 8 Cyl. 4.4 Eng..... | SPP69 |
| | 740I | |
| 01-97 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 95-93 | 8 Cyl. 4.0 Eng..... | SPP67 |
| | 740IL | |
| 01-96 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 95-93 | 8 Cyl. 4.0 Eng..... | SPP67 |
| | 840CI | |
| 97-96 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 95-94 | 8 Cyl. 4.0 Eng..... | SPP67 |
| | ALPINA ROADSTER | |
| 03 | 8 Cyl. 4.8 Eng..... | SPP67 |
| | M3 | |
| 01 | 6 Cyl. 3.2 Eng..... | SPP67 |
| 99-96 | 6 Cyl. 3.2 Eng..... | SPP67 |
| 95-94 | 6 Cyl. 3.0 Eng..... | SPP67 |
| | M5 | |
| 03-00 | 8 Cyl. 5.0 Eng..... | SPP67 |
| | X5 | |
| 03 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 03 | 8 Cyl. 4.6 Eng..... | SPP69 |
| 02 | 6 Cyl. 3.0 Eng..... | SPP69 |
| 02 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 02 | 8 Cyl. 4.6 Eng..... | SPP69 |
| 01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| 01 | 8 Cyl. 4.4 Eng..... | SPP69 |
| 00 | 8 Cyl. 4.4 Eng..... | SPP69 |
| | Z3 | |
| 02 | 6 Cyl. 2.5 Eng..... | SPP69 |
| 02 | 6 Cyl. 3.0 Eng..... | SPP69 |
| 01 | 6 Cyl. 2.5 Eng..... | SPP69 |
| 01 | 6 Cyl. 3.0 Eng..... | SPP69 |
| 01 | 6 Cyl. 3.2 Eng..... | SPP69 |
| 00-99 | 6 Cyl. 2.5 Eng..... | SPP69 |
| 00-99 | 6 Cyl. 2.8 Eng..... | SPP69 |
| 00-99 | 6 Cyl. 3.2 Eng..... | SPP69 |
| 98 | 6 Cyl. 2.8 Eng..... | SPP69 |
| 98 | 6 Cyl. 3.2 Eng..... | SPP69 |
| 97 | 6 Cyl. 2.8 Eng..... | SPP69 |
| | Z8 | |
| 03-00 | 8 Cyl. 5.0 Eng..... | SPP69 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|-------------------------------|--------------|
| | 1800 | |
| 71-68 | 4 Cyl. 1.8 Eng..... | 55705 |
| | 1802 | |
| 71 | 4 Cyl. 1.8 Eng..... | 55705 |
| | 2.8 BAVARIA | |
| 71 | 6 Cyl. 2.8 Eng..... | 55706 |
| | 2000 | |
| 72-67 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2000C | |
| 70-67 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2000CS | |
| 70-67 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2000TI | |
| 71-67 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2000TII | |
| 72-68 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2002 | |
| 76-67 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2002TI | |
| 71-68 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2002TII | |
| 74-71 | 4 Cyl. 2.0 Eng..... | 55705 |
| | 2500 | |
| 71-68 | 6 Cyl. 2.5 Eng..... | 55706 |
| | 2800 | |
| 74-68 | 6 Cyl. 2.8 Eng..... | 55706 |
| | 2800CS | |
| 71-68 | 6 Cyl. 2.8 Eng..... | 55706 |
| | 3.0CS | |
| 74-71 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 3.0CSI | |
| 74-71 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 3.0CSL | |
| 71 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 3.0S | |
| 74-71 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 3.0SI | |
| 76-75 | 6 Cyl. 3.0 Eng..... | 55706 |
| 71 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 318I | |
| 98-96 | 4 Cyl. 1.9 Eng.; w/ Loom..... | 55704 |
| 95-94 | 4 Cyl. 1.8 Eng.; w/ Loom..... | 55704 |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55703 |
| 91 | 4 Cyl. 1.8 Eng..... | 55702 |
| 85-84 | 4 Cyl. 1.8 Eng.; w/ Loom..... | 55701 |
| | 318IC | |
| 97-96 | 4 Cyl. 1.9 Eng.; w/ Loom..... | 55704 |
| 95-94 | 4 Cyl. 1.8 Eng.; w/ Loom..... | 55704 |
| 92 | 4 Cyl. 1.8 Eng..... | 55703 |
| 91 | 4 Cyl. 1.8 Eng..... | 55702 |
| | 318IS | |
| 97-96 | 4 Cyl. 1.9 Eng.; w/ Loom..... | 55704 |
| 95-94 | 4 Cyl. 1.8 Eng.; w/ Loom..... | 55704 |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55703 |
| 91 | 4 Cyl. 1.8 Eng..... | 55702 |
| | 318TI | |
| 99-96 | 4 Cyl. 1.9 Eng.; w/ Loom..... | 55704 |
| 95 | 4 Cyl. 1.8 Eng.; w/ Loom..... | 55704 |
| | 320I | |
| 83-80 | 4 Cyl. 1.8 Eng..... | 55717 |
| 79-77 | 4 Cyl. 2.0 Eng..... | 55700 |
| | 325 | |
| 88-86 | 6 Cyl. 2.7 Eng.; w/ Loom..... | 55709 |

Continued on Next Column

Continued on Next Page

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|-------------------------------|--------------|
| | 325E | |
| 87-84 | 6 Cyl. 2.7 Eng.; w/ Loom..... | 55709 |
| | 325I | |
| 92-88 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55711 |
| 87 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55709 |
| | 325IC | |
| 92-88 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55711 |
| | 325IS | |
| 92-88 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55711 |
| 87 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55709 |
| | 325IX | |
| 91-88 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55711 |
| | 525I | |
| 90-89 | 6 Cyl. 2.5 Eng.; w/ Loom..... | 55710 |
| | 528E | |
| 88-85 | 6 Cyl. 2.7 Eng.; w/ Loom..... | 55709 |
| 84-82 | 6 Cyl. 2.7 Eng..... | 55716 |
| | 528I | |
| 81-79 | 6 Cyl. 2.8 Eng..... | 55706 |
| | 530I | |
| 78 | 6 Cyl. 3.0 Eng..... | 55706 |
| | 533I | |
| 84-83 | 6 Cyl. 3.2 Eng..... | 55716 |
| | 535I | |
| 93-88 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55712 |
| 87-85 | 6 Cyl. 3.5 Eng..... | 55713 |
| | 535IS | |
| 88 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55712 |
| | 633CSI | |
| 84-82 | 6 Cyl. 3.2 Eng..... | 55716 |
| 81-78 | 6 Cyl. 3.2 Eng..... | 55706 |
| | 635CSI | |
| 89-88 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55720 |
| 87-85 | 6 Cyl. 3.5 Eng..... | 55713 |
| | 733I | |
| 84-82 | 6 Cyl. 3.2 Eng..... | 55716 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | 733I | |
| 81-78 | 6 Cyl. 3.2 Eng..... | 55706 |
| | 735I | |
| 92-88 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55712 |
| 87-85 | 6 Cyl. 3.5 Eng..... | 55713 |
| | 735IL | |
| 92-88 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55712 |
| | 750IL | |
| 01-95 | 12 Cyl. 5.4 Eng.; w/ Loom..... | 55707 |
| 94-88 | 12 Cyl. 5.0 Eng.; w/ Loom..... | 55708 |
| | 850CI | |
| 97-95 | 12 Cyl. 5.4 Eng.; w/ Loom..... | 55715 |
| 94 | 12 Cyl. 5.0 Eng.; w/ Loom..... | 55715 |
| 93 | 12 Cyl. 5.0 Eng.; w/ Loom..... | 55708 |
| | 850CSI | |
| 95-94 | 12 Cyl. 5.6 Eng.; w/ Loom..... | 55715 |
| | 850I | |
| 92-91 | 12 Cyl. 5.0 Eng.; w/ Loom..... | 55708 |
| | L6 | |
| 87 | 6 Cyl. 3.5 Eng..... | 55713 |
| | L7 | |
| 87 | 6 Cyl. 3.5 Eng.; w/ Loom..... | 55712 |
| 86 | 6 Cyl. 3.5 Eng..... | 55713 |
| | M3 | |
| 91-88 | 4 Cyl. 2.3 Eng.; w/ Loom..... | 55718 |
| | M5 | |
| 93-91 | 6 Cyl. 3.6 Eng..... | 55714 |
| 88 | 6 Cyl. 3.5 Eng..... | 55719 |
| | M6 | |
| 88-87 | 6 Cyl. 3.5 Eng..... | 55719 |
| | Z3 | |
| 98-96 | 4 Cyl. 1.9 Eng.; w/ Loom..... | 55704 |

DAEWOO**SPARK PLUG WIRE SET**

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | LANOS | |
| 02-98 | 4 Cyl. 1.5 Eng..... | 55432 |
| 02-98 | 4 Cyl. 1.6 Eng..... | 55400 |
| 97 | 4 Cyl. 1.5 Eng..... | 55432 |
| | LEGANZA | |
| 02-99 | 4 Cyl. 2.2 Eng..... | 55402 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| 02-97 | NUBIRA | |
| 02-97 | 4 Cyl. 2.0 Eng..... | 55402 |

DAIHATSU**SPARK PLUG WIRE SET**

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | CHARADE | |
| 92-89 | 4 Cyl. 1.3 Eng..... | 55418 |
| | ROCKY | |
| 92-90 | 4 Cyl. 1.6 Eng..... | 55442 |

DODGE

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|------------------------------------|--------------|
| | COLT | |
| 90-89 | 4 Cyl. 1.6 Eng.; Canada Wagon..... | 55224 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|------------------------------------|--------------|
| | COLT | |
| 90-89 | 4 Cyl. 1.8 Eng.; Canada Wagon..... | 55224 |

EAGLE

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | 2000 GTX | |
| 93 | 4 Cyl. 2.0 Eng..... | 55221 |
| 92-91 | 4 Cyl. 2.0 Eng.; SOHC..... | 55215 |
| 92-91 | 4 Cyl. 2.0 Eng.; DOHC..... | 55221 |
| | MEDALLION | |
| 89-88 | 4 Cyl. 2.2 Eng..... | 55458 |
| | SUMMIT | |
| 96-94 | 4 Cyl. 1.5 Eng..... | 55209 |
| 93-92 | 4 Cyl. 1.5 Eng..... | 55209 |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55215 |
| 91 | 4 Cyl. 1.5 Eng..... | 55209 |
| 90-89 | 4 Cyl. 1.5 Eng..... | 55211 |
| 90-89 | 4 Cyl. 1.6 Eng..... | 55221 |
| | TALON | |
| 98-95 | 4 Cyl. 2.0 Eng.; w/o Turbo.... | 55207 |
| 98-95 | 4 Cyl. 2.0 Eng.; w/ Turbo.... | 55212 |
| 94-93 | 4 Cyl. 1.8 Eng..... | 55215 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | TALON | |
| 94-93 | 4 Cyl. 2.0 Eng..... | 55221 |
| 92-90 | 4 Cyl. 2.0 Eng..... | 55221 |
| | VISTA | |
| 92 | 4 Cyl. 1.5 Eng..... | 55209 |
| 92 | 4 Cyl. 2.0 Eng..... | 55203 |
| 91 | 4 Cyl. 1.5 Eng..... | 55203 |
| 91 | 4 Cyl. 2.0 Eng..... | 55203 |
| 90 | 4 Cyl. 1.5 Eng..... | 55203 |
| 90 | 4 Cyl. 1.6 Eng..... | 55211 |
| 90 | 4 Cyl. 2.0 Eng..... | 55203 |
| 89 | 4 Cyl. 2.0 Eng..... | 55203 |
| 88 | 4 Cyl. 1.5 Eng..... | 55211 |

FIAT

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|----------------------------|--------------|
| | 124 | |
| 83-79 | 4 Cyl. 2.0 Eng..... | 55436 |
| | 128 | |
| 79-76 | 4 Cyl. 1.3 Eng..... | 55439 |
| 75 | 4 Cyl. 1.3 Eng. Coupe..... | 55439 |
| 75 | 4 Cyl. 1.3 Eng. Sedan..... | 55111 |
| 75 | 4 Cyl. 1.3 Eng. Wagon..... | 55111 |
| 74 | 4 Cyl. 1.3 Eng..... | 55111 |
| | 131 | |
| 78-75 | 4 Cyl. 1.8 Eng..... | 55436 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | STRADA | |
| 82-79 | 4 Cyl. 1.5 Eng..... | 55439 |
| | X-1/9 | |
| 83-79 | 4 Cyl. 1.5 Eng..... | 55439 |
| 78-74 | 4 Cyl. 1.3 Eng..... | 55439 |

GEO

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|----------------------------|--------------|
| | METRO | |
| 97-92 | 4 Cyl. 1.3 Eng..... | 55109 |
| | PRIZM | |
| 97-93 | 4 Cyl. 1.6 Eng..... | 55910 |
| 97-93 | 4 Cyl. 1.8 Eng..... | 55910 |
| 92-90 | 4 Cyl. 1.6 Eng.; DOHC..... | 55951 |
| | STORM | |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55405 |
| 91-90 | 4 Cyl. 1.6 Eng.; DOHC..... | 55405 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------------------|--------------|
| | TRACKER | |
| 97-96 | 4 Cyl. 1.6 Eng..... | 55408 |
| 95-94 | 4 Cyl. 1.6 Eng.; MFI; 16 Valve | 55408 |
| 95-94 | 4 Cyl. 1.6 Eng.; TBI; 8 Valve.. | 55425 |
| 93-89 | 4 Cyl. 1.6 Eng..... | 55425 |

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|----------------------------------|----------------|
| | FIT | |
| 08-07 | 4 Cyl. 1.5 Eng..... | SPP111E |
| | PASSPORT | |
| 02-00 | 6 Cyl. 3.2 Eng.; Cyl. 6..... | SPP60 |
| 02-00 | 6 Cyl. 3.2 Eng.; Cyl. 1 to 5.... | SPP61 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | CIVIC DEL SOL | |
| 97-96 | 4 Cyl. 1.6 Eng.; VTEC..... | 55013 |
| 97-96 | 4 Cyl. 1.6 Eng.; Exc. VTEC.... | 55001 |
| 95-94 | 4 Cyl. 1.5 Eng..... | 55002 |
| 95-94 | 4 Cyl. 1.6 Eng.; VTEC..... | 55013 |
| 95-94 | 4 Cyl. 1.6 Eng.; Exc. VTEC.... | 55001 |
| 93 | 4 Cyl. 1.5 Eng..... | 55002 |
| 93 | 4 Cyl. 1.6 Eng..... | 55001 |
| | CR-V | |
| 01-97 | 4 Cyl. 2.0 Eng..... | 55004 |
| | CRX | |
| 91-88 | 4 Cyl. 1.5 Eng..... | 55016 |
| 91-88 | 4 Cyl. 1.6 Eng..... | 55016 |
| 87 | 4 Cyl. 1.5 Eng.; Carb..... | 55021 |
| 87 | 4 Cyl. 1.5 Eng.; FI..... | 55029 |
| 86-85 | 4 Cyl. 1.5 Eng.; Carb..... | 55021 |
| 86-85 | 4 Cyl. 1.5 Eng.; FI..... | 55030 |
| 84 | 4 Cyl. 1.3 Eng. Early..... | 55027 |
| 84 | 4 Cyl. 1.3 Eng. Late..... | 55024 |
| 84 | 4 Cyl. 1.5 Eng. Early..... | 55027 |
| 84 | 4 Cyl. 1.5 Eng. Late..... | 55024 |
| | ODYSSEY | |
| 98 | 4 Cyl. 2.3 Eng..... | 55000 |
| 97-95 | 4 Cyl. 2.2 Eng..... | 55010 |
| | PASSPORT | |
| 96 | 4 Cyl. 2.6 Eng..... | 55413 |
| 96 | 6 Cyl. 3.2 Eng. To 11/95..... | 55014 |
| 95-94 | 4 Cyl. 2.6 Eng..... | 55413 |
| 95-94 | 6 Cyl. 3.2 Eng..... | 55014 |
| | PRELUDE | |
| 01-97 | 4 Cyl. 2.2 Eng..... | 55009 |
| 96-93 | 4 Cyl. 2.2 Eng.; Exc. VTEC.... | 55011 |
| 96-93 | 4 Cyl. 2.2 Eng.; VTEC..... | 55009 |
| 96-93 | 4 Cyl. 2.3 Eng..... | 55003 |
| 92 | 4 Cyl. 2.2 Eng..... | 55011 |
| 92 | 4 Cyl. 2.3 Eng..... | 55003 |
| 91 | 4 Cyl. 2.0 Eng..... | 55015 |
| 91 | 4 Cyl. 2.1 Eng..... | 55015 |
| 90 | 4 Cyl. 2.0 Eng.; Carb..... | 55017 |
| 90 | 4 Cyl. 2.0 Eng.; FI..... | 55015 |
| 90 | 4 Cyl. 2.1 Eng..... | 55015 |
| 89-88 | 4 Cyl. 2.0 Eng.; Carb..... | 55017 |
| 89-88 | 4 Cyl. 2.0 Eng.; FI..... | 55015 |
| 87-85 | 4 Cyl. 1.8 Eng..... | 55007 |
| 87-85 | 4 Cyl. 2.0 Eng..... | 55022 |
| 84-83 | 4 Cyl. 1.8 Eng..... | 55007 |
| 82 | 4 Cyl. 1.8 Eng..... | 55024 |
| 81-79 | 4 Cyl. 1.8 Eng..... | 55028 |
| | WAGOVAN | |
| 87-86 | 4 Cyl. 1.5 Eng..... | 55021 |
| 84 | 4 Cyl. 1.5 Eng..... | 55021 |

Continued on Next Column

HYUNDAI

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-----------------|-------------------------------------|----------|
| ACCENT | | |
| 97 | 4 Cyl. 1.5 Eng.; DOHC To 12/96..... | SPP89 |
| 96-95 | 4 Cyl. 1.5 Eng.; DOHC..... | SPP89 |
| SANTA FE | | |
| 06-03 | 4 Cyl. 2.4 Eng..... | SPP63 |
| 06-03 | 6 Cyl. 3.5 Eng..... | SPP86 |
| 02-01 | 4 Cyl. 2.4 Eng..... | SPP63 |
| SONATA | | |
| 05-04 | 4 Cyl. 2.4 Eng..... | SPP63 |
| 03-99 | 4 Cyl. 2.4 Eng.; VIN:S..... | SPP63 |
| XG300 | | |
| 01 | 6 Cyl. 3.0 Eng..... | SPP86 |
| XG350 | | |
| 05-02 | 6 Cyl. 3.5 Eng..... | SPP86 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|---------------------------------|----------|
| PONY | | |
| 85-84 | 4 Cyl. 1.6 Eng..... | 55337 |
| 83 | 4 Cyl. 1.4 Eng..... | 55337 |
| SANTA FE | | |
| 06-03 | 4 Cyl. 2.4 Eng..... | 55802◊ |
| 06-03 | 6 Cyl. 2.7 Eng..... | 55803 |
| 06-03 | 6 Cyl. 3.5 Eng..... | 55813◎ |
| 02-01 | 4 Cyl. 2.4 Eng..... | 55802◊ |
| 02-01 | 6 Cyl. 2.7 Eng..... | 55803 |
| SCOUPE | | |
| 95-93 | 4 Cyl. 1.5 Eng.; w/ Turbo..... | 55800 |
| 95-93 | 4 Cyl. 1.5 Eng.; w/o Turbo..... | 55215 |
| 92-91 | 4 Cyl. 1.5 Eng..... | 55215 |
| SONATA | | |
| 05-02 | 4 Cyl. 2.4 Eng..... | 55802◊ |
| 05-02 | 6 Cyl. 2.7 Eng..... | 55803 |
| 01-99 | 4 Cyl. 2.4 Eng..... | 55802◊ |
| 01-99 | 6 Cyl. 2.5 Eng..... | 55803 |
| 98-92 | 4 Cyl. 2.0 Eng..... | 55221 |
| 98-92 | 6 Cyl. 3.0 Eng..... | 55814 |
| 91-90 | 4 Cyl. 2.4 Eng..... | 55215 |
| 91-90 | 6 Cyl. 3.0 Eng..... | 55213 |
| 89 | 4 Cyl. 2.4 Eng..... | 55215 |
| STELLAR | | |
| 88-87 | 4 Cyl. 2.0 Eng..... | 55211 |
| 86 | 4 Cyl. 1.5 Eng..... | 55337 |
| 85 | 4 Cyl. 1.6 Eng..... | 55337 |
| TIBURON | | |
| 08-03 | 4 Cyl. 2.0 Eng..... | 55801 |
| 08-03 | 6 Cyl. 2.7 Eng..... | 55803 |
| 01-98 | 4 Cyl. 2.0 Eng..... | 55801 |
| 97 | 4 Cyl. 1.8 Eng..... | 55801 |
| 97 | 4 Cyl. 2.0 Eng..... | 55801 |
| TUCSON | | |
| 09-05 | 4 Cyl. 2.0 Eng..... | 55801 |
| 09-05 | 6 Cyl. 2.7 Eng..... | 55807 |
| XG300 | | |
| 01 | 6 Cyl. 3.0 Eng..... | 55808★ |
| XG350 | | |
| 05-03 | 6 Cyl. 3.5 Eng..... | 55813◎ |
| 02 | 6 Cyl. 3.5 Eng..... | 55808★ |

Continued on Next Column

INFINITI

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------------|---------------------------------|----------|
| FX35 | | |
| 07 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 06-03 | 6 Cyl. 3.5 Eng..... | SPP50 |
| FX45 | | |
| 07-03 | 8 Cyl. 4.5 Eng..... | SPP51 |
| G35 | | |
| 07 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 06-03 | 6 Cyl. 3.5 Eng..... | SPP50 |
| I30 | | |
| 01-00 | 6 Cyl. 3.0 Eng.; Right Bank.... | SPP76 |
| J30 | | |
| 01-00 | 6 Cyl. 3.0 Eng.; Right Bank.... | SPP76 |

Continued on Next Column

COIL ON PLUG BOOT

| Year | Model | Part No. |
|------------|---|----------|
| I30 | | |
| 01-00 | 6 Cyl. 3.0 Eng.; Left Bank..... | SPP77 |
| 99-96 | 6 Cyl. 3.0 Eng.; VIN:C; Right Bank..... | SPP76 |
| 99-96 | 6 Cyl. 3.0 Eng.; VIN:C; Left Bank..... | SPP77 |
| I35 | | |
| 04-02 | 6 Cyl. 3.5 Eng..... | SPP51 |
| J30 | | |
| 97-95 | 6 Cyl. 3.0 Eng..... | SPP54 |

Continued on Next Page

◊ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

◎ Wire Set Contains 3 Leads, Requires 3 Coil On Plug Boots Sold Separately.

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | J30 | |
| 94 | 6 Cyl. 3.0 Eng. To 3/94..... | SPP53 |
| 94 | 6 Cyl. 3.0 Eng. From 3/94..... | SPP54 |
| 93 | 6 Cyl. 3.0 Eng..... | SPP53 |
| | M35 | |
| 06 | 6 Cyl. 3.5 Eng..... | SPP50 |
| | M45 | |
| 07 | 8 Cyl. 4.5 Eng..... | SPP51 |
| 06 | 8 Cyl. 4.5 Eng. From 2/05..... | SPP51 |
| 04-03 | 8 Cyl. 4.5 Eng..... | SPP51 |
| | Q45 | |
| 06-01 | 8 Cyl. 4.5 Eng..... | SPP51 |
| | QX4 | |
| 03-01 | 6 Cyl. 3.5 Eng..... | SPP51 |
| | QX56 | |
| 07-04 | 8 Cyl. 5.6 Eng..... | SPP51 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------------------|--------------|
| | G20 | |
| 02-01 | 4 Cyl. 2.0 Eng..... | 55339 |
| 00 | 4 Cyl. 2.0 Eng. To 11/99..... | 55338 |
| 00 | 4 Cyl. 2.0 Eng. From 12/99..... | 55339 |
| 99 | 4 Cyl. 2.0 Eng..... | 55338 |
| 96-95 | 4 Cyl. 2.0 Eng..... | 55338 |
| 94 | 4 Cyl. 2.0 Eng. To 1/94..... | 55305 |
| 94 | 4 Cyl. 2.0 Eng. From 2/94..... | 55338 |
| 93-91 | 4 Cyl. 2.0 Eng..... | 55305 |
| | M30 | |
| 92 | 6 Cyl. 3.0 Eng. To 12/91..... | 55327 |
| 91-90 | 6 Cyl. 3.0 Eng..... | 55327 |
| | QX4 | |
| 00-97 | 6 Cyl. 3.3 Eng..... | 55301 |

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|-----------------------------------|--------------|
| | AMIGO | |
| 00-98 | 6 Cyl. 3.2 Eng.; Cyl. 6..... | SPP60 |
| 00-98 | 6 Cyl. 3.2 Eng.; Cyl. 1 to 5..... | SPP61 |
| | AXIOM | |
| 04-02 | 6 Cyl. 3.5 Eng.; Cyl 6..... | SPP60 |
| 04-02 | 6 Cyl. 3.5 Eng.; Cyl. 1 to 5..... | SPP61 |
| | RODEO | |
| 04-00 | 6 Cyl. 3.2 Eng.; Cyl 6..... | SPP60 |
| 04-00 | 6 Cyl. 3.2 Eng.; Cyl. 1 to 5..... | SPP61 |
| | RODEO SPORT | |
| 03-01 | 6 Cyl. 3.2 Eng.; Cyl 6..... | SPP60 |
| 03-01 | 6 Cyl. 3.2 Eng.; Cyl. 1 to 5..... | SPP61 |
| | TROOPER | |
| 02-00 | 6 Cyl. 3.5 Eng.; Cyl 6..... | SPP60 |
| 02-00 | 6 Cyl. 3.5 Eng.; Cyl. 1 to 5..... | SPP61 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | AMIGO | |
| 00-98 | 4 Cyl. 2.2 Eng..... | 55404 |
| 94 | 4 Cyl. 2.6 Eng..... | 55413 |
| 93-91 | 4 Cyl. 2.3 Eng..... | 55413 |
| 93-91 | 4 Cyl. 2.6 Eng..... | 55413 |
| 90-89 | 4 Cyl. 2.3 Eng..... | 55410 |
| 90-89 | 4 Cyl. 2.6 Eng..... | 55410 |
| | I-MARK | |
| 89 | 4 Cyl. 1.6 Eng..... | 55405 |
| 85-81 | 4 Cyl. 1.8 Eng..... | 55434 |
| | IMPULSE | |
| 92 | 4 Cyl. 1.6 Eng..... | 55420 |
| 92 | 4 Cyl. 1.8 Eng..... | 55405 |
| 91 | 4 Cyl. 1.6 Eng.; w/ Turbo..... | 55420 |
| 91 | 4 Cyl. 1.6 Eng.; w/o Turbo.... | 55405 |
| 90 | 4 Cyl. 1.6 Eng..... | 55405 |
| 89-88 | 4 Cyl. 2.3 Eng..... | 55410 |
| 87-85 | 4 Cyl. 1.9 Eng..... | 55226 |
| 89-85 | 4 Cyl. 2.0 Eng..... | 55414 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | IMPULSE | |
| 84-83 | 4 Cyl. 1.9 Eng..... | 55226 |
| | OASIS | |
| 99-98 | 4 Cyl. 2.3 Eng..... | 55000 |
| 97-96 | 4 Cyl. 2.2 Eng..... | 55010 |
| | PICKUP | |
| 95 | 4 Cyl. 2.3 Eng..... | 55410 |
| 95 | 4 Cyl. 2.6 Eng..... | 55413 |
| 94-91 | 4 Cyl. 2.3 Eng..... | 55410 |
| 94-91 | 4 Cyl. 2.6 Eng..... | 55413 |
| 94-91 | 6 Cyl. 3.1 Eng..... | 55433 |
| 90-88 | 4 Cyl. 2.6 Eng..... | 55413 |
| 87-86 | 4 Cyl. 1.9 Eng..... | 55434 |
| 90-86 | 4 Cyl. 2.3 Eng..... | 55410 |
| 85-83 | 4 Cyl. 1.9 Eng..... | 55434 |
| 82-81 | 4 Cyl. 1.8 Eng..... | 55434 |
| | RODEO | |
| 03-98 | 4 Cyl. 2.2 Eng..... | 55404 |
| 97 | 4 Cyl. 2.6 Eng..... | 55413 |

Continued on Next Column

Continued on Next Page

ISUZU

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|--------------------|-------------------------------|--------------|
| RODEO | | |
| 96 | 4 Cyl. 2.6 Eng..... | 55413 |
| 96 | 6 Cyl. 3.2 Eng. To 11/95..... | 55014 |
| 95-93 | 4 Cyl. 2.6 Eng..... | 55413 |
| 95-93 | 6 Cyl. 3.2 Eng..... | 55014 |
| 92-91 | 4 Cyl. 2.6 Eng..... | 55413 |
| 92-91 | 6 Cyl. 3.1 Eng..... | 55433 |
| RODEO SPORT | | |
| 03-01 | 4 Cyl. 2.2 Eng..... | 55404 |
| STYLUS | | |
| 93-92 | 4 Cyl. 1.8 Eng..... | 55405 |
| 91 | 4 Cyl. 1.6 Eng.; DOHC..... | 55405 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|----------------------------|--------------|
| TROOPER | | |
| 95-92 | 6 Cyl. 3.2 Eng.; DOHC..... | 55406 |
| 95-92 | 6 Cyl. 3.2 Eng.; SOHC..... | 55412 |
| 91-89 | 4 Cyl. 2.6 Eng..... | 55413 |
| 91-89 | 6 Cyl. 2.8 Eng..... | 55433 |
| 88 | 4 Cyl. 2.6 Eng..... | 55413 |
| 87-86 | 4 Cyl. 2.3 Eng..... | 55410 |
| 85-84 | 4 Cyl. 1.9 Eng..... | 55434 |

JAGUAR

COIL ON PLUG BOOT

| Year | Model | Part No. |
|--------------------|-----------------------------|---------------|
| VANDEN PLAS | | |
| 03 | 8 Cyl. 4.0 Eng.; VIN:2..... | SPP109 |
| 03 | 8 Cyl. 4.0 Eng.; VIN:8..... | SPP109 |
| 02-00 | 8 Cyl. 4.0 Eng.; VIN:B..... | SPP109 |
| 02-00 | 8 Cyl. 4.0 Eng.; VIN:C..... | SPP109 |
| XJ6 | | |
| 97 | 6 Cyl. 4.0 Eng.; VIN:2..... | SPP108 |
| 96 | 6 Cyl. 4.0 Eng.; VIN:2..... | SPP108 |
| 96 | 6 Cyl. 4.0 Eng.; VIN:7..... | SPP108 |
| 95 | 6 Cyl. 4.0 Eng.; VIN:7..... | SPP108 |
| XJ8 | | |
| 03-00 | 8 Cyl. 4.0 Eng..... | SPP109 |
| XJR | | |
| 03-00 | 8 Cyl. 4.0 Eng..... | SPP109 |
| 97-95 | 6 Cyl. 4.0 Eng..... | SPP108 |
| XJS | | |
| 96-95 | 6 Cyl. 4.0 Eng..... | SPP108 |
| XK8 | | |
| 02-00 | 8 Cyl. 4.0 Eng..... | SPP109 |
| XKR | | |
| 02-00 | 8 Cyl. 4.0 Eng..... | SPP109 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------------|---------------------|--------------|
| 2.4 | | |
| 57-56 | 6 Cyl. 2.5 Eng..... | 55426 |
| 3.4 | | |
| 60-57 | 6 Cyl. 3.4 Eng..... | 55426 |
| 3.8 | | |
| 60 | 6 Cyl. 3.8 Eng..... | 55426 |
| C-TYPE | | |
| 53-51 | 6 Cyl. 3.4 Eng..... | 55426 |
| D-TYPE | | |
| 56-54 | 6 Cyl. 3.4 Eng..... | 55426 |
| MARK IX | | |
| 60-59 | 6 Cyl. 3.8 Eng..... | 55426 |
| MARK V | | |
| 50-49 | 6 Cyl. 2.7 Eng..... | 55426 |
| 50-49 | 6 Cyl. 3.5 Eng..... | 55426 |
| MARK VII | | |
| 57-51 | 6 Cyl. 3.4 Eng..... | 55426 |
| MARK VIII | | |
| 58-57 | 6 Cyl. 3.4 Eng..... | 55426 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|--------------------|----------------------|--------------|
| MARK X | | |
| 66 | 6 Cyl. 4.2 Eng..... | 55426 |
| VANDEN PLAS | | |
| 94-90 | 6 Cyl. 4.0 Eng..... | 55421 |
| 89-88 | 6 Cyl. 3.6 Eng..... | 55421 |
| 87-82 | 6 Cyl. 4.2 Eng..... | 55426 |
| XJ | | |
| 71-69 | 6 Cyl. 4.2 Eng..... | 55447 |
| XJ12 | | |
| 96-95 | 12 Cyl. 6.0 Eng..... | 55416 |
| 94 | 12 Cyl. 6.0 Eng..... | 55417 |
| 92 | 12 Cyl. 5.3 Eng..... | 55417 |
| 91-89 | 12 Cyl. 5.3 Eng..... | 55415 |
| 88-81 | 12 Cyl. 5.3 Eng..... | 55454 |
| 79-73 | 12 Cyl. 5.3 Eng..... | 55454 |
| XJ6 | | |
| 94-90 | 6 Cyl. 4.0 Eng..... | 55421 |
| 89-88 | 6 Cyl. 3.6 Eng..... | 55421 |
| 87 | 6 Cyl. 3.6 Eng..... | 55421 |
| 87 | 6 Cyl. 4.2 Eng..... | 55426 |

Continued on Next Page

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|--------------|
| | XJ6 | |
| 86-80 | 6 Cyl. 4.2 Eng..... | 55426 |
| 79-70 | 6 Cyl. 4.2 Eng..... | 55447 |
| | XJRS | |
| 93 | 12 Cyl. 6.0 Eng..... | 55417 |
| | XJS | |
| 95 | 12 Cyl. 6.0 Eng..... | 55417 |
| 94 | 12 Cyl. 6.0 Eng..... | 55417 |
| 94 | 6 Cyl. 4.0 Eng..... | 55421 |
| 93 | 6 Cyl. 4.0 Eng..... | 55421 |
| 92 | 12 Cyl. 5.3 Eng..... | 55417 |
| 92 | 6 Cyl. 4.0 Eng..... | 55421 |
| 91-89 | 12 Cyl. 5.3 Eng.; Lucas Distributor..... | 55454 |
| 91-89 | 12 Cyl. 5.3 Eng.; Marelli Distributor..... | 55415 |
| 88-76 | 12 Cyl. 5.3 Eng..... | 55454 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|----------------------|--------------|
| | XK120 | |
| 54-49 | 6 Cyl. 3.4 Eng..... | 55426 |
| | XK140 | |
| 57-55 | 6 Cyl. 3.4 Eng..... | 55426 |
| | XK150 | |
| 61-58 | 6 Cyl. 3.4 Eng..... | 55426 |
| 61-58 | 6 Cyl. 3.8 Eng..... | 55426 |
| | XKE | |
| 74-72 | 12 Cyl. 5.3 Eng..... | 55454 |
| 71 | 12 Cyl. 5.3 Eng..... | 55454 |
| 71 | 6 Cyl. 4.2 Eng..... | 55447 |
| 70 | 6 Cyl. 4.2 Eng..... | 55447 |
| | XKSS | |
| 57 | 6 Cyl. 3.4 Eng..... | 55426 |

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|--------------------------------|--------------|
| | AMANTI | |
| 06-04 | 6 Cyl. 3.5 Eng..... | SPP86 |
| | MAGENTIS | |
| 06 | 4 Cyl. 2.4 Eng. Early Design.. | SPP63 |
| 05-01 | 4 Cyl. 2.4 Eng..... | SPP63 |
| | OPTIMA | |
| 06 | 4 Cyl. 2.4 Eng. Early Design.. | SPP63 |
| 05-01 | 4 Cyl. 2.4 Eng..... | SPP63 |
| | SEDONA | |
| 05-02 | 6 Cyl. 3.5 Eng..... | SPP86 |
| | SEPHIA | |
| 01-98 | 4 Cyl. 1.8 Eng..... | SPP89 |
| | SPECTRA / SPECTRA5 | |
| 04-00 | 4 Cyl. 1.8 Eng..... | SPP89 |
| | SPORTAGE | |
| 02-96 | 4 Cyl. 2.0 Eng..... | SPP95 |
| 95 | 4 Cyl. 2.0 Eng.; VIN:3; DOHC | SPP95 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|----------------------------|----------------|
| | OPTIMA | |
| 05-02 | 6 Cyl. 2.7 Eng..... | 55803 |
| 01 | 4 Cyl. 2.4 Eng..... | 55802 ❖ |
| 01 | 6 Cyl. 2.5 Eng..... | 55803 |
| | RIO / RIO5 | |
| 05-03 | 4 Cyl. 1.6 Eng..... | 55810 |
| 02-01 | 4 Cyl. 1.5 Eng..... | 55810 |
| | SEDONA | |
| 05-02 | 6 Cyl. 3.5 Eng..... | 55808 ★ |
| | SEPHIA | |
| 01-98 | 4 Cyl. 1.8 Eng..... | 55806 ❖ |
| 97-95 | 4 Cyl. 1.6 Eng.; SOHC..... | 55110 |
| 97-95 | 4 Cyl. 1.6 Eng.; DOHC..... | 55812 |
| 97-95 | 4 Cyl. 1.8 Eng..... | 55812 |
| 94 | 4 Cyl. 1.6 Eng..... | 55110 |
| | SORENTO | |
| 06-03 | 6 Cyl. 3.5 Eng..... | 55809 ★ |
| | SOUL | |
| 10 | 4 Cyl. 2.0 Eng..... | 55801 |
| | SPECTRA / SPECTRA5 | |
| 09-05 | 4 Cyl. 2.0 Eng..... | 55801 |
| 04 | 4 Cyl. 1.8 Eng..... | 55806 ❖ |
| 04 | 4 Cyl. 2.0 Eng..... | 55801 |
| 03-00 | 4 Cyl. 1.8 Eng..... | 55806 ❖ |
| | SPORTAGE | |
| 10-05 | 4 Cyl. 2.0 Eng..... | 55801 |
| 10-05 | 6 Cyl. 2.7 Eng..... | 55807 |
| 02-98 | 4 Cyl. 2.0 Eng..... | 55805 ❖ |
| 97-95 | 4 Cyl. 2.0 Eng.; SOHC..... | 55811 |
| 97-95 | 4 Cyl. 2.0 Eng.; DOHC..... | 55805 ❖ |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|----------------|
| | AMANTI | |
| 06-04 | 6 Cyl. 3.5 Eng..... | 55813 ◎ |
| | MAGENTIS | |
| 06 | 4 Cyl. 2.4 Eng. To 9/05..... | 55802 ❖ |
| 06 | 6 Cyl. 2.7 Eng.; w/o Direct Ignition System..... | 55803 |
| 05-02 | 4 Cyl. 2.4 Eng..... | 55802 ❖ |
| 05-02 | 6 Cyl. 2.7 Eng..... | 55803 |
| 01 | 4 Cyl. 2.4 Eng..... | 55802 ❖ |
| 01 | 6 Cyl. 2.5 Eng..... | 55803 |
| | OPTIMA | |
| 06 | 4 Cyl. 2.4 Eng. To 9/05..... | 55802 ❖ |
| 06 | 6 Cyl. 2.7 Eng.; w/o Direct Ignition System..... | 55803 |
| 05-02 | 4 Cyl. 2.4 Eng..... | 55802 ❖ |

Continued on Next Column

❖ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

◎ Wire Set Contains 3 Leads, Requires 3 Coil On Plug Boots Sold Separately.

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

LADA

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|----------|
| 83 | NIVA | 55111 |
| 82-80 | 4 Cyl. 1600 CC..... 4 Cyl. 1600 CC..... | 55111 |

LAND ROVER

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|-----------------------------------|----------|
| 05-02 | FREELANDER 6 Cyl. 2.5 Eng..... | SPP72 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|----------|
| | DEFENDER 110 | |
| 93 | 8 Cyl. 3.9 Eng..... | 55428 |
| | DEFENDER 90 | |
| 97 | 8 Cyl. 4.0 Eng..... | 55456 |
| 95-94 | 8 Cyl. 3.9 Eng..... | 55428 |
| | DISCOVERY | |
| 04-03 | 8 Cyl. 4.6 Eng..... | 55409 |
| 02-00 | 8 Cyl. 4.0 Eng..... | 55409 |
| 99 | 8 Cyl. 4.0 Eng. Series II..... | 55409 |
| 99 | 8 Cyl. 4.0 Eng.; Distributorless Ignition..... | 55456 |
| 98-96 | 8 Cyl. 4.0 Eng..... | 55456 |
| 95-94 | 8 Cyl. 3.9 Eng..... | 55423 |
| | FREELANDER | |
| 05-02 | 6 Cyl. 2.5 Eng..... | 55441★ |
| | LAND ROVER | |
| 74-70 | 4 Cyl. 2.3 Eng.; w/ Push-On Distributor Cap..... | 55438 |
| 69-67 | 4 Cyl. 2.3 Eng.; w/ Push-On Distributor Cap..... | 55438 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | LAND ROVER | |
| 69-67 | 6 Cyl. 2.6 Eng..... | 55427 |
| | LR3 | |
| 08-05 | 6 Cyl. 4.0 Eng..... | 55401 |
| | RANGE ROVER | |
| 02-01 | 8 Cyl. 4.6 Eng..... | 55409 |
| 00-99 | 8 Cyl. 4.0 Eng..... | 55409 |
| 00-99 | 8 Cyl. 4.6 Eng..... | 55409 |
| 98-96 | 8 Cyl. 4.0 Eng..... | 55456 |
| 98-96 | 8 Cyl. 4.6 Eng..... | 55456 |
| 95 | 8 Cyl. 3.9 Eng..... | 55423 |
| 95 | 8 Cyl. 4.2 Eng..... | 55423 |
| 94-93 | 8 Cyl. 3.9 Eng..... | 55428 |
| 94-93 | 8 Cyl. 4.2 Eng..... | 55428 |
| 92-89 | 8 Cyl. 3.9 Eng..... | 55428 |
| 88-87 | 8 Cyl. 3.5 Eng..... | 55428 |

LEXUS

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|--|----------|
| | ES300 | |
| 01-99 | 6 Cyl. 3.0 Eng.; w/o VVT, w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 01-99 | 6 Cyl. 3.0 Eng.; w/o VVT, w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| 98-96 | 6 Cyl. 3.0 Eng.; w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 98-96 | 6 Cyl. 3.0 Eng.; w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| 95-94 | 6 Cyl. 3.0 Eng..... | SPP83 |
| | GS300 | |
| 05-98 | 6 Cyl. 3.0 Eng..... | SPP49 |
| | IS300 | |
| 05-01 | 6 Cyl. 3.0 Eng..... | SPP49 |
| | SC300 | |
| 00-99 | 6 Cyl. 3.0 Eng..... | SPP49 |
| 98 | 6 Cyl. 3.0 Eng.; VIN:D..... | SPP49 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|-------------------------------|----------|
| | ES250 | |
| 91-90 | 6 Cyl. 2.5 Eng..... | 55936 |
| | ES300 | |
| 01-99 | 6 Cyl. 3.0 Eng.; w/o VVT..... | 55917★ |
| 98-96 | 6 Cyl. 3.0 Eng..... | 55917★ |
| 93-92 | 6 Cyl. 3.0 Eng..... | 55928 |
| | GS300 | |
| 05-98 | 6 Cyl. 3.0 Eng..... | 55924★ |
| 97-93 | 6 Cyl. 3.0 Eng..... | 55942 |
| | IS300 | |
| 05-01 | 6 Cyl. 3.0 Eng..... | 55924★ |
| | LS400 | |
| 98-95 | 8 Cyl. 4.0 Eng..... | 55958 |
| 94-90 | 8 Cyl. 4.0 Eng..... | 55934 |
| | LX450 | |
| 97-96 | 6 Cyl. 4.5 Eng..... | 55922 |
| | SC300 | |
| 00-99 | 6 Cyl. 3.0 Eng..... | 55924★ |
| 98-92 | 6 Cyl. 3.0 Eng..... | 55942 |
| | SC400 | |
| 98-95 | 8 Cyl. 4.0 Eng..... | 55958 |
| 94-92 | 8 Cyl. 4.0 Eng..... | 55934 |

* Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|---------------------|----------------|
| | CX-7 | |
| 07 | 4 Cyl. 2.3 Eng..... | SPP106 |
| | MAZDA 3 | |
| 07-06 | 4 Cyl. 2.0 Eng..... | SPP106 |
| 07-06 | 4 Cyl. 2.3 Eng..... | SPP106 |
| 05-04 | 4 Cyl. 2.0 Eng..... | SPP88 |
| 05-04 | 4 Cyl. 2.3 Eng..... | SPP88 |
| | MAZDA 5 | |
| 07-06 | 4 Cyl. 2.3 Eng..... | SPP122E |
| | MAZDA 6 | |
| 08 | 6 Cyl. 3.0 Eng..... | SPP114E |
| 07 | 4 Cyl. 2.3 Eng..... | SPP106 |
| 07 | 6 Cyl. 3.0 Eng..... | SPP114E |
| 06-03 | 6 Cyl. 3.0 Eng..... | SPP114E |
| | MX-5 / MIATA | |
| 07 | 4 Cyl. 2.0 Eng..... | SPP106 |
| 05-01 | 4 Cyl. 1.8 Eng..... | SPP52 |
| | MILLENNIA | |
| 02-95 | 6 Cyl. 2.3 Eng..... | SPP48 |
| | MPV | |
| 06-02 | 6 Cyl. 3.0 Eng..... | SPP114E |
| | PROTEGE | |
| 03-01 | 4 Cyl. 1.6 Eng..... | SPP42 |
| 03-01 | 4 Cyl. 2.0 Eng..... | SPP48 |
| 00-99 | 4 Cyl. 1.6 Eng..... | SPP42 |
| | PROTEGE5 | |
| 03-02 | 4 Cyl. 2.0 Eng..... | SPP48 |
| | TRIBUTE | |
| 08-05 | 4 Cyl. 2.3 Eng..... | SPP88 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------------------|---------------|
| | 808 | |
| 74-72 | 4 Cyl. 1.6 Eng..... | 55111 |
| | 929 | |
| 95-92 | 6 Cyl. 3.0 Eng..... | 55124 |
| 91-90 | 6 Cyl. 3.0 Eng.; SOHC..... | 55118 |
| 91-90 | 6 Cyl. 3.0 Eng.; DOHC..... | 55121 |
| 89-88 | 6 Cyl. 3.0 Eng..... | 55118 |
| | B1 SERIES PICKUP | |
| 78-77 | 4 Cyl. 1.8 Eng. B1800..... | 55111 |
| 76 | 4 Cyl. 1.6 Eng. B1600..... | 55111 |
| 73-72 | 4 Cyl. 1.6 Eng. B1600..... | 55111 |
| | B2 SERIES PICKUP | |
| 93-90 | 4 Cyl. 2.2 Eng. B2200..... | 55107 |
| 93-90 | 4 Cyl. 2.6 Eng. B2600..... | 55104 |
| 89-88 | 4 Cyl. 2.2 Eng. B2200..... | 55107 |
| 89-88 | 4 Cyl. 2.6 Eng. B2600..... | 55130 |
| 87 | 4 Cyl. 2.0 Eng. B2000..... | 55107 |
| 87 | 4 Cyl. 2.2 Eng. B2200..... | 55107 |
| 87 | 4 Cyl. 2.6 Eng. B2600..... | 55130 |
| 86 | 4 Cyl. 2.0 Eng. B2000..... | 55107 |
| 84-79 | 4 Cyl. 2.0 Eng. B2000..... | 55111 |
| | B3 SERIES PICKUP | |
| 97-95 | 6 Cyl. 3.0 Eng. B3000..... | 55113 |
| | COSMO | |
| 78-76 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55132 |
| | GLC | |
| 85-81 | 4 Cyl. 1.5 Eng..... | 55410 |
| 80-79 | 4 Cyl. 1.4 Eng..... | 55410 |
| 78-77 | 4 Cyl. 1.3 Eng..... | 55410 |
| | MAZDA 6 | |
| 05 | 4 Cyl. 2.3 Eng.; Canada, Fed. | 55112 |
| 04-03 | 4 Cyl. 2.3 Eng..... | 55112 |
| | MX-5 / MIATA | |
| 05-01 | 4 Cyl. 1.8 Eng..... | 55125♦ |
| 00-99 | 4 Cyl. 1.8 Eng..... | 55108 |
| 97-94 | 4 Cyl. 1.8 Eng..... | 55108 |
| 93-90 | 4 Cyl. 1.6 Eng..... | 55108 |
| | MILLENNIA | |
| 02-95 | 6 Cyl. 2.5 Eng..... | 55105 |
| | MIZER | |
| 77-76 | 4 Cyl. 1.3 Eng..... | 55410 |
| | MPV | |
| 98-96 | 6 Cyl. 3.0 Eng..... | 55103 |
| 95 | 6 Cyl. 3.0 Eng..... | 55118 |
| 94-89 | 4 Cyl. 2.6 Eng..... | 55104 |
| 94-89 | 6 Cyl. 3.0 Eng..... | 55118 |
| | MX-3 | |
| 96-94 | 4 Cyl. 1.6 Eng..... | 55116 |
| 96-94 | 6 Cyl. 1.8 Eng..... | 55133 |
| 93-92 | 6 Cyl. 1.8 Eng..... | 55131 |
| | MX-6 | |
| 97-96 | 4 Cyl. 2.0 Eng.; w/ A.T..... | 55114 |
| 97-96 | 4 Cyl. 2.0 Eng.; w/ M.T..... | 55127 |
| 97-96 | 6 Cyl. 2.5 Eng..... | 55105 |
| 95 | 4 Cyl. 2.0 Eng.; w/ A.T..... | 55114 |
| 95 | 4 Cyl. 2.0 Eng.; w/ M.T..... | 55127 |
| 95 | 6 Cyl. 2.5 Eng..... | 55123 |
| 94-93 | 4 Cyl. 2.0 Eng..... | 55114 |
| 94-93 | 6 Cyl. 2.5 Eng..... | 55123 |
| 87 | 4 Cyl. 2.0 Eng..... | 55920 |
| 86-79 | 4 Cyl. 2.0 Eng..... | 55111 |
| | PROTEGE | |
| 03-01 | 4 Cyl. 1.6 Eng..... | 55915♦ |
| 03-01 | 4 Cyl. 2.0 Eng..... | 55101♦ |
| 00-99 | 4 Cyl. 1.6 Eng..... | 55915♦ |

Continued on Next Column

Continued on Next Page

♦ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

MAZDA

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------------|---------------------------------|----------------|
| PROTEGE | | |
| 00-99 | 4 Cyl. 1.8 Eng..... | 55102 |
| 98-96 | 4 Cyl. 1.5 Eng..... | 55106 |
| 98-96 | 4 Cyl. 1.8 Eng..... | 55116 |
| 95 | 4 Cyl. 1.5 Eng..... | 55106 |
| 95 | 4 Cyl. 1.6 Eng..... | 55110 |
| 95 | 4 Cyl. 1.8 Eng..... | 55116 |
| 94-90 | 4 Cyl. 1.8 Eng.; DOHC..... | 55129 |
| 94-90 | 4 Cyl. 1.8 Eng.; SOHC..... | 55110 |
| PROTEGE5 | | |
| 03-02 | 4 Cyl. 2.0 Eng..... | 55101 ♦ |
| R100 | | |
| 72-71 | 2 Cyl. 1.1 Eng.; Rotary Eng.... | 55132 |
| ROTARY PICKUP | | |
| 77-74 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55132 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------|---------------------------------|--------------|
| RX-2 | | |
| 74-71 | 2 Cyl. 1.1 Eng.; Rotary Eng.... | 55132 |
| RX-3 | | |
| 78-72 | 2 Cyl. 1.1 Eng.; Rotary Eng.... | 55132 |
| RX-4 | | |
| 78-74 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55132 |
| RX-7 | | |
| 95-93 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55122 |
| 91-86 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55119 |
| 85-84 | 2 Cyl. 1.1 Eng.; Rotary Eng.... | 55126 |
| 85-84 | 2 Cyl. 1.3 Eng.; Rotary Eng.... | 55126 |
| 83-79 | 2 Cyl. 1.1 Eng.; Rotary Eng.... | 55126 |

MERCEDES-BENZ

COIL ON PLUG BOOT

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| 300CE | | |
| 93 | 6 Cyl. 3.2 Eng..... | SPP74 |
| 300E | | |
| 93 | 6 Cyl. 2.8 Eng..... | SPP74 |
| 93 | 6 Cyl. 3.2 Eng..... | SPP74 |
| 300SE | | |
| 93 | 6 Cyl. 3.2 Eng..... | SPP74 |
| 300TE | | |
| 93 | 6 Cyl. 3.2 Eng..... | SPP74 |
| C230 | | |
| 07-06 | 6 Cyl. 2.5 Eng..... | SPP97 |
| 05-03 | 4 Cyl. 1.8 Eng..... | SPP94 |
| 00-97 | 4 Cyl. 2.3 Eng..... | SPP74 |
| C280 | | |
| 07-06 | 6 Cyl. 3.0 Eng..... | SPP97 |
| 96-94 | 6 Cyl. 2.8 Eng..... | SPP74 |
| C350 | | |
| 10-06 | 6 Cyl. 3.5 Eng..... | SPP97 |
| C36 | | |
| 96-95 | 6 Cyl. 3.6 Eng..... | SPP74 |
| CL500 | | |
| 06-98 | 8 Cyl. 5.0 Eng..... | SPP97 |
| CL550 | | |
| 10-07 | 8 Cyl. 5.5 Eng..... | SPP97 |
| CLK350 | | |
| 07-06 | 6 Cyl. 3.5 Eng..... | SPP97 |
| CLS500 | | |
| 06 | 8 Cyl. 5.0 Eng..... | SPP97 |
| CLS550 | | |
| 10-07 | 8 Cyl. 5.5 Eng..... | SPP97 |
| E300 | | |
| 09-08 | 6 Cyl. 3.0 Eng..... | SPP97 |
| E320 | | |
| 97-94 | 6 Cyl. 3.2 Eng..... | SPP74 |
| E350 | | |
| 10-06 | 6 Cyl. 3.5 Eng..... | SPP97 |
| E420 | | |
| 97 | 8 Cyl. 4.2 Eng..... | SPP82 |
| GL450 | | |
| 10-07 | 8 Cyl. 4.6 Eng..... | SPP97 |
| GL550 | | |
| 10-08 | 8 Cyl. 5.5 Eng..... | SPP97 |

Continued on Next Column

COIL ON PLUG BOOT

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| GLK350 | | |
| 10 | 6 Cyl. 3.5 Eng..... | SPP97 |
| ML350 | | |
| 10-06 | 6 Cyl. 3.5 Eng..... | SPP97 |
| ML500 | | |
| 07 | 8 Cyl. 5.0 Eng..... | SPP97 |
| ML550 | | |
| 10-08 | 8 Cyl. 5.5 Eng..... | SPP97 |
| R350 | | |
| 10-06 | 6 Cyl. 3.5 Eng..... | SPP97 |
| S320 | | |
| 99-94 | 6 Cyl. 3.2 Eng..... | SPP74 |
| S400 | | |
| 10 | 6 Cyl. 3.5 Eng..... | SPP97 |
| S420 | | |
| 99-97 | 8 Cyl. 4.2 Eng..... | SPP82 |
| S450 | | |
| 09 | 8 Cyl. 4.6 Eng..... | SPP97 |
| S500 | | |
| 06 | 8 Cyl. 5.0 Eng..... | SPP97 |
| S550 | | |
| 10-07 | 8 Cyl. 5.5 Eng..... | SPP97 |
| SL320 | | |
| 97-94 | 6 Cyl. 3.2 Eng..... | SPP74 |
| SL500 | | |
| 06 | 8 Cyl. 5.0 Eng..... | SPP97 |
| 99-96 | 8 Cyl. 5.0 Eng..... | SPP74 |
| SL550 | | |
| 09-07 | 8 Cyl. 5.5 Eng..... | SPP97 |
| SLK230 | | |
| 04-01 | 4 Cyl. 2.3 Eng..... | SPP81 |
| 00-98 | 4 Cyl. 2.3 Eng..... | SPP74 |
| SLK350 | | |
| 10-05 | 6 Cyl. 3.5 Eng..... | SPP97 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------|---------------------|--------------|
| 180 | | |
| 63-60 | 4 Cyl. 1.9 Eng..... | 55111 |
| 180A | | |
| 59-56 | 4 Cyl. 1.9 Eng..... | 55111 |

Continued on Next Page

♦ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|--------------|
| | 180B | |
| 62-60 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 180C | |
| 63 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 190 | |
| 65-64 | 4 Cyl. 1.9 Eng..... | 55111 |
| 59-56 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 190B | |
| 62-60 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 190C | |
| 65-63 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 190E | |
| 93-91 | 4 Cyl. 2.3 Eng..... | 55767 |
| 93-91 | 6 Cyl. 2.6 Eng..... | 55772 |
| 90-89 | 6 Cyl. 2.6 Eng..... | 55772 |
| 88 | 4 Cyl. 2.3 Eng..... | 55767 |
| 88 | 6 Cyl. 2.6 Eng..... | 55772 |
| 87 | 4 Cyl. 2.3 Eng.; DOHC..... | 55760 |
| 87 | 4 Cyl. 2.3 Eng.; SOHC..... | 55767 |
| 87 | 6 Cyl. 2.6 Eng..... | 55772 |
| 86 | 4 Cyl. 2.3 Eng.; DOHC..... | 55760 |
| 86 | 4 Cyl. 2.3 Eng.; SOHC..... | 55767 |
| 85-84 | 4 Cyl. 2.3 Eng..... | 55767 |
| | 190SL | |
| 63-55 | 4 Cyl. 1.9 Eng..... | 55111 |
| | 200 | |
| 68-66 | 4 Cyl. 2.0 Eng..... | 55111 |
| | 220 | |
| 73-68 | 4 Cyl. 2.2 Eng..... | 55111 |
| | 230 | |
| 78-74 | 4 Cyl. 2.3 Eng..... | 55111 |
| | 260E | |
| 89-87 | 6 Cyl. 2.6 Eng..... | 55772 |
| | 280 | |
| 76-73 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 76-73 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |
| | 280C | |
| 76-73 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 76-73 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |
| | 280CE | |
| 81-78 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 81-78 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |
| | 280E | |
| 81-77 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 81-77 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |
| | 280S | |
| 76-75 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 76-75 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |
| | 280SE | |
| 80-77 | 6 Cyl. 2.8 Eng.; w/ Push-On Distributor Cap..... | 55774 |
| 80-77 | 6 Cyl. 2.8 Eng.; w/ Screw-On Cap..... | 55777 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|---------------|
| | 280SE | |
| 73-72 | 8 Cyl. 4.5 Eng..... | 55775 |
| 70 | 8 Cyl. 3.5 Eng..... | 55775 |
| | 280SEL | |
| 73-72 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 300CE | |
| 93 | 6 Cyl. 3.0 Eng.; Exc. AWD.... | 55778 |
| 93 | 6 Cyl. 3.0 Eng.; AWD..... | 55772 |
| 93 | 6 Cyl. 3.2 Eng.; w/ Direct Ignition System..... | 55766★ |
| 93 | 6 Cyl. 3.2 Eng.; w/o Direct Ignition System..... | 55778 |
| 92 | 6 Cyl. 3.0 Eng.; DOHC..... | 55778 |
| 91-90 | 6 Cyl. 3.0 Eng.; SOHC..... | 55772 |
| 91-90 | 6 Cyl. 3.0 Eng.; DOHC..... | 55778 |
| 89-88 | 6 Cyl. 3.0 Eng..... | 55772 |
| | 300E | |
| 93 | 6 Cyl. 2.8 Eng..... | 55766★ |
| 93 | 6 Cyl. 3.0 Eng..... | 55772 |
| 93 | 6 Cyl. 3.2 Eng.; w/ Direct Ignition System..... | 55766★ |
| 93 | 6 Cyl. 3.2 Eng.; w/o Direct Ignition System..... | 55778 |
| 92-90 | 6 Cyl. 2.6 Eng..... | 55772 |
| 92-90 | 6 Cyl. 3.0 Eng..... | 55772 |
| 89-86 | 6 Cyl. 3.0 Eng..... | 55772 |
| | 300SE | |
| 93 | 6 Cyl. 3.2 Eng.; w/ Direct Ignition System..... | 55766★ |
| 93 | 6 Cyl. 3.2 Eng.; w/o Direct Ignition System..... | 55778 |
| 92 | 6 Cyl. 3.2 Eng..... | 55772 |
| 91-88 | 6 Cyl. 3.0 Eng..... | 55772 |
| | 300SEL | |
| 91-88 | 6 Cyl. 3.0 Eng..... | 55772 |
| 73-72 | 8 Cyl. 4.5 Eng..... | 55775 |
| 71-70 | 8 Cyl. 3.5 Eng..... | 55775 |
| | 300SL | |
| 93-90 | 6 Cyl. 3.0 Eng..... | 55778 |
| | 300TE | |
| 93 | 6 Cyl. 3.0 Eng..... | 55772 |
| 93 | 6 Cyl. 3.2 Eng.; w/ Direct Ignition System..... | 55766★ |
| 93 | 6 Cyl. 3.2 Eng.; w/o Direct Ignition System..... | 55778 |
| 92-88 | 6 Cyl. 3.0 Eng..... | 55772 |
| | 350SL | |
| 72 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 380SE | |
| 85-84 | 8 Cyl. 3.8 Eng..... | 55771 |
| | 380SEC | |
| 83-82 | 8 Cyl. 3.8 Eng..... | 55771 |
| | 380SEL | |
| 83-81 | 8 Cyl. 3.8 Eng..... | 55771 |
| | 380SL | |
| 85-81 | 8 Cyl. 3.8 Eng..... | 55771 |
| | 380SLC | |
| 81 | 8 Cyl. 3.8 Eng..... | 55771 |
| | 400E | |
| 93-92 | 8 Cyl. 4.2 Eng..... | 55762 |
| | 400SE | |
| 92 | 8 Cyl. 4.2 Eng..... | 55762 |

Continued on Next Page

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

MERCEDES-BENZ

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|---------------|
| | 400SEL | |
| 93 | 8 Cyl. 4.2 Eng..... | 55762 |
| | 420SEL | |
| 91-86 | 8 Cyl. 4.2 Eng..... | 55769 |
| | 450SE | |
| 76-74 | 8 Cyl. 4.5 Eng..... | 55771 |
| 73 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 450SEL | |
| 80 | 8 Cyl. 4.5 Eng..... | 55771 |
| 79-77 | 8 Cyl. 4.5 Eng..... | 55771 |
| 79-77 | 8 Cyl. 6.8 Eng..... | 55771 |
| 76-74 | 8 Cyl. 4.5 Eng..... | 55771 |
| 73 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 450SL | |
| 80-74 | 8 Cyl. 4.5 Eng..... | 55771 |
| 73 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 450SLC | |
| 80-74 | 8 Cyl. 4.5 Eng..... | 55771 |
| 73 | 8 Cyl. 4.5 Eng..... | 55775 |
| | 500E | |
| 93-92 | 8 Cyl. 5.0 Eng..... | 55762 |
| | 500SEC | |
| 93 | 8 Cyl. 5.0 Eng..... | 55762 |
| 85-84 | 8 Cyl. 5.0 Eng..... | 55771 |
| | 500SEL | |
| 93-92 | 8 Cyl. 5.0 Eng..... | 55762 |
| 85-84 | 8 Cyl. 5.0 Eng..... | 55771 |
| | 500SL | |
| 93-90 | 8 Cyl. 5.0 Eng..... | 55773 |
| | 560SEC | |
| 91-86 | 8 Cyl. 5.6 Eng..... | 55769 |
| | 560SEL | |
| 91-86 | 8 Cyl. 5.6 Eng..... | 55769 |
| | 560SL | |
| 89-86 | 8 Cyl. 5.6 Eng..... | 55769 |
| | 600SEC | |
| 93 | 12 Cyl. 6.0 Eng..... | 55776 |
| | 600SEL | |
| 93-92 | 12 Cyl. 6.0 Eng..... | 55776 |
| | 600SL | |
| 93 | 12 Cyl. 6.0 Eng..... | 55776 |
| | B200 | |
| 10-06 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55764 |
| | C220 | |
| 96-94 | 4 Cyl. 2.2 Eng..... | 55770 |
| | C230 | |
| 00-97 | 4 Cyl. 2.3 Eng..... | 55763♦ |
| | C240 | |
| 05-01 | 6 Cyl. 2.6 Eng..... | 55761 |
| | C280 | |
| 00-99 | 6 Cyl. 2.8 Eng..... | 55761 |
| 98-97 | 6 Cyl. 2.8 Eng..... | 55765★ |
| 96 | 6 Cyl. 2.8 Eng. From Engine No. 011794..... | 55765★ |
| 96 | 6 Cyl. 2.8 Eng. To Engine No. 011793..... | 55766★ |
| 95-94 | 6 Cyl. 2.8 Eng..... | 55766★ |
| | C32 AMG | |
| 04-02 | 6 Cyl. 3.2 Eng..... | 55761 |
| | C320 | |
| 05-01 | 6 Cyl. 3.2 Eng..... | 55761 |
| | C36 AMG | |
| 97 | 6 Cyl. 3.6 Eng..... | 55765★ |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|---------------|
| | C36 AMG | |
| 96 | 6 Cyl. 3.6 Eng. To Engine No. 011793..... | 55766★ |
| 96 | 6 Cyl. 3.6 Eng. From Engine No. 011794..... | 55765★ |
| 95 | 6 Cyl. 3.6 Eng..... | 55766★ |
| | C43 AMG | |
| 00-98 | 8 Cyl. 4.3 Eng..... | 55768 |
| | C55 AMG | |
| 06-05 | 8 Cyl. 5.5 Eng..... | 55768 |
| | CL500 | |
| 06-98 | 8 Cyl. 5.0 Eng..... | 55768 |
| | CL55 AMG | |
| 06-01 | 8 Cyl. 5.5 Eng..... | 55768 |
| | CLK320 | |
| 05-98 | 6 Cyl. 3.2 Eng..... | 55761 |
| | CLK430 | |
| 03-99 | 8 Cyl. 4.3 Eng..... | 55768 |
| | CLK500 | |
| 06-03 | 8 Cyl. 5.0 Eng..... | 55768 |
| | CLK55 AMG | |
| 06-01 | 8 Cyl. 5.5 Eng..... | 55768 |
| | CLS500 | |
| 06 | 8 Cyl. 5.0 Eng..... | 55768 |
| | CLS55 AMG | |
| 06 | 8 Cyl. 5.5 Eng..... | 55768 |
| | E320 | |
| 05-98 | 6 Cyl. 3.2 Eng..... | 55761 |
| 97-96 | 6 Cyl. 3.2 Eng..... | 55765★ |
| 95-94 | 6 Cyl. 3.2 Eng..... | 55766★ |
| | E420 | |
| 95-94 | 8 Cyl. 4.2 Eng..... | 55762 |
| | E430 | |
| 02-98 | 8 Cyl. 4.3 Eng..... | 55768 |
| | E500 | |
| 06-03 | 8 Cyl. 5.0 Eng..... | 55768 |
| 94 | 8 Cyl. 5.0 Eng..... | 55762 |
| | E55 AMG | |
| 06-99 | 8 Cyl. 5.5 Eng..... | 55768 |
| | G500 | |
| 05-02 | 8 Cyl. 5.0 Eng..... | 55768 |
| | G55 AMG | |
| 10-03 | 8 Cyl. 5.5 Eng..... | 55768 |
| | ML320 | |
| 03-98 | 6 Cyl. 3.2 Eng..... | 55761 |
| | ML350 | |
| 05-03 | 6 Cyl. 3.7 Eng..... | 55761 |
| | ML430 | |
| 01-99 | 8 Cyl. 4.3 Eng..... | 55768 |
| | ML500 | |
| 07-02 | 8 Cyl. 5.0 Eng..... | 55768 |
| | ML55 AMG | |
| 03-00 | 8 Cyl. 5.5 Eng..... | 55768 |
| | R500 | |
| 07-06 | 8 Cyl. 5.0 Eng..... | 55768 |
| | S320 | |
| 99-97 | 6 Cyl. 3.2 Eng..... | 55765★ |
| 96 | 6 Cyl. 3.2 Eng. To Engine No. 016468..... | 55766★ |
| 96 | 6 Cyl. 3.2 Eng. From Engine No. 016469..... | 55765★ |
| 95-94 | 6 Cyl. 3.2 Eng..... | 55766★ |

Continued on Next Page

♦ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|---------------|
| | S420 | |
| 96-94 | 8 Cyl. 4.2 Eng..... | 55762 |
| | S430 | |
| 06-00 | 8 Cyl. 4.3 Eng..... | 55768 |
| | S500 | |
| 06-99 | 8 Cyl. 5.0 Eng..... | 55768 |
| 95-94 | 8 Cyl. 5.0 Eng..... | 55762 |
| | S55 AMG | |
| 06-01 | 8 Cyl. 5.5 Eng..... | 55768 |
| | S600 | |
| 99-94 | 12 Cyl. 6.0 Eng..... | 55776 |
| | SL320 | |
| 97 | 6 Cyl. 3.2 Eng..... | 55765★ |
| 96 | 6 Cyl. 3.2 Eng. To Engine No. 005248..... | 55766★ |
| 96 | 6 Cyl. 3.2 Eng. From Engine No. 005249..... | 55765★ |
| 95-94 | 6 Cyl. 3.2 Eng..... | 55766★ |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|----------------------|---------------|
| | SL500 | |
| 05-99 | 8 Cyl. 5.0 Eng..... | 55768 |
| 95-94 | 8 Cyl. 5.0 Eng..... | 55762 |
| | SL55 AMG | |
| 08-03 | 8 Cyl. 5.5 Eng..... | 55768 |
| | SL600 | |
| 02-94 | 12 Cyl. 6.0 Eng..... | 55776 |
| | SLK230 | |
| 00-98 | 4 Cyl. 2.3 Eng..... | 55763♦ |
| | SLK32 AMG | |
| 04-02 | 6 Cyl. 3.2 Eng..... | 55761 |
| | SLK320 | |
| 04-01 | 6 Cyl. 3.2 Eng..... | 55761 |
| | SLK55 AMG | |
| 10-05 | 8 Cyl. 5.5 Eng..... | 55768 |

MG
SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | 1100 | |
| 67-63 | 4 Cyl. 1.1 Eng..... | 55437 |
| | 1300 | |
| 69-68 | 4 Cyl. 1.3 Eng..... | 55437 |
| | MAGNETTE | |
| 61-59 | 4 Cyl. 1.5 Eng..... | 55437 |
| | MGA | |
| 62-60 | 4 Cyl. 1.6 Eng..... | 55437 |
| 59 | 4 Cyl. 1.5 Eng..... | 55437 |
| 59 | 4 Cyl. 1.6 Eng..... | 55437 |
| 58-56 | 4 Cyl. 1.5 Eng..... | 55437 |
| | MGB | |
| 81-63 | 4 Cyl. 1.8 Eng..... | 55429 |
| | MIDGET | |
| 79-75 | 4 Cyl. 1.5 Eng..... | 55437 |
| 74-67 | 4 Cyl. 1.3 Eng..... | 55437 |
| 66-63 | 4 Cyl. 1.1 Eng..... | 55437 |
| 62 | 4 Cyl. 1.0 Eng..... | 55437 |
| | TC | |
| 49-45 | 4 Cyl. 1.3 Eng..... | 55437 |
| | TD | |
| 53-50 | 4 Cyl. 1.3 Eng..... | 55437 |
| | TDC | |
| 53-51 | 4 Cyl. 1.3 Eng..... | 55437 |
| | TF | |
| 55 | 4 Cyl. 1.5 Eng..... | 55437 |
| 54 | 4 Cyl. 1.3 Eng..... | 55437 |
| | YA | |
| 50-47 | 4 Cyl. 1.3 Eng..... | 55437 |
| | YB | |
| 53-51 | 4 Cyl. 1.3 Eng..... | 55437 |
| | YT | |
| 50-47 | 4 Cyl. 1.3 Eng..... | 55437 |
| | ZA | |
| 56-54 | 4 Cyl. 1.5 Eng..... | 55437 |
| | ZB | |
| 58-57 | 4 Cyl. 1.5 Eng..... | 55437 |

♦ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

MINI**SPARK PLUG WIRE SET**

| Year | Model | Part No. |
|---------------|--|----------|
| COOPER | | |
| 08-07 | 4 Cyl. 1.6 Eng.; w/o Direct Ignition System..... | 55422 |
| 06-02 | 4 Cyl. 1.6 Eng..... | 55422 |

MITSUBISHI**COIL ON PLUG BOOT**

| Year | Model | Part No. |
|------------------|---|----------|
| ECLIPSE | | |
| 05-00 | 4 Cyl. 2.4 Eng..... | SPP55 |
| ENDEAVOR | | |
| 07-04 | 6 Cyl. 3.8 Eng..... | SPP105 |
| GALANT | | |
| 07-05 | 6 Cyl. 3.8 Eng..... | SPP105 |
| 04 | 4 Cyl. 2.4 Eng..... | SPP55 |
| 04 | 6 Cyl. 3.8 Eng..... | SPP105 |
| 03-99 | 4 Cyl. 2.4 Eng..... | SPP55 |
| 98 | 4 Cyl. 2.4 Eng. From 2/98..... | SPP55 |
| LANCER | | |
| 06 | 4 Cyl. 2.0 Eng.; w/ Turbo From 8/05..... | SPP104 |
| 06 | 4 Cyl. 2.0 Eng.; w/ Turbo To 7/05..... | SPP73 |
| 06 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | SPP55 |
| 05-03 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | SPP55 |
| 05-03 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | SPP73 |
| 02 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | SPP55 |
| MIRAGE | | |
| 02-97 | 4 Cyl. 1.8 Eng..... | SPP55 |
| MONTERO | | |
| 06-03 | 6 Cyl. 3.8 Eng..... | SPP110 |
| OUTLANDER | | |
| 05-04 | 4 Cyl. 2.4 Eng.; Exc. MIVEC Engine..... | SPP55 |
| 03 | 4 Cyl. 2.4 Eng..... | SPP55 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|---------------------------------|----------|
| 3000GT | | |
| 99-97 | 6 Cyl. 3.0 Eng.; DOHC..... | 55117 |
| 99-97 | 6 Cyl. 3.0 Eng.; SOHC..... | 55223 |
| 96-91 | 6 Cyl. 3.0 Eng..... | 55117 |
| CORDIA | | |
| 88-86 | 4 Cyl. 1.8 Eng..... | 55211 |
| 88-86 | 4 Cyl. 2.0 Eng..... | 55216 |
| 85-84 | 4 Cyl. 1.8 Eng..... | 55211 |
| 85-84 | 4 Cyl. 2.0 Eng..... | 55226 |
| 83 | 4 Cyl. 1.8 Eng..... | 55226 |
| DIAMANTE | | |
| 04-97 | 6 Cyl. 3.5 Eng..... | 55202 |
| 96-92 | 6 Cyl. 3.0 Eng.; DOHC..... | 55117 |
| 96-92 | 6 Cyl. 3.0 Eng.; SOHC..... | 55223 |
| ECLIPSE | | |
| 05-00 | 4 Cyl. 2.4 Eng..... | 55200◊ |
| 05-00 | 6 Cyl. 3.0 Eng..... | 55208 |
| 99-96 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | 55212 |
| 99-96 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55207 |
| 99-96 | 4 Cyl. 2.4 Eng..... | 55205 |
| 95 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | 55212 |
| 95 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55207 |
| 94-90 | 4 Cyl. 1.8 Eng..... | 55215 |
| 94-90 | 4 Cyl. 2.0 Eng..... | 55221 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------------|---|----------|
| EXPO | | |
| 92 | 4 Cyl. 2.4 Eng..... | 55215 |
| GALANT | | |
| 04 | 4 Cyl. 2.4 Eng..... | 55200◊ |
| 03-99 | 4 Cyl. 2.4 Eng..... | 55200◊ |
| 03-99 | 6 Cyl. 3.0 Eng..... | 55208 |
| 98 | 4 Cyl. 2.4 Eng. To 2/98..... | 55206 |
| 98 | 4 Cyl. 2.4 Eng. From 2/98..... | 55200◊ |
| 97-95 | 4 Cyl. 2.4 Eng..... | 55206 |
| 94 | 4 Cyl. 2.4 Eng.; DOHC..... | 55212 |
| 94 | 4 Cyl. 2.4 Eng.; SOHC..... | 55206 |
| 93 | 4 Cyl. 2.0 Eng.; DOHC..... | 55221 |
| 93 | 4 Cyl. 2.0 Eng.; SOHC..... | 55206 |
| 92-89 | 4 Cyl. 2.0 Eng.; DOHC..... | 55221 |
| 92-89 | 4 Cyl. 2.0 Eng.; SOHC..... | 55215 |
| 87-85 | 4 Cyl. 2.4 Eng..... | 55211 |
| LANCER | | |
| 06 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55200◊ |
| 06 | 4 Cyl. 2.0 Eng.; w/ Turbo To 7/05..... | 55218◊ |
| 06 | 4 Cyl. 2.0 Eng.; w/ Turbo From 8/05..... | 55222◊ |
| 05-03 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55200◊ |
| 05-03 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | 55218◊ |
| 02 | 4 Cyl. 2.0 Eng..... | 55200◊ |
| MIGHTY MAX | | |
| 96-95 | 4 Cyl. 2.4 Eng..... | 55215 |
| 94-90 | 4 Cyl. 2.4 Eng..... | 55215 |
| 94-90 | 6 Cyl. 3.0 Eng..... | 55204 |
| 89-88 | 4 Cyl. 2.0 Eng..... | 55203 |
| 89-88 | 4 Cyl. 2.6 Eng..... | 55211 |
| 87 | 4 Cyl. 2.0 Eng..... | 55203 |
| 87 | 4 Cyl. 2.6 Eng..... | 55203 |
| 86-85 | 4 Cyl. 2.0 Eng..... | 55226 |
| 86-85 | 4 Cyl. 2.6 Eng..... | 55226 |
| 84-83 | 4 Cyl. 2.0 Eng..... | 55225 |
| 84-83 | 4 Cyl. 2.6 Eng..... | 55225 |
| MIRAGE | | |
| 02-97 | 4 Cyl. 1.5 Eng..... | 55209 |
| 02-97 | 4 Cyl. 1.8 Eng..... | 55200◊ |
| 96-93 | 4 Cyl. 1.5 Eng..... | 55209 |
| 92-91 | 4 Cyl. 1.5 Eng..... | 55209 |
| 92-91 | 4 Cyl. 1.6 Eng..... | 55221 |
| 90 | 4 Cyl. 1.5 Eng..... | 55211 |
| 89 | 4 Cyl. 1.5 Eng..... | 55211 |
| 89 | 4 Cyl. 1.6 Eng..... | 55221 |
| 88-87 | 4 Cyl. 1.5 Eng..... | 55211 |
| 88-87 | 4 Cyl. 1.6 Eng..... | 55211 |
| 86-85 | 4 Cyl. 1.5 Eng..... | 55216 |
| 86-85 | 4 Cyl. 1.6 Eng..... | 55211 |
| MONTERO | | |
| 06-03 | 6 Cyl. 3.8 Eng..... | 55220▲ |
| 02-97 | 6 Cyl. 3.5 Eng..... | 55201 |
| 96-95 | 6 Cyl. 3.0 Eng..... | 55210 |

Continued on Next Column

Continued on Next Page

◊ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition. ▲ Wire Set Contains 3 Leads.

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------------|---------------------|----------------|
| MONTERO | | |
| 96-95 | 6 Cyl. 3.5 Eng..... | 55219 ▲ |
| 94 | 6 Cyl. 3.0 Eng..... | 55204 |
| 94 | 6 Cyl. 3.5 Eng..... | 55219 ▲ |
| 93-90 | 6 Cyl. 3.0 Eng..... | 55204 |
| 89 | 4 Cyl. 2.6 Eng..... | 55211 |
| 89 | 6 Cyl. 3.0 Eng..... | 55204 |
| 88-86 | 4 Cyl. 2.6 Eng..... | 55211 |
| 85-83 | 4 Cyl. 2.6 Eng..... | 55226 |
| MONTERO SPORT | | |
| 04 | 6 Cyl. 3.5 Eng..... | 55201 |
| 03-00 | 6 Cyl. 3.0 Eng..... | 55201 |
| 03-00 | 6 Cyl. 3.5 Eng..... | 55201 |
| 99 | 4 Cyl. 2.4 Eng..... | 55214 |
| 99 | 6 Cyl. 3.0 Eng..... | 55201 |
| 99 | 6 Cyl. 3.5 Eng..... | 55201 |
| 98-97 | 4 Cyl. 2.4 Eng..... | 55214 |
| 98-97 | 6 Cyl. 3.0 Eng..... | 55201 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------------|--|----------------|
| OUTLANDER | | |
| 05-03 | 4 Cyl. 2.4 Eng.; w/o Direct Ignition System..... | 55200 ❖ |
| PRECIS | | |
| 94-90 | 4 Cyl. 1.5 Eng..... | 55215 |
| 89-87 | 4 Cyl. 1.5 Eng..... | 55225 |
| SIGMA | | |
| 90-88 | 6 Cyl. 3.0 Eng..... | 55213 |
| STARION | | |
| 89-88 | 4 Cyl. 2.6 Eng..... | 55203 |
| 87-83 | 4 Cyl. 2.6 Eng..... | 55226 |
| TREDIA | | |
| 88-86 | 4 Cyl. 1.8 Eng..... | 55211 |
| 88-86 | 4 Cyl. 2.0 Eng..... | 55216 |
| 85-84 | 4 Cyl. 1.8 Eng..... | 55211 |
| 85-84 | 4 Cyl. 2.0 Eng..... | 55226 |
| 83 | 4 Cyl. 1.8 Eng..... | 55226 |
| VAN | | |
| 90-87 | 4 Cyl. 2.4 Eng..... | 55215 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|--------------|---------------------|--------------|
| MINOR | | |
| 65 | 4 Cyl. 0.9 Eng..... | 55437 |
| 65 | 4 Cyl. 1.0 Eng..... | 55437 |
| 65 | 4 Cyl. 1.1 Eng..... | 55437 |
| 65 | 4 Cyl. 1.3 Eng..... | 55437 |
| 64-63 | 4 Cyl. 0.9 Eng..... | 55437 |
| 64-63 | 4 Cyl. 1.0 Eng..... | 55437 |
| 64-63 | 4 Cyl. 1.1 Eng..... | 55437 |
| 62-60 | 4 Cyl. 0.9 Eng..... | 55437 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| MINOR | | |
| 62-60 | 4 Cyl. 1.0 Eng..... | 55437 |
| 59-58 | 4 Cyl. 1.0 Eng..... | 55437 |
| OXFORD | | |
| 62-60 | 4 Cyl. 1.5 Eng..... | 55437 |

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-----------------|----------------------------------|--------------|
| 300ZX | | |
| 96-95 | 6 Cyl. 3.0 Eng..... | SPP54 |
| 94 | 6 Cyl. 3.0 Eng. To 3/94..... | SPP53 |
| 94 | 6 Cyl. 3.0 Eng. From 3/94..... | SPP54 |
| 93-90 | 6 Cyl. 3.0 Eng..... | SPP53 |
| 350Z | | |
| 09-07 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 06-03 | 6 Cyl. 3.5 Eng..... | SPP50 |
| ALTIMA | | |
| 07-02 | 4 Cyl. 2.5 Eng..... | SPP62 |
| 07-02 | 6 Cyl. 3.5 Eng..... | SPP51 |
| ARMADA | | |
| 06-05 | 8 Cyl. 5.6 Eng..... | SPP51 |
| FRONTIER | | |
| 09-05 | 4 Cyl. 2.5 Eng..... | SPP62 |
| 09-05 | 6 Cyl. 4.0 Eng..... | SPP51 |
| MAXIMA | | |
| 06-02 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 01-00 | 6 Cyl. 3.0 Eng.; Right Bank..... | SPP76 |
| 01-00 | 6 Cyl. 3.0 Eng.; Left Bank..... | SPP78 |
| 99 | 6 Cyl. 3.0 Eng.; Right Bank.... | SPP76 |

Continued on Next Column

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------------------|---|---------------|
| MAXIMA | | |
| 99 | 6 Cyl. 3.0 Eng.; Left Bank To 3/99..... | SPP77 |
| 99 | 6 Cyl. 3.0 Eng.; Left Bank From 3/99..... | SPP78 |
| 98-95 | 6 Cyl. 3.0 Eng.; Right Bank.... | SPP76 |
| 98-95 | 6 Cyl. 3.0 Eng.; Left Bank..... | SPP77 |
| 94-92 | 6 Cyl. 3.0 Eng.; VIN:E; Left Bank..... | SPP98 |
| 94-92 | 6 Cyl. 3.0 Eng.; VIN:E; Right Bank..... | SPP100 |
| MURANO | | |
| 09 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 07-03 | 6 Cyl. 3.5 Eng..... | SPP51 |
| PATHFINDER | | |
| 07-05 | 6 Cyl. 4.0 Eng..... | SPP51 |
| 04 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 04 | 8 Cyl. 5.6 Eng..... | SPP51 |
| 03-02 | 6 Cyl. 3.5 Eng..... | SPP51 |
| 01 | 6 Cyl. 3.5 Eng.; Cyl. 2 to 6.... | SPP84 |
| 01 | 6 Cyl. 3.5 Eng.; Cyl. 1..... | SPP85 |

Continued on Next Page

❖ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition. ▲ Wire Set Contains 3 Leads.

NISSAN

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|------------------------------|--------------|
| | PULSAR NX | |
| 89-88 | 4 Cyl. 1.8 Eng..... | SPP99 |
| 87 | 4 Cyl. 1.6 Eng.; CA16DE Eng. | SPP99 |
| | QUEST | |
| 07-04 | 6 Cyl. 3.5 Eng..... | SPP51 |
| | SENTRA | |
| 07 | 4 Cyl. 2.5 Eng..... | SPP62 |
| 06-02 | 4 Cyl. 1.8 Eng..... | SPP96 |
| 06-02 | 4 Cyl. 2.5 Eng..... | SPP62 |
| | TITAN | |
| 07-04 | 8 Cyl. 5.6 Eng..... | SPP51 |
| | XTERRA | |
| 09-05 | 6 Cyl. 4.0 Eng..... | SPP51 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|--------------|
| | 410 | |
| 65-63 | 4 Cyl. 1.2 Eng..... | 55459 |
| | 411 | |
| 67 | 4 Cyl. 1.6 Eng..... | 55459 |
| 65 | 4 Cyl. 1.2 Eng..... | 55459 |
| | 510 | |
| 81 | 4 Cyl. 2.0 Eng..... | 55328 |
| 80 | 4 Cyl. 2.0 Eng.; Calif. | 55328 |
| 79-78 | 4 Cyl. 2.0 Eng..... | 55335 |
| 73-68 | 4 Cyl. 1.6 Eng..... | 55335 |
| | 520 PICKUP | |
| 68-65 | 4 Cyl. 1.3 Eng..... | 55459 |
| | 521 PICKUP | |
| 72-70 | 4 Cyl. 1.6 Eng..... | 55335 |
| 69 | 4 Cyl. 1.3 Eng..... | 55459 |
| | 610 | |
| 76-74 | 4 Cyl. 2.0 Eng..... | 55335 |
| 73 | 4 Cyl. 1.8 Eng..... | 55335 |
| | 620 PICKUP | |
| 79-75 | 4 Cyl. 2.0 Eng..... | 55335 |
| 74 | 4 Cyl. 1.8 Eng..... | 55335 |
| 73-72 | 4 Cyl. 1.6 Eng..... | 55335 |
| | 710 | |
| 77-75 | 4 Cyl. 2.0 Eng..... | 55335 |
| 74 | 4 Cyl. 1.8 Eng..... | 55335 |
| | 720 PICKUP | |
| 86 | 4 Cyl. 2.0 Eng..... | 55314 |
| 86 | 4 Cyl. 2.4 Eng..... | 55314 |
| 85 | 4 Cyl. 2.0 Eng..... | 55329 |
| 85 | 4 Cyl. 2.4 Eng..... | 55329 |
| 84 | 4 Cyl. 2.0 Eng..... | 55328 |
| 84 | 4 Cyl. 2.4 Eng..... | 55328 |
| 83 | 4 Cyl. 2.0 Eng..... | 55328 |
| 83 | 4 Cyl. 2.2 Eng..... | 55328 |
| 83 | 4 Cyl. 2.4 Eng..... | 55328 |
| 82-81 | 4 Cyl. 2.2 Eng..... | 55328 |
| 80 | 4 Cyl. 2.0 Eng..... | 55335 |
| | 810 | |
| 81-77 | 6 Cyl. 2.4 Eng..... | 55326 |
| | ALTIMA | |
| 01-97 | 4 Cyl. 2.4 Eng..... | 55303 |
| 96-93 | 4 Cyl. 2.4 Eng..... | 55317 |
| | AXXESS | |
| 95-90 | 4 Cyl. 2.4 Eng..... | 55310 |
| | B210 | |
| 78-75 | 4 Cyl. 1.4 Eng..... | 55459 |
| 74 | 4 Cyl. 1.3 Eng..... | 55459 |
| | D21 PICKUP | |
| 93-90 | 4 Cyl. 2.4 Eng..... | 55310 |
| 93-90 | 6 Cyl. 3.0 Eng..... | 55312 |
| 89-86 | 4 Cyl. 2.4 Eng..... | 55314 |
| | F10 | |
| 78-76 | 4 Cyl. 1.4 Eng..... | 55453 |
| | FRONTIER | |
| 04-02 | 4 Cyl. 2.4 Eng..... | 55306 |
| 04-02 | 6 Cyl. 3.3 Eng.; w/o Supercharger..... | 55301 |
| 04-02 | 6 Cyl. 3.3 Eng.; w/ Supercharger..... | 55323 |
| 01 | 4 Cyl. 2.4 Eng..... | 55304 |
| 01 | 6 Cyl. 3.3 Eng.; w/o Supercharger..... | 55301 |

Continued on Next Column

Continued on Next Page

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------------|---|--------------|
| FRONTIER | | |
| 01 | 6 Cyl. 3.3 Eng.; w/ Supercharger..... | 55323 |
| 00-99 | 4 Cyl. 2.4 Eng..... | 55304 |
| 00-99 | 6 Cyl. 3.3 Eng..... | 55301 |
| 98 | 4 Cyl. 2.4 Eng..... | 55304 |
| MAXIMA | | |
| 94 | 6 Cyl. 3.0 Eng.; w/o Direct Ignition System To 2/94..... | 55316 |
| 93-92 | 6 Cyl. 3.0 Eng.; w/o Direct Ignition System..... | 55316 |
| 91-89 | 6 Cyl. 3.0 Eng..... | 55316 |
| 88-85 | 6 Cyl. 3.0 Eng..... | 55313 |
| 84-81 | 6 Cyl. 2.4 Eng..... | 55326 |
| MICRA | | |
| 91-84 | 4 Cyl. 1.2 Eng..... | 55319 |
| MULTI | | |
| 88-86 | 4 Cyl. 2.0 Eng..... | 55324 |
| PATHFINDER | | |
| 00-96 | 6 Cyl. 3.3 Eng..... | 55301 |
| 95-90 | 6 Cyl. 3.0 Eng..... | 55312 |
| 88-87 | 4 Cyl. 2.4 Eng..... | 55314 |
| PICKUP | | |
| 97 | 4 Cyl. 2.4 Eng..... | 55311 |
| 96 | 4 Cyl. 2.4 Eng. From 1/96..... | 55311 |
| 96 | 4 Cyl. 2.4 Eng. To 12/95..... | 55310 |
| 96 | 6 Cyl. 3.0 Eng. To 1/96..... | 55312 |
| 95-94 | 4 Cyl. 2.4 Eng..... | 55310 |
| 95-94 | 6 Cyl. 3.0 Eng..... | 55312 |
| PULSAR NX | | |
| 93-91 | 4 Cyl. 1.6 Eng..... | 55302 |
| 93-91 | 4 Cyl. 2.0 Eng..... | 55305 |
| 90-89 | 4 Cyl. 1.6 Eng..... | 55321 |
| 88-85 | 4 Cyl. 1.6 Eng..... | 55319 |
| 84-83 | 4 Cyl. 1.5 Eng..... | 55319 |
| 84-83 | 4 Cyl. 1.6 Eng..... | 55319 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------|---|--------------|
| QUEST | | |
| 02-99 | 6 Cyl. 3.3 Eng..... | 55318 |
| 98-93 | 6 Cyl. 3.0 Eng..... | 55300 |
| SENTRA | | |
| 01-00 | 4 Cyl. 2.0 Eng..... | 55339 |
| 99-98 | 4 Cyl. 1.6 Eng..... | 55302 |
| 99-98 | 4 Cyl. 2.0 Eng..... | 55338 |
| 97-95 | 4 Cyl. 1.6 Eng..... | 55302 |
| 94 | 4 Cyl. 1.6 Eng..... | 55302 |
| 94 | 4 Cyl. 2.0 Eng..... | 55338 |
| 93-91 | 4 Cyl. 1.6 Eng..... | 55302 |
| 93-91 | 4 Cyl. 2.0 Eng..... | 55305 |
| 90-89 | 4 Cyl. 1.6 Eng..... | 55321 |
| 88-84 | 4 Cyl. 1.6 Eng..... | 55319 |
| 83 | 4 Cyl. 1.5 Eng..... | 55319 |
| 83 | 4 Cyl. 1.6 Eng..... | 55319 |
| 82 | 4 Cyl. 1.5 Eng..... | 55319 |
| STANZA | | |
| 92-90 | 4 Cyl. 2.4 Eng..... | 55322 |
| 89-86 | 4 Cyl. 2.0 Eng. Wagon..... | 55324 |
| 89-86 | 4 Cyl. 2.0 Eng. Sedan..... | 55325 |
| 85 | 4 Cyl. 2.0 Eng..... | 55324 |
| 84-82 | 4 Cyl. 2.0 Eng..... | 55332 |
| VAN | | |
| 88-87 | 4 Cyl. 2.4 Eng..... | 55314 |
| XTERRA | | |
| 04-02 | 4 Cyl. 2.4 Eng..... | 55306 |
| 04-02 | 6 Cyl. 3.3 Eng.; w/o Supercharger..... | 55301 |
| 04-02 | 6 Cyl. 3.3 Eng.; w/ Supercharger..... | 55323 |
| 01-00 | 4 Cyl. 2.4 Eng..... | 55304 |
| 01-00 | 6 Cyl. 3.3 Eng..... | 55301 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| 1900 | | |
| 75-71 | 4 Cyl. 1.9 Eng..... | 55111 |
| ISUZU | | |
| 79-76 | 4 Cyl. 1.8 Eng..... | 55434 |
| KADETT | | |
| 72-69 | 4 Cyl. 1.1 Eng..... | 55111 |
| 68 | 4 Cyl. 1.1 Eng..... | 55111 |
| 68 | 4 Cyl. 1.5 Eng..... | 55111 |
| 68 | 4 Cyl. 1.9 Eng..... | 55111 |
| 67 | 4 Cyl. 1.1 Eng..... | 55111 |
| MANTA | | |
| 75-71 | 4 Cyl. 1.9 Eng..... | 55111 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| OPEL | | |
| 73-71 | 4 Cyl. 1.9 Eng..... | 55111 |
| 70-69 | 4 Cyl. 1.1 Eng..... | 55111 |
| 70-69 | 4 Cyl. 1.9 Eng..... | 55111 |
| RALLYE | | |
| 70 | 4 Cyl. 1.9 Eng..... | 55111 |
| 69 | 4 Cyl. 1.1 Eng..... | 55111 |
| 69 | 4 Cyl. 1.9 Eng..... | 55111 |

PEUGEOT

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------------------|--------------|
| 70 | 4 Cyl. 1.6 Eng..... | 404 55431 |
| | | 405 |
| 91-89 | 4 Cyl. 1.9 Eng.; SOHC..... | 55451 |
| 91-89 | 4 Cyl. 1.9 Eng.; DOHC..... | 55424 |
| | | 505 |
| 91 | 4 Cyl. 2.2 Eng.; w/ Turbo..... | 55458 |
| 91 | 4 Cyl. 2.2 Eng.; w/o Turbo..... | 55431 |
| 90-88 | 4 Cyl. 2.2 Eng.; w/ Turbo..... | 55458 |
| 90-88 | 4 Cyl. 2.2 Eng.; w/o Turbo..... | 55431 |
| 90-88 | 6 Cyl. 2.8 Eng..... | 55554 |
| 87 | 4 Cyl. 2.0 Eng..... | 55431 |
| 87 | 4 Cyl. 2.2 Eng.; w/ Turbo..... | 55458 |
| 87 | 4 Cyl. 2.2 Eng.; w/o Turbo..... | 55431 |
| 87 | 6 Cyl. 2.8 Eng..... | 55554 |
| 86-85 | 4 Cyl. 2.0 Eng..... | 55431 |
| 86-85 | 4 Cyl. 2.2 Eng..... | 55458 |
| 84-80 | 4 Cyl. 2.0 Eng..... | 55431 |
| | | 604 |
| 80-79 | 6 Cyl. 2.8 Eng..... | 55557 |

PLYMOUTH

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------|---|----------|
| | COLT | |
| 90 | 4 Cyl. 1.6 Eng.; w/ Turbo; Canada Wagon..... | 55224 |
| 90 | 4 Cyl. 1.8 Eng..... | 55224 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------|---------------------------------------|----------|
| | COLT | |
| 89 | 4 Cyl. 1.6 Eng.; Canada Wagon..... | 55224 |
| 89 | 4 Cyl. 1.8 Eng..... | 55224 |

Continued on Next Column

PORSCHE

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|---------------------|----------|
| | 911 SERIES | |
| 08 | 6 Cyl. 3.6 Eng..... | SPP70 |
| 08 | 6 Cyl. 3.8 Eng..... | SPP70 |
| 08 | 6 Cyl. 3.8 Eng..... | SPP70 |
| 07-05 | 6 Cyl. 3.6 Eng..... | SPP70 |
| 07-05 | 6 Cyl. 3.8 Eng..... | SPP70 |
| 04-02 | 6 Cyl. 3.6 Eng..... | SPP70 |
| 01 | 6 Cyl. 3.4 Eng..... | SPP71 |
| 01 | 6 Cyl. 3.6 Eng..... | SPP70 |
| 00-99 | 6 Cyl. 3.4 Eng..... | SPP71 |
| | BOXSTER | |
| 06-00 | 6 Cyl. 2.7 Eng..... | SPP71 |
| 06-00 | 6 Cyl. 3.2 Eng..... | SPP71 |
| 99-97 | 6 Cyl. 2.5 Eng..... | SPP71 |
| | CAYENNE | |
| 06-03 | 8 Cyl. 4.5 Eng..... | SPP112E |
| | CAYMAN | |
| 06 | 6 Cyl. 3.4 Eng..... | SPP71 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|----------|
| | 911 SERIES | |
| 97-95 | 6 Cyl. 3.6 Eng.; Dual Plug Engine..... | 55642 |
| 97-95 | 6 Cyl. 3.6 Eng.; Single Plug Engine..... | 55627 |
| 94 | 6 Cyl. 3.6 Eng..... | 55621 |
| 93 | 6 Cyl. 3.6 Eng.; w/o Turbo.... | 55644 |
| 93 | 6 Cyl. 3.6 Eng.; w/ Turbo.... | 55621 |
| 92 | 6 Cyl. 3.6 Eng..... | 55644 |
| 91 | 6 Cyl. 3.3 Eng..... | 55641 |
| 91 | 6 Cyl. 3.6 Eng..... | 55644 |
| 90 | 6 Cyl. 3.6 Eng..... | 55641 |
| 89 | 6 Cyl. 3.2 Eng..... | 55629 |
| 89 | 6 Cyl. 3.3 Eng..... | 55640 |
| 89 | 6 Cyl. 3.6 Eng..... | 55641 |
| 88-85 | 6 Cyl. 3.2 Eng..... | 55629 |
| 88-85 | 6 Cyl. 3.3 Eng..... | 55640 |
| 84 | 6 Cyl. 3.2 Eng..... | 55628 |
| 84 | 6 Cyl. 3.3 Eng..... | 55640 |
| 83-81 | 6 Cyl. 3.0 Eng..... | 55640 |
| 83-81 | 6 Cyl. 3.3 Eng..... | 55640 |
| 80-78 | 6 Cyl. 3.0 Eng..... | 55640 |
| 77-76 | 6 Cyl. 2.7 Eng..... | 55640 |
| 77-76 | 6 Cyl. 3.0 Eng..... | 55640 |
| 75 | 6 Cyl. 2.7 Eng..... | 55640 |
| 74 | 6 Cyl. 2.7 Eng..... | 55622 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------|---|----------|
| | 911 SERIES | |
| 98 | 6 Cyl. 3.6 Eng.; Dual Plug Engine..... | 55642 |

Continued on Next Column

Continued on Next Page

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------------|---------------------------------|--------------|
| 911 SERIES | | |
| 73-72 | 6 Cyl. 2.4 Eng..... | 55622 |
| 71-70 | 6 Cyl. 2.2 Eng..... | 55622 |
| 69-65 | 6 Cyl. 2.0 Eng..... | 55622 |
| 912 SERIES | | |
| 76 | 4 Cyl. 2.0 Eng..... | 55615 |
| 914 SERIES | | |
| 76 | 4 Cyl. 2.0 Eng..... | 55615 |
| 75-74 | 4 Cyl. 1.8 Eng..... | 55615 |
| 75-74 | 4 Cyl. 2.0 Eng..... | 55615 |
| 73 | 4 Cyl. 1.7 Eng..... | 55615 |
| 73 | 4 Cyl. 2.0 Eng..... | 55615 |
| 72-70 | 4 Cyl. 1.7 Eng..... | 55615 |
| 72-70 | 6 Cyl. 2.0 Eng..... | 55622 |
| 924 SERIES | | |
| 88-87 | 4 Cyl. 2.5 Eng..... | 55610 |
| 82-80 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55619 |
| 82-80 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | 55638 |
| 79-77 | 4 Cyl. 2.0 Eng..... | 55619 |
| 928 SERIES | | |
| 95-93 | 8 Cyl. 5.4 Eng..... | 55636 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------------|--------------------------------|--------------|
| 928 SERIES | | |
| 91-87 | 8 Cyl. 5.0 Eng..... | 55636 |
| 86-85 | 8 Cyl. 5.0 Eng..... | 55635 |
| 84-83 | 8 Cyl. 4.7 Eng..... | 55634 |
| 82-78 | 8 Cyl. 4.5 Eng..... | 55634 |
| 930 SERIES | | |
| 79-78 | 6 Cyl. 3.3 Eng..... | 55640 |
| 944 SERIES | | |
| 91-90 | 4 Cyl. 3.0 Eng.; 16 Valve..... | 55626 |
| 91-90 | 4 Cyl. 3.0 Eng.; 8 Valve..... | 55610 |
| 89 | 4 Cyl. 2.5 Eng.; 16 Valve..... | 55626 |
| 89 | 4 Cyl. 2.5 Eng.; 8 Valve..... | 55610 |
| 89 | 4 Cyl. 2.7 Eng..... | 55610 |
| 89 | 4 Cyl. 3.0 Eng.; 16 Valve..... | 55626 |
| 88-87 | 4 Cyl. 2.5 Eng.; 8 Valve..... | 55610 |
| 88-87 | 4 Cyl. 2.5 Eng.; 16 Valve..... | 55626 |
| 86-83 | 4 Cyl. 2.5 Eng..... | 55610 |
| 968 SERIES | | |
| 95-92 | 4 Cyl. 3.0 Eng..... | 55639 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|---------------------|--------------|
| ALLIANCE | | |
| 87 | 4 Cyl. 1.4 Eng..... | 55435 |
| 87 | 4 Cyl. 1.7 Eng..... | 55450 |
| 87 | 4 Cyl. 2.0 Eng..... | 55457 |
| 86-85 | 4 Cyl. 1.4 Eng..... | 55435 |
| 86-85 | 4 Cyl. 1.7 Eng..... | 55450 |
| 84 | 4 Cyl. 1.4 Eng..... | 55435 |
| 83 | 4 Cyl. 1.4 Eng..... | 55438 |
| ENCORE | | |
| 86-85 | 4 Cyl. 1.4 Eng..... | 55435 |
| 86-85 | 4 Cyl. 1.7 Eng..... | 55450 |
| 84 | 4 Cyl. 1.4 Eng..... | 55435 |
| FUEGO | | |
| 85 | 4 Cyl. 2.2 Eng..... | 55458 |
| 84 | 4 Cyl. 1.6 Eng..... | 55419 |
| 84 | 4 Cyl. 2.2 Eng..... | 55458 |
| 83-82 | 4 Cyl. 1.6 Eng..... | 55419 |
| LECAR | | |
| 85 | 4 Cyl. 2.2 Eng..... | 55458 |
| 84 | 4 Cyl. 1.4 Eng..... | 55437 |
| 84 | 4 Cyl. 2.2 Eng..... | 55458 |
| 83-80 | 4 Cyl. 1.4 Eng..... | 55437 |
| 79-77 | 4 Cyl. 1.3 Eng..... | 55437 |
| R10 | | |
| 71-70 | 4 Cyl. 1.3 Eng..... | 55437 |
| 69-68 | 4 Cyl. 1.1 Eng..... | 55437 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------|------------------------------|--------------|
| R10 | | |
| 69-68 | 4 Cyl. 1.3 Eng..... | 55437 |
| R12 | | |
| 77-71 | 4 Cyl. 1.6 Eng..... | 55453 |
| R15 | | |
| 76-72 | 4 Cyl. 1.6 Eng..... | 55453 |
| R16 | | |
| 72-69 | 4 Cyl. 1.6 Eng..... | 55437 |
| R17 | | |
| 79-76 | 4 Cyl. 1.6 Eng..... | 55453 |
| 75 | 4 Cyl. 1.6 Eng..... | 55437 |
| 74-73 | 4 Cyl. 1.6 Eng..... | 55453 |
| 72 | 4 Cyl. 1.6 Eng..... | 55437 |
| R18 | | |
| 81 | 4 Cyl. 1.6 Eng..... | 55419 |
| R18I | | |
| 86-84 | 4 Cyl. 2.2 Eng. Sport Wagon. | 55458 |
| 83-81 | 4 Cyl. 1.6 Eng..... | 55419 |
| R5 | | |
| 86 | 4 Cyl. 2.2 Eng..... | 55458 |
| 76 | 4 Cyl. 1.3 Eng..... | 55437 |

ROVER

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------|---------------------|---------------|
| 80 | 8 Cyl. 3.5 Eng..... | 3500 55446 |

SAAB

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------|---------------------------------|----------|
| 900 | | |
| 98 | 4 Cyl. 2.0 Eng..... | 55407 |
| 98 | 4 Cyl. 2.3 Eng..... | 55407 |
| 97-95 | 4 Cyl. 2.0 Eng..... | 55407 |
| 97-95 | 4 Cyl. 2.3 Eng..... | 55407 |
| 97-95 | 6 Cyl. 2.5 Eng..... | 55449 |
| 94 | 4 Cyl. 2.0 Eng..... | 55407 |
| 94 | 4 Cyl. 2.1 Eng. Convertible.... | 55440 |
| 94 | 4 Cyl. 2.3 Eng..... | 55407 |
| 94 | 6 Cyl. 2.5 Eng..... | 55449 |
| 93-91 | 4 Cyl. 2.0 Eng..... | 55440 |
| 93-91 | 4 Cyl. 2.1 Eng..... | 55440 |
| 90-89 | 4 Cyl. 2.0 Eng..... | 55440 |
| 88-85 | 4 Cyl. 2.0 Eng.; 8 Valve..... | 55430 |
| 88-85 | 4 Cyl. 2.0 Eng.; 16 Valve..... | 55440 |
| 84 | 4 Cyl. 2.0 Eng..... | 55452 |
| 9000 | | |
| 98 | 4 Cyl. 2.3 Eng..... | 55440 |
| 97-95 | 6 Cyl. 3.0 Eng..... | 55449 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------|--|----------------|
| 9000 | | |
| 93-91 | 4 Cyl. 2.3 Eng.; Exc. Distributorless Ignition..... | 55440 55440 |
| 90 | 4 Cyl. 2.0 Eng..... | 55440 |
| 90 | 4 Cyl. 2.3 Eng.; Exc. Distributorless Ignition..... | 55440 |
| 89-88 | 4 Cyl. 2.0 Eng..... | 55440 |
| 87-86 | 4 Cyl. 2.0 Eng.; 8 Valve..... | 55430 |
| 87-86 | 4 Cyl. 2.0 Eng.; 16 Valve..... | 55440 |
| 9-2X | | |
| 06-05 | 4 Cyl. 2.5 Eng..... | 55504 |
| 9-3 | | |
| 01-99 | 4 Cyl. 2.0 Eng..... | 55407 |
| 01-99 | 4 Cyl. 2.3 Eng..... | 55407 |
| 99 | | |
| 80-75 | 4 Cyl. 2.0 Eng..... | 55452 |

STERLING

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|----------|
| | 825 | |
| 88-87 | 6 Cyl. 2.5 Eng..... | 55018 |
| | 827 | |
| 91-89 | 6 Cyl. 2.7 Eng..... | 55018 |

SUBARU

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-----------------|--------------------------------|----------|
| BAJA | | |
| 06-04 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| FORESTER | | |
| 09-04 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| IMPREZA | | |
| 09-04 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| LEGACY | | |
| 09-08 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| 09-08 | 6 Cyl. 3.0 Eng..... | SPP118E |
| 07-05 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| OUTBACK | | |
| 09-05 | 4 Cyl. 2.5 Eng.; w/ Turbo..... | SPP121E |
| 09-05 | 6 Cyl. 3.0 Eng..... | SPP118E |
| 04-01 | 6 Cyl. 3.0 Eng..... | SPP118E |
| TRIBECA | | |
| 09-08 | 6 Cyl. 3.6 Eng..... | SPP118E |
| 07-06 | 6 Cyl. 3.0 Eng..... | SPP118E |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|--|--------------|
| BAJA | | |
| 06-05 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55500 |
| 04-03 | 4 Cyl. 2.5 Eng..... | 55500 |
| BRAT | | |
| 87-81 | 4 Cyl. 1.8 Eng..... | 55512 |
| 80 | 4 Cyl. 1.6 Eng..... | 55512 |
| 80 | 4 Cyl. 1.8 Eng..... | 55512 |
| 79-78 | 4 Cyl. 1.6 Eng..... | 55511 |
| DL | | |
| 89-88 | 4 Cyl. 1.8 Eng..... | 55509 |
| 87 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 87 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| 86 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 86 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55512 |
| 85 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 85 | 4 Cyl. 1.8 Eng.; w/ Turbo 4 Door..... | 55507 |
| 85 | 4 Cyl. 1.8 Eng.; w/ Turbo 2 Door..... | 55512 |
| 84-80 | 4 Cyl. 1.6 Eng..... | 55512 |
| 84-80 | 4 Cyl. 1.8 Eng..... | 55512 |
| 79-77 | 4 Cyl. 1.6 Eng..... | 55511 |
| 76 | 4 Cyl. 1.4 Eng..... | 55511 |
| 76 | 4 Cyl. 1.6 Eng..... | 55511 |
| FE | | |
| 79 | 4 Cyl. 1.6 Eng..... | 55511 |
| FORESTER | | |
| 10-06 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55504 |
| 05 | 4 Cyl. 2.5 Eng..... | 55504 |
| 04 | 4 Cyl. 2.5 Eng.; SOHC..... | 55500 |
| 03-99 | 4 Cyl. 2.5 Eng..... | 55500 |
| 98 | 4 Cyl. 2.5 Eng..... | 55505 |
| GF | | |
| 79-77 | 4 Cyl. 1.6 Eng..... | 55511 |
| 76 | 4 Cyl. 1.4 Eng..... | 55511 |
| 76 | 4 Cyl. 1.6 Eng..... | 55511 |
| GL | | |
| 89-88 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 89-88 | 4 Cyl. 1.8 Eng. 2 Door..... | 55512 |
| 89-88 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| 87 | 4 Cyl. 1.6 Eng..... | 55512 |
| 87 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 87 | 4 Cyl. 1.8 Eng. 2 Door..... | 55512 |
| 87 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| 86 | 4 Cyl. 1.6 Eng..... | 55509 |
| 86 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 86 | 4 Cyl. 1.8 Eng.; Carb. 4 Door. | 55507 |
| 86 | 4 Cyl. 1.8 Eng.; Carb. 2 Door. | 55512 |
| 86 | 4 Cyl. 1.8 Eng.; MFI..... | 55515 |
| 85 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 85 | 4 Cyl. 1.8 Eng.; Carb. 4 Door. | 55507 |
| 85 | 4 Cyl. 1.8 Eng.; Carb. 2 Door. | 55512 |
| 85 | 4 Cyl. 1.8 Eng.; MFI..... | 55515 |
| 84-81 | 4 Cyl. 1.8 Eng..... | 55512 |
| 80 | 4 Cyl. 1.6 Eng..... | 55512 |
| 80 | 4 Cyl. 1.8 Eng..... | 55512 |
| 79 | 4 Cyl. 1.6 Eng..... | 55512 |
| 75-73 | 4 Cyl. 1.4 Eng..... | 55512 |
| 72 | 4 Cyl. 1.3 Eng..... | 55512 |
| GL-10 | | |
| 89-86 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 89-86 | 4 Cyl. 1.8 Eng. 2 Door..... | 55512 |
| 89-86 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|---|--------------|
| GL-10 | | |
| 85 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 85 | 4 Cyl. 1.8 Eng.; MFI..... | 55515 |
| GLF | | |
| 82-81 | 4 Cyl. 1.8 Eng..... | 55512 |
| 80 | 4 Cyl. 1.6 Eng..... | 55512 |
| 80 | 4 Cyl. 1.8 Eng..... | 55512 |
| IMPREZA | | |
| 10-05 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55504 |
| 04 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55500 |
| 03-02 | 4 Cyl. 2.5 Eng..... | 55500 |
| 01-99 | 4 Cyl. 2.2 Eng..... | 55500 |
| 01-99 | 4 Cyl. 2.5 Eng..... | 55500 |
| 98 | 4 Cyl. 2.5 Eng..... | 55505 |
| 97 | 4 Cyl. 1.8 Eng..... | 55503 |
| 98-97 | 4 Cyl. 2.2 Eng..... | 55503 |
| 96 | 4 Cyl. 1.8 Eng. From 2/96..... | 55503 |
| 96 | 4 Cyl. 1.8 Eng. To 2/96..... | 55506 |
| 96 | 4 Cyl. 2.2 Eng..... | 55502 |
| 95 | 4 Cyl. 1.8 Eng..... | 55506 |
| 95 | 4 Cyl. 2.2 Eng..... | 55502 |
| 94-93 | 4 Cyl. 1.8 Eng..... | 55506 |
| JUSTY | | |
| 94-87 | 3 Cyl. 1.2 Eng..... | 55513 |
| LEGACY | | |
| 08-07 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55504 |
| 06 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55500 |
| 05 | 4 Cyl. 2.5 Eng.; SOHC; Exc. Calif..... | 55504 |
| 05 | 4 Cyl. 2.5 Eng.; SOHC; Calif..... | 55516 |
| 04 | 4 Cyl. 2.5 Eng.; SOHC; Exc. Calif..... | 55500 |
| 04 | 4 Cyl. 2.5 Eng.; SOHC; Calif..... | 55516 |
| 03-02 | 4 Cyl. 2.5 Eng.; SOHC..... | 55500 |
| 01-00 | 4 Cyl. 2.5 Eng..... | 55500 |
| 99 | 4 Cyl. 2.2 Eng..... | 55500 |
| 99 | 4 Cyl. 2.5 Eng..... | 55501 |
| 98 | 4 Cyl. 2.2 Eng..... | 55503 |
| 98 | 4 Cyl. 2.5 Eng..... | 55501 |
| 97 | 4 Cyl. 2.2 Eng..... | 55503 |
| 97 | 4 Cyl. 2.2 Eng.; 90 Deg. Coil Boot..... | 55514 |
| 97 | 4 Cyl. 2.5 Eng. To 4/97..... | 55505 |
| 97 | 4 Cyl. 2.5 Eng. From 5/97..... | 55501 |
| 96 | 4 Cyl. 2.2 Eng..... | 55502 |
| 96 | 4 Cyl. 2.5 Eng. To 5/96..... | 55508 |
| 96 | 4 Cyl. 2.5 Eng. From 6/96..... | 55505 |
| 95-90 | 4 Cyl. 2.2 Eng..... | 55502 |
| LOYALE | | |
| 94-91 | 4 Cyl. 1.8 Eng..... | 55509 |
| 90 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 90 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| OUTBACK | | |
| 08-07 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55504 |
| 06 | 4 Cyl. 2.5 Eng.; w/o Turbo..... | 55516 |
| 05 | 4 Cyl. 2.5 Eng.; Exc. Calif..... | 55504 |
| 05 | 4 Cyl. 2.5 Eng.; Calif..... | 55516 |
| 04 | 4 Cyl. 2.5 Eng.; SOHC; Fed..... | 55500 |
| 04 | 4 Cyl. 2.5 Eng.; SOHC; Calif..... | 55516 |
| 03 | 4 Cyl. 2.5 Eng..... | 55500 |
| 02 | 4 Cyl. 2.5 Eng.; SOHC..... | 55500 |
| 01-00 | 4 Cyl. 2.5 Eng..... | 55500 |

Continued on Next Page

SUBARU

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|---------------------------------|--------------|
| RX | | |
| 89-86 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 89-86 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| STANDARD | | |
| 87 | 4 Cyl. 1.6 Eng..... | 55509 |
| 87 | 4 Cyl. 1.8 Eng..... | 55512 |
| 86-85 | 4 Cyl. 1.6 Eng..... | 55509 |
| 84-80 | 4 Cyl. 1.6 Eng..... | 55512 |
| 79-77 | 4 Cyl. 1.6 Eng..... | 55511 |
| 76 | 4 Cyl. 1.4 Eng..... | 55511 |
| XT | | |
| 91-90 | 4 Cyl. 1.8 Eng..... | 55515 |
| 91-90 | 6 Cyl. 2.7 Eng..... | 55510 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------|---------------------------------|--------------|
| XT | | |
| 89-88 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 89-88 | 4 Cyl. 1.8 Eng. 2 Door..... | 55512 |
| 89-88 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| 89-88 | 6 Cyl. 2.7 Eng..... | 55510 |
| 87-86 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 87-86 | 4 Cyl. 1.8 Eng. 2 Door..... | 55512 |
| 87-86 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |
| 85 | 4 Cyl. 1.8 Eng.; w/o Turbo..... | 55509 |
| 85 | 4 Cyl. 1.8 Eng.; w/ Turbo..... | 55515 |

SUZUKI

COIL ON PLUG BOOT

| Year | Model | Part No. |
|---------------------|---------------------|--------------|
| AERIO | | |
| 07-04 | 4 Cyl. 2.3 Eng..... | SPP91 |
| 03-02 | 4 Cyl. 2.0 Eng..... | SPP91 |
| ESTEEM | | |
| 02 | 4 Cyl. 1.8 Eng..... | SPP91 |
| 01-99 | 4 Cyl. 1.6 Eng..... | SPP92 |
| 01-99 | 4 Cyl. 1.8 Eng..... | SPP91 |
| GRAND VITARA | | |
| 06 | 6 Cyl. 2.7 Eng..... | SPP91 |
| 05-02 | 6 Cyl. 2.5 Eng..... | SPP91 |
| 01 | 6 Cyl. 2.5 Eng..... | SPP91 |
| 01 | 6 Cyl. 2.7 Eng..... | SPP91 |
| 00-99 | 6 Cyl. 2.5 Eng..... | SPP91 |
| SIDEKICK | | |
| 98-96 | 4 Cyl. 1.8 Eng..... | SPP91 |
| SWIFT | | |
| 01-99 | 4 Cyl. 1.3 Eng..... | SPP91 |
| VERONA | | |
| 06-04 | 6 Cyl. 2.5 Eng..... | SPP93 |
| VITARA | | |
| 04 | 6 Cyl. 2.5 Eng..... | SPP91 |
| 03 | 4 Cyl. 2.0 Eng..... | SPP91 |
| 02-99 | 4 Cyl. 1.6 Eng..... | SPP91 |
| 02-99 | 4 Cyl. 2.0 Eng..... | SPP91 |
| XL-7 | | |
| 06-01 | 6 Cyl. 2.7 Eng..... | SPP91 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|--------------------------------|--------------|
| RENO | | |
| 08-05 | 4 Cyl. 2.0 Eng..... | 55402 |
| SAMURAI | | |
| 95-85 | 4 Cyl. 1.3 Eng..... | 55425 |
| SIDEKICK | | |
| 98-96 | 4 Cyl. 1.6 Eng..... | 55408 |
| 95-92 | 4 Cyl. 1.6 Eng.; 16 Valve..... | 55408 |
| 95-92 | 4 Cyl. 1.6 Eng.; 8 Valve..... | 55425 |
| 91-90 | 4 Cyl. 1.6 Eng..... | 55425 |
| 89 | 4 Cyl. 1.3 Eng..... | 55425 |
| 89 | 4 Cyl. 1.6 Eng..... | 55425 |
| SJ413 | | |
| 85 | 4 Cyl. 1.3 Eng..... | 55425 |
| SWIFT | | |
| 01-99 | 4 Cyl. 1.3 Eng..... | 55411 |
| 98 | 4 Cyl. 1.3 Eng..... | 55408 |
| 97-95 | 4 Cyl. 1.3 Eng..... | 55109 |
| 94 | 3 Cyl. 1.0 Eng..... | 55460 |
| 94 | 4 Cyl. 1.3 Eng.; SOHC..... | 55109 |
| 94 | 4 Cyl. 1.3 Eng.; DOHC..... | 55455 |
| 93-92 | 3 Cyl. 1.0 Eng..... | 55460 |
| 93-92 | 4 Cyl. 1.3 Eng.; SOHC..... | 55109 |
| 93-92 | 4 Cyl. 1.3 Eng.; DOHC..... | 55455 |
| 93-92 | 4 Cyl. 1.6 Eng..... | 55403 |
| 91-89 | 4 Cyl. 1.3 Eng.; SOHC..... | 55109 |
| 91-89 | 4 Cyl. 1.3 Eng.; DOHC..... | 55455 |
| VITARA | | |
| 02-99 | 4 Cyl. 1.6 Eng..... | 55411 |
| X-90 | | |
| 98-96 | 4 Cyl. 1.6 Eng..... | 55408 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|---------------------|--------------|
| ESTEEM | | |
| 02 | 4 Cyl. 1.8 Eng..... | 55411 |
| 01-99 | 4 Cyl. 1.6 Eng..... | 55411 |
| 01-99 | 4 Cyl. 1.8 Eng..... | 55411 |
| 98 | 4 Cyl. 1.6 Eng..... | 55408 |
| 97-95 | 4 Cyl. 1.6 Eng..... | 55403 |
| FORENZA | | |
| 08-04 | 4 Cyl. 2.0 Eng..... | 55402 |

Continued on Next Column

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------|--|----------------|
| | 4RUNNER | |
| 02-96 | 6 Cyl. 3.4 Eng..... | SPP79 |
| | AVALON | |
| 99-96 | 6 Cyl. 3.0 Eng.; w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 99-96 | 6 Cyl. 3.0 Eng.; w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| 95 | 6 Cyl. 3.0 Eng..... | SPP83 |
| | CAMRY | |
| 01-96 | 6 Cyl. 3.0 Eng.; w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 01-96 | 6 Cyl. 3.0 Eng.; w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| 95-94 | 6 Cyl. 3.0 Eng..... | SPP83 |
| | PASEO | |
| 99-96 | 4 Cyl. 1.5 Eng..... | SPP80 |
| | SIENNA | |
| 00-98 | 6 Cyl. 3.0 Eng.; w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 00-98 | 6 Cyl. 3.0 Eng.; w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| | SOLARA | |
| 03-99 | 6 Cyl. 3.0 Eng.; w/ 1 5/16 Inch Coil Stem..... | SPP75 |
| 03-99 | 6 Cyl. 3.0 Eng.; w/ 3 1/4 Inch Coil Stem..... | SPP115E |
| | SUPRA | |
| 98-93 | 6 Cyl. 3.0 Eng.; w/ Turbo..... | SPP49 |
| | T100 | |
| 98-95 | 6 Cyl. 3.4 Eng..... | SPP79 |
| | TACOMA | |
| 04-95 | 6 Cyl. 3.4 Eng..... | SPP79 |
| | TERCEL | |
| 99-95 | 4 Cyl. 1.5 Eng..... | SPP80 |
| | TUNDRA | |
| 04-00 | 6 Cyl. 3.4 Eng..... | SPP79 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--------------------------------|---------------|
| | 2000GT | |
| 68-67 | 6 Cyl. 2.0 Eng..... | 55946 |
| | 4RUNNER | |
| 02-01 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 00-97 | 4 Cyl. 2.7 Eng..... | 55901 |
| 00-97 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 96 | 4 Cyl. 2.7 Eng..... | 55900 |
| 96 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 95-93 | 4 Cyl. 2.4 Eng..... | 55907 |
| 95-93 | 6 Cyl. 3.0 Eng..... | 55912 |
| 92 | 4 Cyl. 2.4 Eng..... | 55920 |
| 92 | 6 Cyl. 3.0 Eng..... | 55912 |
| 91 | 4 Cyl. 2.4 Eng..... | 55920 |
| 91 | 6 Cyl. 3.0 Eng..... | 55908 |
| 90 | 4 Cyl. 2.4 Eng..... | 55932 |
| 90 | 6 Cyl. 3.0 Eng..... | 55908 |
| 89 | 4 Cyl. 2.4 Eng..... | 55932 |
| 89 | 6 Cyl. 3.0 Eng. To 3/89..... | 55925 |
| 89 | 6 Cyl. 3.0 Eng. From 4/89..... | 55908 |
| 88 | 4 Cyl. 2.4 Eng..... | 55932 |
| 88 | 6 Cyl. 3.0 Eng..... | 55925 |
| 87-84 | 4 Cyl. 2.4 Eng..... | 55920 |
| | AVALON | |
| 99-96 | 6 Cyl. 3.0 Eng..... | 55917 |

Continued on Next Column

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|--|--------------|
| | CAMRY | |
| 01-99 | 4 Cyl. 2.2 Eng..... | 55906 |
| 01-99 | 6 Cyl. 3.0 Eng.; w/o VVT..... | 55917 |
| 98-97 | 4 Cyl. 2.2 Eng..... | 55906 |
| 98-97 | 6 Cyl. 3.0 Eng..... | 55917 |
| 96 | 4 Cyl. 2.2 Eng..... | 55905 |
| 96 | 6 Cyl. 3.0 Eng..... | 55917 |
| 95-94 | 4 Cyl. 2.2 Eng.; Fed..... | 55904 |
| 95-94 | 4 Cyl. 2.2 Eng.; Calif..... | 55905 |
| 95-94 | 6 Cyl. 3.0 Eng..... | 55928 |
| 93 | 4 Cyl. 2.2 Eng..... | 55903 |
| 93 | 6 Cyl. 3.0 Eng..... | 55928 |
| 92 | 4 Cyl. 2.2 Eng..... | 55903 |
| 92 | 6 Cyl. 2.5 Eng..... | 55936 |
| 92 | 6 Cyl. 3.0 Eng..... | 55928 |
| 91-88 | 6 Cyl. 2.5 Eng..... | 55936 |
| 86-83 | 4 Cyl. 2.0 Eng..... | 55913 |
| | CARINA | |
| 73-72 | 4 Cyl. 1.6 Eng..... | 55931 |
| | CELICA | |
| 99-98 | 4 Cyl. 2.2 Eng..... | 55902 |
| 97-96 | 4 Cyl. 1.8 Eng..... | 55910 |
| 97-96 | 4 Cyl. 2.2 Eng..... | 55902 |
| 95-94 | 4 Cyl. 1.8 Eng..... | 55910 |
| 95-94 | 4 Cyl. 2.2 Eng.; Fed..... | 55904 |
| 95-94 | 4 Cyl. 2.2 Eng.; Calif..... | 55902 |
| 93 | 4 Cyl. 2.0 Eng..... | 55945 |
| 93 | 4 Cyl. 2.2 Eng..... | 55904 |
| 92 | 4 Cyl. 2.0 Eng..... | 55945 |
| 92 | 4 Cyl. 2.2 Eng. Convertible From 8/91 To 9/91..... | 55927 |
| 92 | 4 Cyl. 2.2 Eng. Coupe From 8/91 To 9/91..... | 55904 |
| 91-90 | 4 Cyl. 2.0 Eng..... | 55954 |
| 91-90 | 4 Cyl. 2.2 Eng..... | 55927 |
| 89-88 | 4 Cyl. 2.0 Eng.; w/ Turbo..... | 55947 |
| 89-88 | 4 Cyl. 2.0 Eng.; w/o Turbo..... | 55953 |
| 87 | 4 Cyl. 2.0 Eng..... | 55953 |
| 86 | 4 Cyl. 2.0 Eng..... | 55913 |
| 86 | 4 Cyl. 2.0 Eng. GTS..... | 55953 |
| 85-83 | 4 Cyl. 2.4 Eng..... | 55920 |
| 82-81 | 4 Cyl. 2.4 Eng..... | 55921 |
| 80 | 4 Cyl. 2.2 Eng..... | 55921 |
| 79-78 | 4 Cyl. 2.2 Eng..... | 55956 |
| 74-72 | 4 Cyl. 2.0 Eng..... | 55437 |
| 71 | 4 Cyl. 1.9 Eng..... | 55437 |
| | COROLLA | |
| 00-98 | 4 Cyl. 1.8 Eng..... | 55919 |
| 97-93 | 4 Cyl. 1.6 Eng..... | 55910 |
| 97-93 | 4 Cyl. 1.8 Eng..... | 55910 |
| 92 | 4 Cyl. 1.6 Eng. Sedan..... | 55909 |
| 91-90 | 4 Cyl. 1.6 Eng. Coupe..... | 55951 |
| 89 | 4 Cyl. 1.6 Eng. GTS Coupe.... | 55933 |
| 88 | 4 Cyl. 1.6 Eng. Coupe..... | 55933 |
| 87 | 4 Cyl. 1.6 Eng. FX16..... | 55933 |
| 87 | 4 Cyl. 1.6 Eng. Sport GTS.... | 55952 |
| 87 | 4 Cyl. 1.6 Eng.; U.S. Models.. | 55940 |
| 86 | 4 Cyl. 1.6 Eng.; U.S. Models.. | 55940 |
| 86-85 | 4 Cyl. 1.6 Eng. Sport GTS.... | 55952 |
| 85 | 4 Cyl. 1.6 Eng.; U.S. Models Coupe..... | 55940 |
| 84 | 4 Cyl. 1.6 Eng.; U.S. Models Coupe..... | 55940 |

Continued on Next Page

TOYOTA

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------------|--|---------------|
| COROLLA | | |
| 83 | 4 Cyl. 1.6 Eng..... | 55940 |
| 82-80 | 4 Cyl. 1.8 Eng..... | 55938 |
| 79-71 | 4 Cyl. 1.2 Eng..... | 55955 |
| 79-71 | 4 Cyl. 1.6 Eng..... | 55931 |
| 70 | 4 Cyl. 1.2 Eng..... | 55955 |
| 69 | 4 Cyl. 1.1 Eng..... | 55955 |
| 69 | 4 Cyl. 1.2 Eng..... | 55955 |
| 68 | 4 Cyl. 1.1 Eng..... | 55955 |
| CORONA | | |
| 82-81 | 4 Cyl. 2.4 Eng..... | 55921 |
| 80 | 4 Cyl. 2.2 Eng..... | 55921 |
| 79-78 | 4 Cyl. 2.2 Eng..... | 55956 |
| 74-72 | 4 Cyl. 2.0 Eng..... | 55437 |
| 71-69 | 4 Cyl. 1.9 Eng..... | 55437 |
| 71-69 | 4 Cyl. 1.9 Eng. Mark II..... | 55437 |
| 68-67 | 4 Cyl. 1.9 Eng..... | 55437 |
| CRESSIDA | | |
| 92-89 | 6 Cyl. 3.0 Eng..... | 55943 |
| 88-83 | 6 Cyl. 2.8 Eng..... | 55929 |
| 82-81 | 6 Cyl. 2.8 Eng..... | 55946 |
| 80-78 | 6 Cyl. 2.6 Eng..... | 55946 |
| CROWN | | |
| 72 | 6 Cyl. 2.6 Eng..... | 55946 |
| 71 | 6 Cyl. 2.3 Eng..... | 55946 |
| 71 | 6 Cyl. 2.6 Eng..... | 55946 |
| 70-67 | 6 Cyl. 2.3 Eng..... | 55946 |
| LAND CRUISER | | |
| 97-93 | 6 Cyl. 4.5 Eng..... | 55922 |
| 92-91 | 6 Cyl. 4.0 Eng..... | 55935 |
| 90-88 | 6 Cyl. 4.0 Eng..... | 55949 |
| 87-81 | 6 Cyl. 4.2 Eng..... | 55941 |
| MARK II | | |
| 76-73 | 6 Cyl. 2.6 Eng..... | 55946 |
| 72 | 6 Cyl. 2.3 Eng..... | 55946 |
| MR2 | | |
| 95-93 | 4 Cyl. 2.0 Eng..... | 55957 |
| 95-93 | 4 Cyl. 2.2 Eng..... | 55904 |
| 92 | 4 Cyl. 2.0 Eng. From 1/92..... | 55957 |
| 92 | 4 Cyl. 2.0 Eng. To 1/92..... | 55954 |
| 92 | 4 Cyl. 2.2 Eng. To 1/92..... | 55944 |
| 92 | 4 Cyl. 2.2 Eng. From 1/92..... | 55904 |
| 91 | 4 Cyl. 2.0 Eng..... | 55954 |
| 91 | 4 Cyl. 2.2 Eng..... | 55944 |
| 89-88 | 4 Cyl. 1.6 Eng.; w/o Supercharger..... | 55933 |
| 89-88 | 4 Cyl. 1.6 Eng.; w/ Supercharger..... | 55918 |
| 87-85 | 4 Cyl. 1.6 Eng..... | 55933 |
| PASEO | | |
| 99-96 | 4 Cyl. 1.5 Eng..... | 55914♦ |
| 95-92 | 4 Cyl. 1.5 Eng..... | 55909 |
| PICKUP | | |
| 95-93 | 4 Cyl. 2.4 Eng..... | 55907 |
| 95-93 | 6 Cyl. 3.0 Eng..... | 55912 |
| 92 | 4 Cyl. 2.4 Eng..... | 55920 |
| 92 | 6 Cyl. 3.0 Eng..... | 55912 |
| 91 | 4 Cyl. 2.4 Eng..... | 55920 |
| 91 | 6 Cyl. 3.0 Eng..... | 55908 |
| 90-89 | 4 Cyl. 2.4 Eng.; Carb..... | 55932 |
| 90-89 | 4 Cyl. 2.4 Eng.; FI..... | 55920 |
| 90-89 | 6 Cyl. 3.0 Eng..... | 55908 |
| 88 | 4 Cyl. 2.4 Eng..... | 55920 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|----------------------------------|---------------|
| PICKUP | | |
| 88 | 6 Cyl. 3.0 Eng..... | 55908 |
| 87-83 | 4 Cyl. 2.4 Eng..... | 55920 |
| 82-81 | 4 Cyl. 2.4 Eng..... | 55921 |
| 80 | 4 Cyl. 2.2 Eng..... | 55921 |
| 79-78 | 4 Cyl. 2.2 Eng..... | 55956 |
| 74-72 | 4 Cyl. 2.0 Eng..... | 55437 |
| 71-67 | 4 Cyl. 1.9 Eng..... | 55437 |
| PREVIA | | |
| 97-91 | 4 Cyl. 2.4 Eng..... | 55911 |
| RAV4 | | |
| 00-98 | 4 Cyl. 2.0 Eng..... | 55906 |
| 97-96 | 4 Cyl. 2.0 Eng..... | 55902 |
| SIENNA | | |
| 00-98 | 6 Cyl. 3.0 Eng..... | 55917 |
| SOLARA | | |
| 03-02 | 6 Cyl. 3.0 Eng..... | 55917 |
| 01-99 | 4 Cyl. 2.2 Eng..... | 55906 |
| 01-99 | 6 Cyl. 3.0 Eng..... | 55917 |
| STARLET | | |
| 84-83 | 4 Cyl. 1.3 Eng..... | 55950 |
| 82-81 | 4 Cyl. 1.3 Eng..... | 55937 |
| SUPRA | | |
| 98 | 6 Cyl. 3.0 Eng.; w/o Turbo..... | 55924● |
| 97-93 | 6 Cyl. 3.0 Eng.; w/o Turbo..... | 55942 |
| 92-87 | 6 Cyl. 3.0 Eng.; w/o Turbo..... | 55930 |
| 92-87 | 6 Cyl. 3.0 Eng.; w/ Turbo..... | 55948 |
| 86 | 6 Cyl. 3.0 Eng..... | 55930 |
| 85-82 | 6 Cyl. 2.8 Eng..... | 55929 |
| 81 | 6 Cyl. 2.8 Eng..... | 55946 |
| 80-79 | 6 Cyl. 2.6 Eng..... | 55946 |
| T100 | | |
| 98 | 4 Cyl. 2.7 Eng..... | 55901 |
| 98 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 97-95 | 4 Cyl. 2.7 Eng..... | 55900 |
| 97-95 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 94 | 4 Cyl. 2.7 Eng..... | 55900 |
| 94 | 6 Cyl. 3.0 Eng..... | 55912 |
| 93 | 6 Cyl. 3.0 Eng..... | 55912 |
| TACOMA | | |
| 04-01 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 00 | 4 Cyl. 2.4 Eng.; Exc. Calif..... | 55901 |
| 00 | 4 Cyl. 2.7 Eng.; Exc. Calif..... | 55901 |
| 00 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 99-98 | 4 Cyl. 2.4 Eng..... | 55901 |
| 99-98 | 4 Cyl. 2.7 Eng..... | 55901 |
| 99-98 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 97 | 4 Cyl. 2.4 Eng..... | 55900 |
| 97 | 4 Cyl. 2.7 Eng..... | 55901 |
| 97 | 6 Cyl. 3.4 Eng..... | 55916★ |
| 96-95 | 4 Cyl. 2.4 Eng..... | 55900 |
| 96-95 | 4 Cyl. 2.7 Eng..... | 55900 |
| 96-95 | 6 Cyl. 3.4 Eng..... | 55916★ |
| TERCEL | | |
| 99-95 | 4 Cyl. 1.5 Eng..... | 55914♦ |
| 94-93 | 4 Cyl. 1.5 Eng..... | 55926 |
| 88 | 4 Cyl. 1.5 Eng..... | 55940 |
| 87 | 4 Cyl. 1.5 Eng.; Calif..... | 55940 |
| 86-83 | 4 Cyl. 1.5 Eng..... | 55940 |
| 82-80 | 4 Cyl. 1.5 Eng..... | 55939 |
| TUNDRA | | |
| 04-00 | 6 Cyl. 3.4 Eng..... | 55916★ |

Continued on Next Page

● This 6 Cylinder Set requires three plug leads. The other three cylinders are direct fire.

♦ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

★ Wire Set Contains 3 Leads. Requires 3 Coil Connector Boots.

TOYOTA

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------------------|---------------------|--------------|
| VAN / VAN WAGON | | |
| 89 | 4 Cyl. 2.2 Eng..... | 55923 |
| 88 | 4 Cyl. 2.2 Eng..... | 55923 |
| 88 | 4 Cyl. 2.3 Eng..... | 55923 |
| 88 | 4 Cyl. 2.4 Eng..... | 55923 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------------------|---------------------|--------------|
| VAN / VAN WAGON | | |
| 87-86 | 4 Cyl. 2.2 Eng..... | 55923 |
| 85-84 | 4 Cyl. 2.0 Eng..... | 55923 |

TRIUMPH

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|---------------------|--------------|
| SPITFIRE | | |
| 80-73 | 4 Cyl. 1.5 Eng..... | 55437 |
| 72-68 | 4 Cyl. 1.3 Eng..... | 55437 |
| 67-63 | 4 Cyl. 1.2 Eng..... | 55459 |
| TR6 | | |
| 76 | 6 Cyl. 2.5 Eng..... | 55427 |
| TR7 | | |
| 82-80 | 4 Cyl. 2.0 Eng..... | 55410 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------|---------------------|--------------|
| TR7 | | |
| 79-75 | 4 Cyl. 2.0 Eng..... | 55452 |
| TR8 | | |
| 82-80 | 8 Cyl. 3.5 Eng..... | 55444 |
| 79-78 | 8 Cyl. 3.5 Eng..... | 55445 |

VOLKSWAGEN

COIL ON PLUG BOOT

| Year | Model | Part No. |
|---------------|---------------------|--------------|
| PASSAT | | |
| 99-98 | 4 Cyl. 1.8 Eng..... | SPP56 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------------------|-------------------------------|--------------|
| 411 | | |
| 72-71 | 4 Cyl. 1.7 Eng..... | 55615 |
| 412 | | |
| 74 | 4 Cyl. 1.7 Eng..... | 55615 |
| 74 | 4 Cyl. 1.8 Eng..... | 55615 |
| 73 | 4 Cyl. 1.7 Eng..... | 55615 |
| BEETLE | | |
| 05-02 | 4 Cyl. 2.0 Eng..... | 55602 |
| 01 | 4 Cyl. 2.0 Eng.; AEG Eng..... | 55601 |
| 01 | 4 Cyl. 2.0 Eng.; AZG Eng..... | 55602 |
| 01 | 4 Cyl. 2.0 Eng.; AVH Eng..... | 55602 |
| 00-98 | 4 Cyl. 2.0 Eng..... | 55601 |
| 79-71 | 4 Cyl. 1.6 Eng..... | 55607 |
| 70 | 4 Cyl. 1.6 Eng..... | 55633 |
| 69-67 | 4 Cyl. 1.5 Eng..... | 55633 |
| 66 | 4 Cyl. 1.2 Eng..... | 55633 |
| 66 | 4 Cyl. 1.3 Eng..... | 55633 |
| 65-54 | 4 Cyl. 1.2 Eng..... | 55633 |
| 53 | 4 Cyl. 1.1 Eng..... | 55633 |
| CABRIO | | |
| 02-95 | 4 Cyl. 2.0 Eng..... | 55600 |
| CABRIOLET | | |
| 93-85 | 4 Cyl. 1.8 Eng..... | 55608 |
| CAMPMOBILE | | |
| 79-76 | 4 Cyl. 2.0 Eng..... | 55615 |
| 75-74 | 4 Cyl. 1.8 Eng..... | 55615 |
| 73-72 | 4 Cyl. 1.7 Eng..... | 55615 |
| 71-68 | 4 Cyl. 1.6 Eng..... | 55607 |
| CORRADO | | |
| 95-93 | 6 Cyl. 2.8 Eng..... | 55614 |
| 92 | 4 Cyl. 1.8 Eng..... | 55608 |
| 92 | 6 Cyl. 2.8 Eng..... | 55614 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-----------------|--------------------------------|--------------|
| CORRADO | | |
| 91-90 | 4 Cyl. 1.8 Eng..... | 55608 |
| DASHER | | |
| 81 | 4 Cyl. 1.6 Eng..... | 55613 |
| 80-79 | 4 Cyl. 1.5 Eng..... | 55613 |
| 80-79 | 4 Cyl. 1.6 Eng..... | 55613 |
| 78-76 | 4 Cyl. 1.6 Eng..... | 55613 |
| 75 | 4 Cyl. 1.5 Eng..... | 55613 |
| 74 | 4 Cyl. 1.5 Eng. From 1/74..... | 55613 |
| EUROVAN | | |
| 01-99 | 6 Cyl. 2.8 Eng..... | 55616 |
| 97 | 6 Cyl. 2.8 Eng..... | 55616 |
| 96-92 | 5 Cyl. 2.5 Eng..... | 55623 |
| FASTBACK | | |
| 73-66 | 4 Cyl. 1.6 Eng..... | 55607 |
| FOX | | |
| 93-87 | 4 Cyl. 1.8 Eng..... | 55608 |
| GOLF | | |
| 06-03 | 4 Cyl. 2.0 Eng..... | 55602 |
| 02 | 4 Cyl. 2.0 Eng..... | 55602 |
| 02 | 6 Cyl. 2.8 Eng..... | 55606 |
| 01 | 4 Cyl. 2.0 Eng.; AZG Eng..... | 55602 |
| 01 | 4 Cyl. 2.0 Eng.; AEG Eng..... | 55601 |
| 01 | 4 Cyl. 2.0 Eng.; AVH Eng..... | 55602 |
| 01 | 6 Cyl. 2.8 Eng..... | 55606 |
| 00 | 4 Cyl. 2.0 Eng..... | 55601 |
| 00 | 6 Cyl. 2.8 Eng..... | 55606 |
| 99 | 4 Cyl. 2.0 Eng.; AEG Eng..... | 55601 |
| 99 | 4 Cyl. 2.0 Eng.; ABA Eng..... | 55600 |
| 99 | 6 Cyl. 2.8 Eng.; AAA Eng..... | 55614 |
| 99 | 6 Cyl. 2.8 Eng.; AFP Eng..... | 55606 |
| 98-95 | 4 Cyl. 1.8 Eng..... | 55608 |

Continued on Next Page

VOLKSWAGEN

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------------|--------------------------------|--------------|
| GOLF | | |
| 98-95 | 4 Cyl. 2.0 Eng..... | 55600 |
| 98-95 | 6 Cyl. 2.8 Eng..... | 55614 |
| 94-93 | 4 Cyl. 1.8 Eng..... | 55608 |
| 94-93 | 4 Cyl. 2.0 Eng..... | 55600 |
| 92-90 | 4 Cyl. 1.8 Eng..... | 55608 |
| 92-90 | 4 Cyl. 2.0 Eng..... | 55631 |
| 89-85 | 4 Cyl. 1.8 Eng.; 8 Valve..... | 55608 |
| 89-85 | 4 Cyl. 1.8 Eng.; 16 Valve..... | 55631 |
| GTI | | |
| 06 | 4 Cyl. 2.0 Eng..... | 55602 |
| JETTA | | |
| 10-07 | 4 Cyl. 2.0 Eng..... | 55602 |
| 06 | 4 Cyl. 2.0 Eng. Wagon..... | 55602 |
| 05 | 4 Cyl. 2.0 Eng..... | 55602 |
| 04-03 | 4 Cyl. 2.0 Eng..... | 55602 |
| 04-03 | 6 Cyl. 2.8 Eng..... | 55606 |
| 02 | 4 Cyl. 2.0 Eng..... | 55602 |
| 02 | 6 Cyl. 2.8 Eng.; AFP Eng..... | 55606 |
| 01 | 4 Cyl. 2.0 Eng.; AVH Eng..... | 55602 |
| 01 | 4 Cyl. 2.0 Eng.; AZG Eng..... | 55602 |
| 01 | 4 Cyl. 2.0 Eng.; AEG Eng..... | 55601 |
| 01 | 6 Cyl. 2.8 Eng..... | 55606 |
| 00 | 4 Cyl. 2.0 Eng..... | 55601 |
| 00 | 6 Cyl. 2.8 Eng..... | 55606 |
| 99 | 4 Cyl. 2.0 Eng.; AEG Eng..... | 55601 |
| 99 | 4 Cyl. 2.0 Eng.; ABA Eng..... | 55600 |
| 99 | 6 Cyl. 2.8 Eng.; AAA Eng..... | 55614 |
| 99 | 6 Cyl. 2.8 Eng.; AFP Eng..... | 55606 |
| 98-96 | 4 Cyl. 2.0 Eng..... | 55600 |
| 98-96 | 6 Cyl. 2.8 Eng..... | 55614 |
| 95-94 | 4 Cyl. 1.8 Eng..... | 55608 |
| 95-94 | 4 Cyl. 2.0 Eng..... | 55600 |
| 95-94 | 6 Cyl. 2.8 Eng..... | 55614 |
| 93 | 4 Cyl. 1.8 Eng..... | 55608 |
| 93 | 4 Cyl. 2.0 Eng..... | 55600 |
| 92-90 | 4 Cyl. 1.8 Eng..... | 55608 |
| 92-90 | 4 Cyl. 2.0 Eng..... | 55631 |
| 89-86 | 4 Cyl. 1.8 Eng.; 16 Valve..... | 55631 |
| 89-86 | 4 Cyl. 1.8 Eng.; 8 Valve..... | 55608 |
| 85 | 4 Cyl. 1.8 Eng..... | 55608 |
| 84 | 4 Cyl. 1.7 Eng..... | 55613 |
| 84 | 4 Cyl. 1.8 Eng..... | 55608 |
| 83-82 | 4 Cyl. 1.7 Eng..... | 55613 |
| 81 | 4 Cyl. 1.6 Eng..... | 55613 |
| 81 | 4 Cyl. 1.7 Eng..... | 55613 |
| 80 | 4 Cyl. 1.6 Eng..... | 55613 |
| KARMANN GHIA | | |
| 74-70 | 4 Cyl. 1.6 Eng..... | 55607 |
| 69-67 | 4 Cyl. 1.5 Eng..... | 55633 |
| 66 | 4 Cyl. 1.3 Eng..... | 55633 |
| 65-56 | 4 Cyl. 1.2 Eng..... | 55633 |
| PASSAT | | |
| 05-98 | 6 Cyl. 2.8 Eng..... | 55603 |
| 97 | 6 Cyl. 2.8 Eng..... | 55614 |
| 96-95 | 4 Cyl. 2.0 Eng.; 8 Valve..... | 55600 |
| 96-95 | 4 Cyl. 2.0 Eng.; 16 Valve..... | 55631 |
| 96-95 | 6 Cyl. 2.8 Eng..... | 55614 |
| 94-93 | 4 Cyl. 1.8 Eng..... | 55608 |
| 94-93 | 4 Cyl. 2.0 Eng..... | 55631 |
| 94-93 | 6 Cyl. 2.8 Eng..... | 55614 |
| 92-91 | 4 Cyl. 1.8 Eng..... | 55608 |
| 92-91 | 4 Cyl. 2.0 Eng..... | 55631 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|---------------------------|--------------------------------|--------------|
| PASSAT | | |
| 90 | 4 Cyl. 2.0 Eng..... | 55631 |
| QUANTUM | | |
| 88-86 | 5 Cyl. 2.2 Eng..... | 55624 |
| 85 | 4 Cyl. 1.8 Eng..... | 55608 |
| 85 | 5 Cyl. 2.2 Eng..... | 55624 |
| 84 | 4 Cyl. 1.8 Eng..... | 55608 |
| 84 | 5 Cyl. 2.2 Eng..... | 55632 |
| 83 | 4 Cyl. 1.7 Eng..... | 55608 |
| 83 | 5 Cyl. 2.2 Eng..... | 55632 |
| 82 | 4 Cyl. 1.7 Eng..... | 55608 |
| RABBIT | | |
| 84-83 | 4 Cyl. 1.7 Eng..... | 55613 |
| 84-83 | 4 Cyl. 1.8 Eng..... | 55613 |
| 82 | 4 Cyl. 1.7 Eng..... | 55613 |
| 81 | 4 Cyl. 1.7 Eng..... | 55613 |
| 80 | 4 Cyl. 1.5 Eng..... | 55613 |
| 81-80 | 4 Cyl. 1.6 Eng..... | 55613 |
| 79-78 | 4 Cyl. 1.5 Eng..... | 55613 |
| 77 | 4 Cyl. 1.5 Eng..... | 55613 |
| 77 | 4 Cyl. 1.6 Eng..... | 55613 |
| 76 | 4 Cyl. 1.6 Eng..... | 55613 |
| 75 | 4 Cyl. 1.5 Eng..... | 55613 |
| RABBIT CONVERTIBLE | | |
| 84 | 4 Cyl. 1.8 Eng..... | 55613 |
| 83-81 | 4 Cyl. 1.7 Eng..... | 55613 |
| 80 | 4 Cyl. 1.6 Eng..... | 55613 |
| RABBIT PICKUP | | |
| 84-83 | 4 Cyl. 1.7 Eng..... | 55613 |
| 84-83 | 4 Cyl. 1.8 Eng..... | 55613 |
| 82 | 4 Cyl. 1.7 Eng..... | 55613 |
| 81 | 4 Cyl. 1.7 Eng..... | 55613 |
| 80 | 4 Cyl. 1.5 Eng..... | 55613 |
| 81-80 | 4 Cyl. 1.6 Eng..... | 55613 |
| SCIROCCO | | |
| 89-86 | 4 Cyl. 1.8 Eng.; 16 Valve..... | 55631 |
| 89-86 | 4 Cyl. 1.8 Eng.; 8 Valve..... | 55608 |
| 85 | 4 Cyl. 1.8 Eng..... | 55608 |
| 84 | 4 Cyl. 1.8 Eng..... | 55613 |
| 83 | 4 Cyl. 1.7 Eng..... | 55613 |
| 83 | 4 Cyl. 1.8 Eng..... | 55613 |
| 82-81 | 4 Cyl. 1.7 Eng..... | 55613 |
| 80-79 | 4 Cyl. 1.6 Eng..... | 55613 |
| 78 | 4 Cyl. 1.5 Eng..... | 55613 |
| 77-76 | 4 Cyl. 1.6 Eng..... | 55613 |
| 75 | 4 Cyl. 1.5 Eng..... | 55613 |
| SQUAREBACK | | |
| 73-66 | 4 Cyl. 1.6 Eng..... | 55607 |
| SUPER BEETLE | | |
| 80-79 | 4 Cyl. 1.6 Eng..... | 55633 |
| 78-71 | 4 Cyl. 1.6 Eng..... | 55607 |
| THING | | |
| 74-73 | 4 Cyl. 1.6 Eng..... | 55607 |
| TRANSPORTER | | |
| 93-92 | 5 Cyl. 2.5 Eng..... | 55623 |
| 91-86 | 4 Cyl. 2.1 Eng..... | 55612 |
| 85 | 4 Cyl. 1.9 Eng..... | 55612 |
| 79-76 | 4 Cyl. 2.0 Eng..... | 55615 |
| 75-74 | 4 Cyl. 1.8 Eng..... | 55615 |
| 73 | 4 Cyl. 1.7 Eng..... | 55615 |
| 72 | 4 Cyl. 1.6 Eng..... | 55615 |
| 72 | 4 Cyl. 1.7 Eng..... | 55615 |
| 71-68 | 4 Cyl. 1.6 Eng..... | 55607 |

Continued on Next Page

VOLKSWAGEN

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|--------------------|---------------------|--------------|
| TRANSPORTER | | |
| 67-65 | 4 Cyl. 1.5 Eng..... | 55607 |
| 64-63 | 4 Cyl. 1.2 Eng..... | 55607 |
| 64-63 | 4 Cyl. 1.5 Eng..... | 55607 |
| 62-54 | 4 Cyl. 1.2 Eng..... | 55607 |
| VANAGON | | |
| 91-86 | 4 Cyl. 2.1 Eng..... | 55612 |

Continued on Next Column

VOLVO

COIL ON PLUG BOOT

| Year | Model | Part No. |
|-------------|------------------------------|---------------|
| C70 | | |
| 01-99 | 5 Cyl. 2.3 Eng..... | SPP101 |
| 01-99 | 5 Cyl. 2.4 Eng..... | SPP101 |
| S40 | | |
| 09-05 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 09-05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 04 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 04 | 5 Cyl. 2.5 Eng.; VIN:68..... | SPP102 |
| S60 | | |
| 07-05 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 07-05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 04 | 5 Cyl. 2.5 Eng..... | SPP101 |
| 03-01 | 5 Cyl. 2.3 Eng..... | SPP101 |
| 04-01 | 5 Cyl. 2.4 Eng..... | SPP101 |
| S70 | | |
| 00-99 | 5 Cyl. 2.3 Eng..... | SPP101 |
| 00-99 | 5 Cyl. 2.4 Eng..... | SPP101 |
| S80 | | |
| 06 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 05 | 6 Cyl. 2.9 Eng..... | SPP101 |
| 04 | 5 Cyl. 2.5 Eng..... | SPP101 |
| 04 | 6 Cyl. 2.9 Eng..... | SPP101 |
| 03-02 | 6 Cyl. 2.9 Eng..... | SPP101 |
| 01-99 | 6 Cyl. 2.8 Eng..... | SPP101 |
| 01-99 | 6 Cyl. 2.9 Eng..... | SPP101 |
| V50 | | |
| 07 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 06-05 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 06-05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| V70 | | |
| 07-05 | 5 Cyl. 2.4 Eng..... | SPP102 |
| 07-05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 04-03 | 5 Cyl. 2.3 Eng..... | SPP101 |
| 04-03 | 5 Cyl. 2.4 Eng..... | SPP101 |
| 04-03 | 5 Cyl. 2.5 Eng..... | SPP101 |
| 02-99 | 5 Cyl. 2.3 Eng..... | SPP101 |
| 02-99 | 5 Cyl. 2.4 Eng..... | SPP101 |
| XCT0 | | |
| 07-05 | 5 Cyl. 2.5 Eng..... | SPP102 |
| 04-03 | 5 Cyl. 2.5 Eng..... | SPP101 |
| XC90 | | |
| 05-03 | 5 Cyl. 2.5 Eng..... | SPP101 |
| 05-03 | 6 Cyl. 2.9 Eng..... | SPP101 |

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|------------|---------------------|--------------|
| 122 | | |
| 68-62 | 4 Cyl. 1.8 Eng..... | 55556 |
| 61-59 | 4 Cyl. 1.6 Eng..... | 55556 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|----------------|---------------------|--------------|
| VANAGON | | |
| 85-84 | 4 Cyl. 1.9 Eng..... | 55612 |
| 83 | 4 Cyl. 1.9 Eng..... | 55612 |
| 83 | 4 Cyl. 2.0 Eng..... | 55615 |
| 82-80 | 4 Cyl. 2.0 Eng..... | 55615 |

Continued on Next Page

VOLVO

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|--------------|
| | 264 | |
| 81-80 | 4 Cyl. 2.1 Eng..... | 55561 |
| | 444 | |
| 58-50 | 4 Cyl. 1.4 Eng..... | 55556 |
| | 445 | |
| 60-59 | 4 Cyl. 1.4 Eng..... | 55556 |
| 60-59 | 4 Cyl. 1.6 Eng..... | 55556 |
| 58-56 | 4 Cyl. 1.4 Eng..... | 55556 |
| | 544 | |
| 67-62 | 4 Cyl. 1.8 Eng..... | 55556 |
| 61-59 | 4 Cyl. 1.6 Eng..... | 55556 |
| | 740 | |
| 92-91 | 4 Cyl. 2.3 Eng.; Bosch Coil.... | 55552 |
| 92-91 | 4 Cyl. 2.3 Eng.; w/ Rex Regina Coil..... | 55553 |
| 90-89 | 4 Cyl. 2.3 Eng.; B234F Eng.; 16 Valve..... | 55551 |
| 90-89 | 4 Cyl. 2.3 Eng.; Bosch Coil.... | 55552 |
| 90-89 | 4 Cyl. 2.3 Eng.; w/ Rex Regina Coil..... | 55553 |
| 88-86 | 4 Cyl. 2.3 Eng..... | 55552 |
| 85 | 4 Cyl. 2.3 Eng..... | 55559 |
| | 745 | |
| 85 | 4 Cyl. 2.3 Eng..... | 55559 |
| | 760 | |
| 90-87 | 4 Cyl. 2.3 Eng..... | 55552 |
| 90-87 | 6 Cyl. 2.8 Eng..... | 55554 |
| 86 | 4 Cyl. 2.3 Eng..... | 55552 |
| 86 | 6 Cyl. 2.8 Eng..... | 55557 |
| 85 | 4 Cyl. 2.3 Eng..... | 55559 |
| 85 | 6 Cyl. 2.8 Eng..... | 55557 |
| 84 | 4 Cyl. 2.3 Eng..... | 55559 |
| | 780 | |
| 91 | 4 Cyl. 2.3 Eng..... | 55552 |
| 90-89 | 4 Cyl. 2.3 Eng..... | 55552 |
| 90-89 | 6 Cyl. 2.8 Eng..... | 55554 |
| 88-87 | 6 Cyl. 2.8 Eng..... | 55554 |

Continued on Next Column

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---|---------------|
| | 850 | |
| 97-94 | 5 Cyl. 2.3 Eng..... | 55550 |
| 97-94 | 5 Cyl. 2.4 Eng..... | 55550 |
| 93 | 5 Cyl. 2.4 Eng..... | 55550 |
| | 940 | |
| 95-94 | 4 Cyl. 2.3 Eng.; Bosch Coil.... | 55552 |
| 95-94 | 4 Cyl. 2.3 Eng.; w/ Rex Regina Coil..... | 55558 |
| 93-91 | 4 Cyl. 2.3 Eng.; Bosch Coil.... | 55552 |
| 93-91 | 4 Cyl. 2.3 Eng.; B234F Eng.; 16 Valve..... | 55551 |
| 93-91 | 4 Cyl. 2.3 Eng.; w/ Rex Regina Coil..... | 55553 |
| | C70 | |
| 98 | 5 Cyl. 2.3 Eng..... | 55550 |
| | DL | |
| 84 | 4 Cyl. 2.1 Eng..... | 55559 |
| | GLE | |
| 84 | 4 Cyl. 2.3 Eng..... | 55559 |
| | S40 | |
| 04-00 | 4 Cyl. 1.9 Eng.; w/o B4184SM Engine..... | 55560♦ |
| | S70 | |
| 98 | 5 Cyl. 2.3 Eng..... | 55550 |
| 98 | 5 Cyl. 2.4 Eng..... | 55550 |
| | V40 | |
| 04-00 | 4 Cyl. 1.9 Eng.; w/o B4184SM Engine..... | 55560♦ |
| | V70 | |
| 98 | 5 Cyl. 2.3 Eng..... | 55550 |
| 98 | 5 Cyl. 2.4 Eng..... | 55550 |

YUGO

SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | CABRIO | |
| 92-90 | 4 Cyl. 1.3 Eng..... | 55448 |
| | GV | |
| 92-90 | 4 Cyl. 1.3 Eng..... | 55448 |
| 89-86 | 4 Cyl. 1.1 Eng..... | 55448 |
| | GVL | |
| 89-88 | 4 Cyl. 1.1 Eng..... | 55448 |

Continued on Next Column






SPARK PLUG WIRE SET

| Year | Model | Part No. |
|-------|---------------------|--------------|
| | GVS | |
| 88 | 4 Cyl. 1.1 Eng..... | 55448 |
| | GVX | |
| 89-88 | 4 Cyl. 1.3 Eng..... | 55448 |




♦ Wire Set Contains 2 Leads, The other 2 Cylinders are Coil On Plug Boots.

❖ Wire Set Contains 2 Leads, The Other Two Cylinders Are Direct Ignition.

ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|--|
|  <p>SPP42 Coil On Plug Boot MAZDA 03-99</p> |  <p>SPP53 Coil On Plug Boot INFINITI 94-93 NISSAN 94-90</p> |  <p>SPP60 Coil On Plug Boot HONDA 02-00 ISUZU 04-98</p> |  <p>SPP70 Coil On Plug Boot PORSCHE 08-01</p> |
|  <p>SPP48 Coil On Plug Boot MAZDA 03-95</p> |  <p>SPP54 Coil On Plug Boot INFINITI 97-94 NISSAN 96-94</p> |  <p>SPP61 Coil On Plug Boot HONDA 02-00 ISUZU 04-98</p> |  <p>SPP71 Coil On Plug Boot PORSCHE 06-97</p> |
|  <p>SPP49 Coil On Plug Boot LEXUS 05-98 TOYOTA 98-93</p> |  <p>SPP55 Coil On Plug Boot MITSUBISHI 06-97</p> |  <p>SPP62 Coil On Plug Boot NISSAN 09-02</p> |  <p>SPP72 Coil On Plug Boot LAND ROVER 05-02</p> |
|  <p>SPP50 Coil On Plug Boot INFINITI 06-03 NISSAN 06-03</p> |  <p>SPP56 Coil On Plug Boot AUDI 00-97 VOLKSWAGEN 99-98</p> |  <p>SPP63 Coil On Plug Boot HYUNDAI 06-99 KIA 06-01</p> |  <p>SPP73 Coil On Plug Boot MITSUBISHI 06-03</p> |
|  <p>SPP51 Coil On Plug Boot INFINITI 07-01 NISSAN 09-02</p> |  <p>SPP57 Coil On Plug Boot AUDI 99-97</p> |  <p>SPP67 Coil On Plug Boot BMW 03-91</p> |  <p>SPP74 Coil On Plug Boot MERCEDES-BENZ 00-93</p> |
|  <p>SPP52 Coil On Plug Boot MAZDA 05-01</p> |  <p>SPP58 Coil On Plug Boot AUDI 97-92</p> |  <p>SPP69 Coil On Plug Boot BMW 05-96</p> |  <p>SPP75 Coil On Plug Boot LEXUS 01-96 TOYOTA 03-96</p> |

ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|--|
|  <p>SPP76 Coil On Plug Boot INFINITI 01-96 NISSAN 01-95</p> |  <p>SPP82 Coil On Plug Boot MERCEDES-BENZ 99-97</p> |  <p>SPP89 Coil On Plug Boot HYUNDAI 97-95 KIA 04-98</p> |  <p>SPP96 Coil On Plug Boot NISSAN 06-02</p> |
|  <p>SPP77 Coil On Plug Boot INFINITI 01-96 NISSAN 99-95</p> |  <p>SPP83 Coil On Plug Boot LEXUS 95-94 TOYOTA 95-94</p> |  <p>SPP91 Coil On Plug Boot SUZUKI 07-96</p> |  <p>SPP97 Coil On Plug Boot MERCEDES-BENZ 10-05</p> |
|  <p>SPP78 Coil On Plug Boot NISSAN 01-99</p> |  <p>SPP84 Coil On Plug Boot NISSAN 2001</p> |  <p>SPP92 Coil On Plug Boot SUZUKI 01-99</p> |  <p>SPP98 Coil On Plug Boot NISSAN 94-92</p> |
|  <p>SPP79 Coil On Plug Boot TOYOTA 04-95</p> |  <p>SPP85 Coil On Plug Boot NISSAN 2001</p> |  <p>SPP93 Coil On Plug Boot SUZUKI 06-04</p> |  <p>SPP99 Coil On Plug Boot NISSAN 89-87</p> |
|  <p>SPP80 Coil On Plug Boot TOYOTA 99-95</p> |  <p>SPP86 Coil On Plug Boot HYUNDAI 06-01 KIA 06-02</p> |  <p>SPP94 Coil On Plug Boot MERCEDES-BENZ 05-03</p> |  <p>SPP100 Coil On Plug Boot NISSAN 94-92 NISSAN 94-92</p> |
|  <p>SPP81 Coil On Plug Boot MERCEDES-BENZ 04-01</p> |  <p>SPP88 Coil On Plug Boot MAZDA 08-04</p> |  <p>SPP95 Coil On Plug Boot KIA 02-95</p> | |


ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|--|
|  |  SPP108 Coil On Plug Boot JAGUAR 97-95 |  SPP114E Coil On Plug Boot MAZDA 08-02 |  55001 Spark Plug Wire Set ACURA 00-97 HONDA 00-92 |
|  SPP102 Coil On Plug Boot VOLVO 09-04 |  SPP109 Coil On Plug Boot JAGUAR 03-00 |  SPP115E Coil On Plug Boot LEXUS 01-96 TOYOTA 03-96 |  55002 Spark Plug Wire Set HONDA 95-92 |
|  SPP104 Coil On Plug Boot MITSUBISHI 2006 |  SPP110 Coil On Plug Boot MITSUBISHI 06-03 |  SPP118E Coil On Plug Boot SUBARU 09-01 |  55003 Spark Plug Wire Set HONDA 96-92 |
|  SPP105 Coil On Plug Boot MITSUBISHI 07-04 |  SPP111E Coil On Plug Boot HONDA 08-07 |  SPP121E Coil On Plug Boot SUBARU 09-05 |  55004 Spark Plug Wire Set ACURA 01-96 HONDA 01-97 |
|  SPP106 Coil On Plug Boot MAZDA 07-06 |  SPP112E Coil On Plug Boot PORSCHE 06-03 |  SPP122E Coil On Plug Boot MAZDA 07-06 |  55005 Spark Plug Wire Set ACURA 93-90 |
| | |  55000 Spark Plug Wire Set ACURA 99-97 HONDA 02-94 ISUZU 99-98 | |



ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|---|
| | | | |
| <p>55006 Spark Plug Wire Set ACURA 95-94</p> | <p>55011 Spark Plug Wire Set HONDA 97-90</p> | <p>55016 Spark Plug Wire Set HONDA 91-88</p> | <p>55021 Spark Plug Wire Set HONDA 87-84</p> |
| | | | |
| <p>55007 Spark Plug Wire Set HONDA 87-84</p> | <p>55012 Spark Plug Wire Set ACURA 99-97 HONDA 99-98</p> | <p>55017 Spark Plug Wire Set HONDA 90-88</p> | <p>55022 Spark Plug Wire Set HONDA 87-85</p> |
| | | | |
| <p>55008 Spark Plug Wire Set HONDA 85-83</p> | <p>55013 Spark Plug Wire Set ACURA 01-92 HONDA 00-94</p> | <p>55018 Spark Plug Wire Set ACURA 90-86 STERLING 91-87</p> | <p>55023 Spark Plug Wire Set HONDA 1985</p> |
| | | | |
| <p>55009 Spark Plug Wire Set HONDA 01-93</p> | <p>55014 Spark Plug Wire Set HONDA 96-94 ISUZU 96-93</p> | <p>55019 Spark Plug Wire Set ACURA 98-92</p> | |
| | | | |
| <p>55010 Spark Plug Wire Set HONDA 97-95 ISUZU 97-96</p> | <p>55015 Spark Plug Wire Set HONDA 91-88</p> | <p>55020 Spark Plug Wire Set ACURA 89-86</p> | <p>55025 Spark Plug Wire Set HONDA 89-88</p> |


ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|---|
|  |  |  |  |
| 55026 Spark Plug Wire Set HONDA 97-95 | 55100 Spark Plug Wire Set MAZDA 02-98 | 55105 Spark Plug Wire Set MAZDA 02-95 | 55110 Spark Plug Wire Set KIA 97-94 MAZDA 95-90 |
|  |  |  |  |
| 55027 Spark Plug Wire Set HONDA 1984 | 55101 Spark Plug Wire Set MAZDA 03-01 | 55106 Spark Plug Wire Set MAZDA 98-95 | 55111 Spark Plug Wire Set FIAT 75-74 LADA 83-80 MAZDA 86-70 MERCEDES-BENZ 78-55 OPEL 75-67 |
|  |  |  |  |
| 55028 Spark Plug Wire Set HONDA 83-75 | 55102 Spark Plug Wire Set MAZDA 00-99 | 55107 Spark Plug Wire Set MAZDA 93-86 | 55112 Spark Plug Wire Set MAZDA 05-03 |
|  |  |  |  |
| 55029 Spark Plug Wire Set HONDA 1987 | 55103 Spark Plug Wire Set MAZDA 98-96 | 55108 Spark Plug Wire Set MAZDA 00-90 | 55113 Spark Plug Wire Set MAZDA 97-95 |
|  |  |  |  |
| 55030 Spark Plug Wire Set HONDA 86-85 | 55104 Spark Plug Wire Set MAZDA 94-89 | 55109 Spark Plug Wire Set GEO 97-92 SUZUKI 97-89 | 55114 Spark Plug Wire Set MAZDA 97-93 |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|--|---|
|  |  |  |  |
| 55115 Spark Plug Wire Set MAZDA 02-98 | 55120 Spark Plug Wire Set MAZDA 89-86 | 55125 Spark Plug Wire Set MAZDA 05-01 | 55129 Spark Plug Wire Set MAZDA 94-90 |
|  |  |  |  |
| 55116 Spark Plug Wire Set MAZDA 98-94 | 55121 Spark Plug Wire Set MAZDA 91-90 | 55126 Spark Plug Wire Set MAZDA 85-79 | 55130 Spark Plug Wire Set MAZDA 89-87 |
|  |  |  |  |
| 55117 Spark Plug Wire Set MITSUBISHI 99-91 | 55122 Spark Plug Wire Set MAZDA 95-93 | 55127 Spark Plug Wire Set MAZDA 97-95 | 55131 Spark Plug Wire Set MAZDA 93-92 |
|  |  |  |  |
| 55118 Spark Plug Wire Set MAZDA 95-88 | 55123 Spark Plug Wire Set MAZDA 95-93 | 55128 Spark Plug Wire Set MAZDA 89-88 | 55132 Spark Plug Wire Set MAZDA 78-71 |
|  |  | |  |
| 55119 Spark Plug Wire Set MAZDA 91-86 | 55124 Spark Plug Wire Set MAZDA 95-92 | | 55133 Spark Plug Wire Set MAZDA 96-94 |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|---|--|
|  <p>55200 Spark Plug Wire Set MITSUBISHI 06-97</p> |  <p>55205 Spark Plug Wire Set MITSUBISHI 99-96</p> |  <p>55210 Spark Plug Wire Set MITSUBISHI 96-95</p> |  <p>55215 Spark Plug Wire Set EAGLE 94-91 HYUNDAI 95-89 MITSUBISHI 96-87</p> |
|  <p>55201 Spark Plug Wire Set MITSUBISHI 04-97</p> |  <p>55206 Spark Plug Wire Set MITSUBISHI 98-93</p> |  <p>55211 Spark Plug Wire Set EAGLE 90-88 HYUNDAI 88-87 MITSUBISHI 90-84</p> |  <p>55216 Spark Plug Wire Set MITSUBISHI 88-85</p> |
|  <p>55202 Spark Plug Wire Set MITSUBISHI 04-97</p> |  <p>55207 Spark Plug Wire Set EAGLE 98-95 MITSUBISHI 99-95</p> |  <p>55212 Spark Plug Wire Set EAGLE 98-95 MITSUBISHI 99-94</p> |  <p>55217 Spark Plug Wire Set</p> |
|  <p>55203 Spark Plug Wire Set EAGLE 92-89 MITSUBISHI 89-87</p> |  <p>55208 Spark Plug Wire Set MITSUBISHI 05-99</p> |  <p>55213 Spark Plug Wire Set HYUNDAI 91-90 MITSUBISHI 90-88</p> |  <p>55218 Spark Plug Wire Set MITSUBISHI 06-03</p> |
|  <p>55204 Spark Plug Wire Set MITSUBISHI 94-89</p> |  <p>55209 Spark Plug Wire Set EAGLE 96-91 MITSUBISHI 02-91</p> |  <p>55214 Spark Plug Wire Set MITSUBISHI 99-97</p> | |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|---|---|
|  |  |  |  |
| <p>55219 Spark Plug Wire Set MITSUBISHI 96-94</p> | <p>55223 Spark Plug Wire Set MITSUBISHI 99-92</p> | <p>55301 Spark Plug Wire Set INFINITI 00-97 NISSAN 04-96</p> | <p>55306 Spark Plug Wire Set NISSAN 04-02</p> |
|  |  |  |  |
| <p>55220 Spark Plug Wire Set MITSUBISHI 06-03</p> | <p>55224 Spark Plug Wire Set DODGE 90-89 PLYMOUTH 90-89</p> | <p>55302 Spark Plug Wire Set NISSAN 99-91</p> | <p>55307 Spark Plug Wire Set NISSAN 94-91</p> |
|  |  |  |  |
| <p>55221 Spark Plug Wire Set EAGLE 94-89 HYUNDAI 98-92 MITSUBISHI 94-89</p> | <p>55225 Spark Plug Wire Set HYUNDAI 89-86 MITSUBISHI 89-83</p> | <p>55303 Spark Plug Wire Set NISSAN 01-97</p> | <p>55308 Spark Plug Wire Set NISSAN 96-95</p> |
|  |  |  |  |
| <p>55222 Spark Plug Wire Set MITSUBISHI 2006</p> | <p>55226 Spark Plug Wire Set ISUZU 87-83 MITSUBISHI 87-83</p> | <p>55304 Spark Plug Wire Set NISSAN 01-98</p> | <p>55309 Spark Plug Wire Set NISSAN 98-97</p> |
| |  |  |  |
| | <p>55300 Spark Plug Wire Set NISSAN 98-93</p> | <p>55305 Spark Plug Wire Set INFINITI 94-91 NISSAN 93-91</p> | <p>55310 Spark Plug Wire Set NISSAN 96-90</p> |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|--|---|
| | <p>55316 Spark Plug Wire Set NISSAN 94-89</p> | <p>55321 Spark Plug Wire Set NISSAN 90-89</p> | <p>55326 Spark Plug Wire Set NISSAN 84-70</p> |
| <p>55311 Spark Plug Wire Set NISSAN 97-89</p> | <p>55317 Spark Plug Wire Set NISSAN 96-93</p> | <p>55321 Spark Plug Wire Set NISSAN 90-89</p> | <p>55327 Spark Plug Wire Set INFINITI 92-90 NISSAN 89-85</p> |
| <p>55312 Spark Plug Wire Set NISSAN 96-90</p> | <p>55318 Spark Plug Wire Set NISSAN 02-99</p> | <p>55322 Spark Plug Wire Set NISSAN 92-90</p> | <p>55328 Spark Plug Wire Set NISSAN 84-80</p> |
| <p>55313 Spark Plug Wire Set NISSAN 88-85</p> | <p>55319 Spark Plug Wire Set NISSAN 91-82</p> | <p>55323 Spark Plug Wire Set NISSAN 04-01</p> | <p>55329 Spark Plug Wire Set NISSAN 1985</p> |
| <p>55314 Spark Plug Wire Set NISSAN 89-86</p> | <p>55320 Spark Plug Wire Set NISSAN 83-79</p> | <p>55324 Spark Plug Wire Set NISSAN 89-85</p> | <p>55330 Spark Plug Wire Set NISSAN 1984</p> |
| <p>55315 Spark Plug Wire Set NISSAN 89-86</p> | | <p>55325 Spark Plug Wire Set NISSAN 89-86</p> | |


ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|---|
|  <p>55331 Spark Plug Wire Set NISSAN 88-84</p> |  <p>55337 Spark Plug Wire Set HYUNDAI 87-83 NISSAN 81-79</p> |  <p>55402 Spark Plug Wire Set DAEWOO 02-97 SUZUKI 08-04</p> |  <p>55407 Spark Plug Wire Set SAAB 01-94</p> |
|  <p>55332 Spark Plug Wire Set NISSAN 84-82</p> |  <p>55338 Spark Plug Wire Set INFINITI 00-94 NISSAN 99-94</p> |  <p>55403 Spark Plug Wire Set SUZUKI 97-92</p> |  <p>55408 Spark Plug Wire Set GEO 97-94 SUZUKI 98-92</p> |
|  <p>55333 Spark Plug Wire Set NISSAN 88-87</p> |  <p>55339 Spark Plug Wire Set INFINITI 02-00 NISSAN 01-00</p> |  <p>55404 Spark Plug Wire Set ISUZU 03-98</p> |  <p>55409 Spark Plug Wire Set LAND ROVER 04-99</p> |
|  <p>55334 Spark Plug Wire Set NISSAN 87-84</p> |  <p>55400 Spark Plug Wire Set DAEWOO 02-98</p> |  <p>55405 Spark Plug Wire Set ASUNA 93-92 GEO 93-90 ISUZU 93-89</p> |  <p>55410 Spark Plug Wire Set ISUZU 95-86 MAZDA 85-72 TRIUMPH 82-80</p> |
|  <p>55335 Spark Plug Wire Set NISSAN 80-68</p> |  <p>55401 Spark Plug Wire Set LAND ROVER 08-05</p> |  <p>55406 Spark Plug Wire Set ISUZU 95-92</p> |  <p>55411 Spark Plug Wire Set SUZUKI 02-99 SUZUKI 01-99</p> |

ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|---|---|
| | | | |
| 55411 Spark Plug Wire Set | 55416 Spark Plug Wire Set JAGUAR 96-95 | 55421 Spark Plug Wire Set JAGUAR 94-87 | 55426 Spark Plug Wire Set JAGUAR 87-49 |
| | | | |
| 55412 Spark Plug Wire Set ISUZU 95-92 | 55417 Spark Plug Wire Set JAGUAR 95-92 | 55422 Spark Plug Wire Set MINI 08-02 | 55427 Spark Plug Wire Set LAND ROVER 69-67 TRIUMPH 1976 |
| | | | |
| 55413 Spark Plug Wire Set HONDA 96-94 ISUZU 97-88 | 55418 Spark Plug Wire Set DAIHATSU 92-89 | 55423 Spark Plug Wire Set LAND ROVER 95-94 | 55428 Spark Plug Wire Set LAND ROVER 95-87 |
| | | | |
| 55414 Spark Plug Wire Set ISUZU 89-85 | 55419 Spark Plug Wire Set RENAULT 84-81 | 55424 Spark Plug Wire Set PEUGEOT 91-89 | 55429 Spark Plug Wire Set AUSTIN 75-68 MG 81-63 |
| | | | |
| 55415 Spark Plug Wire Set JAGUAR 91-89 | 55420 Spark Plug Wire Set ISUZU 92-91 | 55425 Spark Plug Wire Set ASUNA 94-92 GEO 95-89 SUZUKI 95-85 | 55430 Spark Plug Wire Set SAAB 88-85 |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|--|---|
|  |  |  |  |
| 55431 Spark Plug Wire Set PEUGEOT 91-70 | 55436 Spark Plug Wire Set FIAT 83-75 | 55441 Spark Plug Wire Set LAND ROVER 05-02 | 55445 Spark Plug Wire Set TRIUMPH 79-78 |
|  |  |  |  |
| 55432 Spark Plug Wire Set DAEWOO 02-97 | 55437 Spark Plug Wire Set MG 79-45 MORRIS 65-58 RENAULT 84-68 TOYOTA 74-67 TRIUMPH 80-68 | 55442 Spark Plug Wire Set DAIHATSU 92-90 |  |
|  |  |  |  |
| 55433 Spark Plug Wire Set ISUZU 94-89 | 55438 Spark Plug Wire Set LAND ROVER 74-67 RENAULT 1983 | 55443 Spark Plug Wire Set ALFA ROMEO 94-82 |  |
| 55434 Spark Plug Wire Set ISUZU 87-81 OPEL 79-76 |  |  |  |
|  | 55439 Spark Plug Wire Set BERTONE 89-84 FIAT 83-74 | 55444 Spark Plug Wire Set TRIUMPH 82-80 |  |
| 55435 Spark Plug Wire Set RENAULT 87-84 | 55440 Spark Plug Wire Set SAAB 98-85 | | 55449 Spark Plug Wire Set SAAB 97-94 |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|--|--|
|  <p>55450 Spark Plug Wire Set RENAULT 87-85</p> |  <p>55455 Spark Plug Wire Set SUZUKI 94-89</p> |  <p>55459 TRIUMPH 67-63 VOLVO 75-66</p> |  <p>55502 Spark Plug Wire Set SUBARU 96-90</p> |
|  <p>55451 Spark Plug Wire Set PEUGEOT 91-89</p> |  <p>55456 Spark Plug Wire Set LAND ROVER 99-96</p> |  <p>55460 Spark Plug Wire Set SUZUKI 94-92</p> |  <p>55503 Spark Plug Wire Set SUBARU 98-96</p> |
|  <p>55452 Spark Plug Wire Set SAAB 84-75 TRIUMPH 79-75</p> |  <p>55457 Spark Plug Wire Set RENAULT 1987</p> |  <p>55461 Spark Plug Wire Set ALFA ROMEO 81-55</p> |  <p>55504 Spark Plug Wire Set SAAB 06-05 SUBARU 10-05</p> |
|  <p>55453 Spark Plug Wire Set NISSAN 81-76 RENAULT 79-71</p> |  <p>55458 Spark Plug Wire Set EAGLE 89-88 PEUGEOT 91-85 RENAULT 86-84</p> | <p>55500 Spark Plug Wire Set SUBARU 06-99</p> |  <p>55505 Spark Plug Wire Set SUBARU 98-96</p> |
|  <p>55454 Spark Plug Wire Set JAGUAR 91-71</p> |  <p>55459 Spark Plug Wire Set AUSTIN 68-62 NISSAN 82-63</p> |  <p>55501 Spark Plug Wire Set SUBARU 99-97</p> |  <p>55506 Spark Plug Wire Set SUBARU 96-93</p> |
| <p>Continued Next Column</p> | | | |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|---|---|
| <p>55507 Spark Plug Wire Set SUBARU 86-85</p> | <p>55512 Spark Plug Wire Set SUBARU 89-72</p> | <p>55550 Spark Plug Wire Set VOLVO 98-93</p> | <p>55555 Spark Plug Wire Set VOLVO 80-76</p> |
| <p>55508 Spark Plug Wire Set SUBARU 1996</p> | <p>55513 Spark Plug Wire Set SUBARU 94-87</p> | <p>55551 Spark Plug Wire Set VOLVO 93-89</p> | <p>55556 Spark Plug Wire Set VOLVO 69-50</p> |
| <p>55509 Spark Plug Wire Set SUBARU 94-85</p> | <p>55514 Spark Plug Wire Set SUBARU 1997</p> | <p>55552 Spark Plug Wire Set VOLVO 95-86</p> | <p>55557 Spark Plug Wire Set PEUGEOT 80-79 VOLVO 86-85</p> |
| <p>55510 Spark Plug Wire Set SUBARU 91-88</p> | <p>55515 Spark Plug Wire Set SUBARU 91-85</p> | <p>55553 Spark Plug Wire Set VOLVO 93-89</p> | <p>55558 Spark Plug Wire Set VOLVO 95-88</p> |
| <p>55511 Spark Plug Wire Set SUBARU 79-76</p> | <p>55516 Spark Plug Wire Set SUBARU 06-04</p> | <p>55554 Spark Plug Wire Set PEUGEOT 90-87 VOLVO 90-87</p> | <p>55559 Spark Plug Wire Set VOLVO 85-83</p> |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|---|--|
|  <p>55560 Spark Plug Wire Set VOLVO 04-00</p> |  <p>55603 Spark Plug Wire Set AUDI 01-97 VOLKSWAGEN 05-98</p> |  <p>55607 Spark Plug Wire Set VOLKSWAGEN 79-54</p> |  <p>55612 Spark Plug Wire Set VOLKSWAGEN 91-83</p> |
|  <p>55561 Spark Plug Wire Set VOLVO 87-80</p> |  <p>55604 Spark Plug Wire Set AUDI 91-90</p> |  <p>55608 Spark Plug Wire Set VOLKSWAGEN 98-82</p> |  <p>55613 Spark Plug Wire Set VOLKSWAGEN 84-74 VOLVO 73-70</p> |
|  <p>55600 Spark Plug Wire Set VOLKSWAGEN 02-93</p> |  <p>55605 Spark Plug Wire Set AUDI 1991</p> |  <p>55609 Spark Plug Wire Set AUDI 90-85</p> |  <p>55614 Spark Plug Wire Set VOLKSWAGEN 99-92</p> |
|  <p>55601 Spark Plug Wire Set VOLKSWAGEN 01-98</p> |  <p>55606 Spark Plug Wire Set VOLKSWAGEN 04-99</p> |  <p>55610 Spark Plug Wire Set PORSCHE 91-83</p> |  <p>55615 Spark Plug Wire Set PORSCHE 76-70 VOLKSWAGEN 83-71</p> |
|  <p>55602 Spark Plug Wire Set VOLKSWAGEN 10-01</p> | |  <p>55611 Spark Plug Wire Set AUDI 79-73</p> |  <p>55616 Spark Plug Wire Set VOLKSWAGEN 01-97</p> |


ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|---|---|
| | | | |
| 55617 Spark Plug Wire Set AUDI 98-92 | 55621 Spark Plug Wire Set PORSCHE 94-93 | 55626 Spark Plug Wire Set PORSCHE 91-87 | 55632 Spark Plug Wire Set AUDI 90-81 VOLKSWAGEN 84-83 |
| | | | |
| 55618 Spark Plug Wire Set AUDI 77-69 | 55622 Spark Plug Wire Set PORSCHE 74-65 | 55627 Spark Plug Wire Set PORSCHE 97-95 | 55633 Spark Plug Wire Set VOLKSWAGEN 80-53 |
| | | | |
| 55619 Spark Plug Wire Set PORSCHE 82-77 | 55623 Spark Plug Wire Set VOLKSWAGEN 96-92 | 55628 Spark Plug Wire Set PORSCHE 1984 | 55634 Spark Plug Wire Set PORSCHE 84-78 |
| | | | |
| 55620 Spark Plug Wire Set AUDI 1985 | 55624 Spark Plug Wire Set AUDI 92-88 VOLKSWAGEN 88-85 | 55629 Spark Plug Wire Set PORSCHE 89-85 | 55635 Spark Plug Wire Set PORSCHE 86-85 |
| | | | |
| | 55625 Spark Plug Wire Set AUDI 88-78 | 55631 Spark Plug Wire Set VOLKSWAGEN 96-85 | 55636 Spark Plug Wire Set PORSCHE 95-87 |

ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|--|--|
| | | | |
| 55637 Spark Plug Wire Set AUDI 84-80 | 55642 Spark Plug Wire Set PORSCHE 98-95 | 55702 Spark Plug Wire Set BMW 1991 | 55707 Spark Plug Wire Set BMW 01-95 |
| | | | |
| 55638 Spark Plug Wire Set PORSCHE 82-80 | 55643 Spark Plug Wire Set AUDI 94-90 | 55703 Spark Plug Wire Set BMW 93-92 | 55708 Spark Plug Wire Set BMW 94-88 |
| | | | |
| 55639 Spark Plug Wire Set PORSCHE 95-92 | 55644 Spark Plug Wire Set PORSCHE 93-91 | 55704 Spark Plug Wire Set BMW 99-94 | 55709 Spark Plug Wire Set BMW 88-84 |
| | | | |
| 55640 Spark Plug Wire Set PORSCHE 89-75 | 55700 Spark Plug Wire Set BMW 79-77 | 55705 Spark Plug Wire Set BMW 76-67 | 55710 Spark Plug Wire Set BMW 90-89 |
| | | | |
| 55641 Spark Plug Wire Set PORSCHE 91-89 | 55701 Spark Plug Wire Set BMW 85-84 | 55706 Spark Plug Wire Set BMW 81-68 | 55711 Spark Plug Wire Set BMW 92-88 |


ILLUSTRATED PARTS GUIDE

| | | | |
|--|---|--|---|
|  <p>55712 Spark Plug Wire Set BMW 93-87</p> |  <p>55717 Spark Plug Wire Set BMW 83-80</p> |  <p>55761 Spark Plug Wire Set MERCEDES-BENZ 05-98</p> |  <p>55765 Spark Plug Wire Set MERCEDES-BENZ 99-96</p> |
|  <p>55713 Spark Plug Wire Set BMW 87-85</p> |  <p>55718 Spark Plug Wire Set BMW 91-88</p> |  <p>55762 Spark Plug Wire Set MERCEDES-BENZ 96-92</p> |  <p>55766 Spark Plug Wire Set MERCEDES-BENZ 96-93</p> |
|  <p>55714 Spark Plug Wire Set BMW 93-91</p> |  <p>55719 Spark Plug Wire Set BMW 88-87</p> |  <p>55763 Spark Plug Wire Set MERCEDES-BENZ 00-97</p> |  <p>55767 Spark Plug Wire Set MERCEDES-BENZ 93-84</p> |
|  <p>55715 Spark Plug Wire Set BMW 97-94</p> |  <p>55720 Spark Plug Wire Set BMW 89-88</p> |  <p>55764 Spark Plug Wire Set MERCEDES-BENZ 10-06</p> |  <p>55768 Spark Plug Wire Set MERCEDES-BENZ 10-98</p> |
|  <p>55716 Spark Plug Wire Set BMW 84-82</p> | | | |

ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|---|
|  <p>55769 Spark Plug Wire Set MERCEDES-BENZ 91-86</p> |  <p>55774 Spark Plug Wire Set MERCEDES-BENZ 81-73</p> |  <p>55800 Spark Plug Wire Set HYUNDAI 03-93</p> |  <p>55805 Spark Plug Wire Set KIA 02-95</p> |
|  <p>55770 Spark Plug Wire Set MERCEDES-BENZ 96-94</p> |  <p>55775 Spark Plug Wire Set MERCEDES-BENZ 73-70</p> |  <p>55801 Spark Plug Wire Set HYUNDAI 10-96 KIA 10-04</p> |  <p>55806 Spark Plug Wire Set KIA 04-98</p> |
|  <p>55771 Spark Plug Wire Set MERCEDES-BENZ 85-74</p> |  <p>55776 Spark Plug Wire Set MERCEDES-BENZ 02-92</p> |  <p>55802 Spark Plug Wire Set HYUNDAI 06-99 KIA 06-01</p> |  <p>55807 Spark Plug Wire Set HYUNDAI 09-05 KIA 10-05</p> |
|  <p>55772 Spark Plug Wire Set MERCEDES-BENZ 93-86</p> |  <p>55777 Spark Plug Wire Set MERCEDES-BENZ 81-73</p> |  <p>55803 Spark Plug Wire Set HYUNDAI 08-99 KIA 06-01</p> |  <p>55808 Spark Plug Wire Set HYUNDAI 02-01 KIA 05-02</p> |
|  <p>55773 Spark Plug Wire Set MERCEDES-BENZ 93-90</p> |  <p>55778 Spark Plug Wire Set MERCEDES-BENZ 93-90</p> |  <p>55804 Spark Plug Wire Set HYUNDAI 05-97</p> | |



ILLUSTRATED PARTS GUIDE

| | | | |
|--|--|---|---|
|  <p>55809 Spark Plug Wire Set KIA 06-03</p> |  <p>55814 Spark Plug Wire Set HYUNDAI 98-92</p> |  <p>55903 Spark Plug Wire Set TOYOTA 93-92</p> |  <p>55908 Spark Plug Wire Set TOYOTA 91-88</p> |
|  <p>55810 Spark Plug Wire Set KIA 05-01</p> |  <p>55815 Spark Plug Wire Set HYUNDAI 97-95</p> |  <p>55904 Spark Plug Wire Set TOYOTA 95-92</p> |  <p>55909 Spark Plug Wire Set TOYOTA 95-92</p> |
|  <p>55811 Spark Plug Wire Set KIA 97-95</p> |  <p>55900 Spark Plug Wire Set TOYOTA 97-94</p> |  <p>55905 Spark Plug Wire Set TOYOTA 96-94</p> |  <p>55910 Spark Plug Wire Set GEO 97-93 TOYOTA 97-93</p> |
|  <p>55812 Spark Plug Wire Set KIA 97-95</p> |  <p>55901 Spark Plug Wire Set TOYOTA 00-97</p> |  <p>55906 Spark Plug Wire Set TOYOTA 01-97</p> |  <p>55911 Spark Plug Wire Set TOYOTA 97-91</p> |
|  <p>55813 Spark Plug Wire Set HYUNDAI 06-03 KIA 06-04</p> |  <p>55902 Spark Plug Wire Set TOYOTA 99-94</p> |  <p>55907 Spark Plug Wire Set TOYOTA 95-93</p> | |




ILLUSTRATED PARTS GUIDE

| | | | |
|---|--|--|--|
| | | | |
| 55912 Spark Plug Wire Set TOYOTA 95-92 | 55917 Spark Plug Wire Set LEXUS 01-96 TOYOTA 03-96 | 55922 Spark Plug Wire Set LEXUS 97-96 TOYOTA 97-93 | 55926 Spark Plug Wire Set TOYOTA 94-93 |
| | | | |
| 55913 Spark Plug Wire Set TOYOTA 86-83 | 55918 Spark Plug Wire Set TOYOTA 89-88 | 55923 Spark Plug Wire Set TOYOTA 89-84 | 55927 Spark Plug Wire Set TOYOTA 92-90 |
| | | | |
| 55914 Spark Plug Wire Set TOYOTA 99-95 | 55919 Spark Plug Wire Set TOYOTA 00-98 | | 55928 Spark Plug Wire Set LEXUS 93-92 TOYOTA 95-92 |
| | | | |
| 55915 Spark Plug Wire Set MAZDA 03-99 | 55920 Spark Plug Wire Set MAZDA 1987 TOYOTA 92-83 | | 55929 Spark Plug Wire Set TOYOTA 88-82 |
| | | | 55930 Spark Plug Wire Set TOYOTA 92-86 |
| 55916 Spark Plug Wire Set TOYOTA 04-95 | 55921 Spark Plug Wire Set TOYOTA 82-80 | | |

ILLUSTRATED PARTS GUIDE

| | | | |
|---|---|--|---|
|  |  |  |  |
| 55931 Spark Plug Wire Set TOYOTA 79-71 | 55936 Spark Plug Wire Set LEXUS 91-90 TOYOTA 92-88 | 55941 Spark Plug Wire Set TOYOTA 87-81 | 55946 Spark Plug Wire Set TOYOTA 82-67 |
|  |  |  |  |
| 55932 Spark Plug Wire Set TOYOTA 90-88 | 55937 Spark Plug Wire Set TOYOTA 82-81 | 55942 Spark Plug Wire Set LEXUS 98-92 TOYOTA 97-93 | 55947 Spark Plug Wire Set TOYOTA 89-88 |
|  |  |  |  |
| 55933 Spark Plug Wire Set TOYOTA 89-85 | 55938 Spark Plug Wire Set TOYOTA 82-80 | 55943 Spark Plug Wire Set TOYOTA 92-89 | 55948 Spark Plug Wire Set TOYOTA 92-87 |
|  |  |  |  |
| 55934 Spark Plug Wire Set LEXUS 94-90 | 55939 Spark Plug Wire Set TOYOTA 82-80 | 55944 Spark Plug Wire Set TOYOTA 92-91 | 55949 Spark Plug Wire Set TOYOTA 90-88 |
|  |  |  | |
| 55935 Spark Plug Wire Set TOYOTA 92-91 | 55940 Spark Plug Wire Set TOYOTA 88-83 | 55945 Spark Plug Wire Set TOYOTA 93-92 | |

ILLUSTRATED PARTS GUIDE

| | | | |
|---|--|---|---|
|  | 55950 Spark Plug Wire Set TOYOTA 84-83 | 55954 TOYOTA 92-90 | |
|  | 55951 Spark Plug Wire Set GEO 92-90 TOYOTA 91-90 |  | 55955 Spark Plug Wire Set TOYOTA 79-68 |
|  | 55952 Spark Plug Wire Set TOYOTA 87-85 |  | 55956 Spark Plug Wire Set TOYOTA 79-78 |
|  | 55953 Spark Plug Wire Set TOYOTA 89-86 |  | 55957 Spark Plug Wire Set TOYOTA 95-92 |
|  | 55954 Spark Plug Wire Set Continued Next Column |  | 55958 Spark Plug Wire Set LEXUS 98-95 |

Notes

Notes

Notes

Notes

Notes

GENUINE INTERMOTOR™ IGNITION WIRE SET LIMITED LIFETIME WARRANTY

Your new Intermotor™ ignition wire set is warranted to you, the original customer, to be free of defects in material and workmanship (as determined solely by Standard Motor Products, Inc.) for the entire life of the engine on which it was originally installed for as long as the engine is owned by the original purchaser of the spark plug wire set.

This warranty does not include labor or cover the cost of any other components or labor required to restore the motor vehicle to its proper operating condition.

This warranty does not apply to Intermotor™ products that have been: 1) altered; 2) improperly installed, maintained or repaired or installed on another engine or motor vehicle; 3) damaged by accident, negligence or misuse; or 4) used in commercial, fleet, heavy duty, off road, public or governmental vehicles.

ALL IMPLIED WARRANTIES, INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE LIMITED TO THE ENTIRE LIFE OF THE ENGINE ON WHICH IT WAS ORIGINALLY INSTALLED FOR SO LONG AS THE ENGINE IS OWNED BY THE ORIGINAL PURCHASER OF THE SPARK PLUG WIRE SET. INTERMOTOR™ IS NOT RESPONSIBLE FOR INJURY, PROPERTY DAMAGE OR OTHER INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING DIRECTLY OR INDIRECTLY OUT OF THE USE OF THIS PRODUCT, NOTWITHSTANDING THE FACT THAT SAID INJURY, PROPERTY DAMAGE OR OTHER INCIDENTAL OR CONSEQUENTIAL DAMAGES AROSE DIRECTLY OR INDIRECTLY FROM AN ACTUAL ALLEGED DEFECT IN MATERIAL AND/OR WORKMANSHIP.

Some states do not allow limitations on how long an implied warranty lasts, or the exclusion of limitation of incidental or consequential damages, so the above limitations or exclusions may not apply to you. This warranty gives you specific legal rights. You may also have other rights that vary from state to state.

For further information regarding this Limited Warranty, contact Standard Motor Products, Inc., 37-18 Northern Boulevard, Long Island City, N.Y. 11101-1616, Attention: Product Assistance Group, 1-800-732-4832.

GARANTIE À VIE LIMITÉE DES CÂBLES DE BOUGIE INTERMOTOR™

Ce nouveau jeu de câbles de bougie Intermotor™ est garanti à l'acheteur original contre tout défaut de matériaux et de fabrication (comme déterminé à la seule discrétion de Standard Motor Products, Inc.) pour toute la durée de vie du moteur sur lequel il a été initialement installé, et tant et aussi longtemps que le moteur appartient à l'acheteur original du jeu de câbles.

Cette garantie ne couvre pas les frais de main-d'œuvre ni le coût de tout autre composant ou de main-d'œuvre nécessaire pour rétablir le bon état de fonctionnement du véhicule.

Cette garantie ne s'applique pas aux produits Intermotor™ qui ont été: 1) modifiés; 2) installés, entretenus ou réparés de manière incorrecte, ou installés sur un autre moteur ou un autre véhicule; 3) endommagés en raison d'un accident, d'une négligence ou d'une utilisation abusive; ou 4) utilisés sur des véhicules lourds, commerciaux, de parcs, tout-terrain, de transport en commun ou gouvernementaux.

TOUTES LES GARANTIES IMPLICITES, NOTAMMENT LES GARANTIES DE QUALITÉ MARCHANDE ET D'ADAPTABILITÉ À UN USAGE PARTICULIER, SE LIMITENT À LA DURÉE DE VIE DU MOTEUR SUR LEQUEL LE JEU DE CÂBLES A ÉTÉ ORIGINALEMENT INSTALLÉ, ET CE, TANT ET AUSSI LONGTEMPS QUE LE MOTEUR APPARTIENT À L'ACHETEUR D'ORIGINE DU JEU DE CÂBLES DE BOUGIE. INTERMOTOR™ N'EST PAS RESPONSABLE DES BLESSURES, DES DOMMAGES MATERIELS ET D'AUTRES DOMMAGES-INTÉRÊTS INDIRECTS OU CONSÉCUTIFS DÉCOULANT DIRECTEMENT OU INDIRECTEMENT DE L'UTILISATION DE CE PRODUIT, MALGRÉ LE FAIT QUE LESDITES BLESSURES, LESDITS DOMMAGES OU TOUS LES AUTRES DOMMAGES-INTÉRÊTS INDIRECTS OU CONSÉCUTIFS PUISENT DÉCOULER DIRECTEMENT OU INDIRECTEMENT D'UN DÉFAUT RÉEL PRÉSUMÉ DE MATERIAUX OU DE FABRICATION.

Certaines provinces interdisent la limitation de la durée d'une garantie implicite ou l'exclusion de la limitation des dommages indirects ou consécutifs; par conséquent, il est possible que les limitations ou les exclusions susmentionnées ne s'appliquent pas au titulaire de cette garantie. Cette garantie confère des droits particuliers à son titulaire, mais il est possible que ce dernier ait d'autres droits pouvant varier d'une province à l'autre.

Pour obtenir de plus amples renseignements sur cette garantie limitée, contacter Standard Motor Products, Inc., 37-18 Northern Boulevard, Long Island City, N.Y. 11101-1616, ou composer le 1 800 732 4832 et demander le Groupe d'assistance sur les produits.

GARANTÍA DE POR VIDA PARA CABLES DE BUJÍAS INTERMOTOR™

Su nuevo conjunto de cables de bujías Intermotor™ está garantizado para usted, el cliente original, como producto libre de defectos de materiales y mano de obra (según lo determinado exclusivamente por Standard Motor Products, Inc.) durante toda la vida útil del motor en el cual se instaló originalmente, siempre que el motor sea propiedad del comprador original del conjunto de cables de bujía.

Esta garantía no incluye mano de obra ni cubre el costo de cualquier otro componente o mano de obra requeridos para restaurar el vehículo motorizado a su condición de operación apropiada.

Esta garantía no se aplica a los productos Intermotor™ que han sido: 1) alterados; 2) instalados, mantenidos o reparados incorrectamente o instalados en otro motor o vehículo motorizado; 3) dañados por accidente, negligencia o mal uso; o 4) usados en flotas comerciales, trabajo pesado, vehículos de obras, públicos o gubernamentales.

TODAS LAS GARANTÍAS IMPLÍCITAS, INCLUSIVELY LAS GARANTÍAS DE COMERCIABILIDAD E IDONEIDAD PARA PROPÓSITOS PARTICULARES, ESTÁN LIMITADAS A LA VIDA ÚTIL DEL MOTOR EN EL CUAL SE INSTALÓ EL PRODUCTO ORIGINALMENTE, SIEMPRE QUE EL MOTOR SEA PROPIEDAD DEL COMPRADOR ORIGINAL DEL CONJUNTO DE CABLES DE BUJÍAS. INTERMOTOR™ NO SERÁ RESPONSABLE POR LESIONES PERSONALES, DAÑOS MATERIALES U OTROS DAÑOS INCIDENTALES O CONSECUENTES QUE SURJAN DIRECTA O INDIRECTAMENTE DEL USO DE ESTE PRODUCTO, NO OBSTANTE EL HECHO DE QUE DICHAS LESIONES PERSONALES, DAÑOS MATERIALES U OTROS DAÑOS INCIDENTALES O CONSECUENTES SURJAN DIRECTA O INDIRECTAMENTE DE UN SUPUESTO DEFECTO REAL DE MATERIAL O MANO DE OBRA.

Algunos estados no permiten limitaciones en la duración de una garantía implícita o la exclusión de limitación de daños incidentales o consecuentes, por lo tanto las limitaciones o exclusiones indicadas anteriormente pueden no aplicarse en su caso. Esta garantía le otorga derechos legales específicos. Usted también puede tener otros derechos que varían de un estado a otro.

Para obtener más información respecto a esta Garantía Limitada, comuníquese con Standard Motor Products, Inc., 37-18 Northern Boulevard, Long Island City, N.Y. 11101-1616, Attention: Product Assistance Group, 1-800-732-4832.

PREMIUM IMPORT IGNITION WIRE SETS

INCLUDING COIL-ON-PLUG BOOTS

APPLICATION & ILLUSTRATED
PARTS GUIDE

Intermotor™
Genuine Import Parts



Long Island City, NY 11101
www.intermotorimport.com


SMP®
Standard Motor Products, Inc.



AAIA®
Automotive Aftermarket
Industry Association



Distributed By:



XXXX.XXM.XXX

Printed in the USA