

## **Learning Log - Toolbox Talk**

Supervisor/Manager to discuss the issue/topic outlined below with the relevant people.

All attendees at the discussion must sign this document to acknowledge the issue.

This completed document is to be submitted to the quality team for closure.

Target completion date				26/01/2023		
Sales Order number		168107				
Process Order number		46086				
Learning Log number				61		
Issue/Topic to	The gu	ılly side openi	ng where th	ne channel joins sl	hould be 13	37mm deep.
be discussed	_	-	_	s at different dep		
	same	because the sa	ame size cha	annel is joined to	both openi	ngs.
Corrective						
Action Taken						
Commonts from						
Comments from Quality						
Department						
Department						
	•					
Name (Block Capitals)				Signature		Date
				~		

## **Relevant Photos**







