Figure 4: FSM Hysteresis Parameter Sweeps and System Trade-offs Across Fault Environments

lines = in-process sweep; diamonds = real live spot-checks (divergence is real, not noise); dashed line = real production default (=2)