

Atlas Copco GA75 Compressor Hydraulic Subsystem — Maintenance Manual

Document number: MAN-HYD-004 Revision: Rev. D
Published: 2024-05-30T00:00:00Z

EQUIPMENT

Tag: EQ-CMP-GA75-02 Plant: South Plant Utilities
Model: GA75 VSD+ Category: Rotary Screw Compressor
Serial: AC-GA75-55021
Manufacturer: Atlas Copco (Sweden)

SAFETY HAZARDS

- High-pressure oil
- Hot surfaces
- Stored hydraulic energy

AUTHORS

- T-1117 Marek Janowski (Hydraulics)
- T-1001 Jordan Reyes (Rotating Equipment)

CONTENTS

- 2 Section 4 — Hydraulic Filter Service
- 3 Section 5 — Oil Change
- 4 Section 6 — Check-Valve Service

Section 4 — Hydraulic Filter Service

Procedure ID: PRC-HYD-004-A

Category: Preventive Maintenance Severity: Low

Performed by: T-1117 Marek Janowski (Hydraulics)

OVERVIEW

This procedure covers replace return-line filter element on equipment EQ-CMP-GA75-02 (GA75 VSD+). Follow the safety hazards listed on page 1 before starting. Lock out and tag out upstream isolation before disassembly.

PARTS REQUIRED

- FLT-HYD-10MIC — Hydraulic Return-Line Filter 10 micron (Filters)
- GSKT-ANSI-150 — ANSI 150 Spiral-Wound Gasket DN50 (Gaskets)

STEPS

1. Confirm isolation per plant LOTO procedure. Verify zero energy state.
2. Stage the parts listed above plus a calibrated torque wrench and clean rags.
3. Disassemble per Section 4 of this manual.
4. Inspect mating surfaces for wear, scoring, or corrosion. Photograph any anomalies.
5. Install replacement parts in the order listed. Torque fasteners per Table 2.
6. Reassemble and reinstate auxiliaries (lubrication, cooling, instrumentation).
7. Remove isolation and perform a no-load function test.
8. Record completion against work order in CMMS.

ACCEPTANCE CRITERIA

- No abnormal vibration or noise during no-load run.
- All fasteners torqued and witness-marked.
- No leaks at static or dynamic seals after a 5-minute run.

Section 5 — Oil Change

Procedure ID: PRC-HYD-004-B

Category: Preventive Maintenance Severity: Medium

Performed by: T-1117 Marek Janowski (Hydraulics)

OVERVIEW

This procedure covers drain and refill hydraulic reservoir on equipment EQ-CMP-GA75-02 (GA75 VSD+). Follow the safety hazards listed on page 1 before starting. Lock out and tag out upstream isolation before disassembly.

PARTS REQUIRED

- OIL-ISO-VG46 — ISO VG46 Hydraulic Oil 20L (Lubricants)

STEPS

1. Confirm isolation per plant LOTO procedure. Verify zero energy state.
2. Stage the parts listed above plus a calibrated torque wrench and clean rags.
3. Disassemble per Section 5 of this manual.
4. Inspect mating surfaces for wear, scoring, or corrosion. Photograph any anomalies.
5. Install replacement parts in the order listed. Torque fasteners per Table 2.
6. Reassemble and reinstate auxiliaries (lubrication, cooling, instrumentation).
7. Remove isolation and perform a no-load function test.
8. Record completion against work order in CMMS.

ACCEPTANCE CRITERIA

- No abnormal vibration or noise during no-load run.
- All fasteners torqued and witness-marked.
- No leaks at static or dynamic seals after a 5-minute run.

Section 6 — Check-Valve Service

Procedure ID: PRC-HYD-004-C

Category: Corrective Maintenance Severity: Medium

Performed by: T-1001 Jordan Reyes (Rotating Equipment)

OVERVIEW

This procedure covers inspect and lap check valve seat on equipment EQ-CMP-GA75-02 (GA75 VSD+). Follow the safety hazards listed on page 1 before starting. Lock out and tag out upstream isolation before disassembly.

PARTS REQUIRED

- VLV-CHK-DN50 — DN50 Swing Check Valve (Valves)

STEPS

1. Confirm isolation per plant LOTO procedure. Verify zero energy state.
2. Stage the parts listed above plus a calibrated torque wrench and clean rags.
3. Disassemble per Section 6 of this manual.
4. Inspect mating surfaces for wear, scoring, or corrosion. Photograph any anomalies.
5. Install replacement parts in the order listed. Torque fasteners per Table 2.
6. Reassemble and reinstate auxiliaries (lubrication, cooling, instrumentation).
7. Remove isolation and perform a no-load function test.
8. Record completion against work order in CMMS.

ACCEPTANCE CRITERIA

- No abnormal vibration or noise during no-load run.
- All fasteners torqued and witness-marked.
- No leaks at static or dynamic seals after a 5-minute run.