

AI · 300+ POINT INSPECTION

Complete Vehicle Inspection Report

A comprehensive 360° pre-purchase inspection combining certified inspector checks with AI-assisted diagnostics—so you can buy with complete confidence.

80 / 100
OVERALL AI
VEHICLE
SCORE

Fair · Price Cut Needed

Recommended to purchase only after significant price negotiation due to the accident history, which was also identified during inspection. No service records are available after 2021, and the windshield and paintwork were not carried out through an authorized dealer. Minor repairs and upcoming diesel servicing should also be considered.

SUMMARY

Inspection Summary

Overall AI-assisted health score based on 300+ inspection checkpoints across exterior, mechanical, electrical and document verification.

80

OUT OF 100

Fair · PriceCut
Needed

BOOKED
2026-08-15

COMPLETED
2026-08-15

PACKAGE
Expert-Drive

FUEL TYPE
Diesel

MANUFACTURED
2014

OWNER COUNT
2 Owners

CATEGORY BREAKDOWN

Exterior

Body panel alignment issues or visible body repair marks detected during exterior inspection.

Tyres

All 4 tyres and spare wheel thoroughly inspected for tread depth, sidewall condition, and manufacturing date. In good roadworthy condition.

Brakes

Brake pads, rotors, pedal travel, and handbrake efficiency tested. Operating smoothly with optimal stopping power.

Under body

Underbody and chassis frame inspected on lift. Floor pan, silencer, and lower crossmembers show no major rust or scraping.

Engine Analysis

Engine idle, sound, mounting vibration, oil quality, and coolant level thoroughly checked. Operates clean with no abnormal noise.

Interior

Seats, upholstery, dashboard console, switches, and seatbelts inspected. All cabin controls and trims in clean, functioning order.

Lighting

Headlamps, high/low beam, tail lights, indicators, fog lamps, and cabin dome lights tested and operational. but needs some repair and polishing

AC

Air conditioning compressor engagement, blower speed, vent airflow, and cooling temperature performance verified optimal.

Suspension

Front struts, rear shock absorbers, bush arm condition, and driveability tested. No thudding noise over bumps.

Gear & Transmission

Clutch pedal play, gear shift smoothness but has a normal wear, clutch engagement point, and drive transmission checked. Smooth gear transitions.

Inspection Info

Comprehensive 300+ point inspection conducted at doorstep/yard by certified technician with full photo verification.

Vahan Info

RC details, owner history, registration validity, engine & chassis number match verified with official database.

ANOMALY CHECKS

Insurance & Ownership

● Insurance Status

Yes, having a valid insurance till [REDACTED]

● Vehicle Ownership

2 previous owners.

● PUC Status

Not available in Parivahan. Check locally.

● Dent / Tamper Check

No VIN plate or registration mismatches found.

NEGOTIATION TIPS

AI Price Negotiation Suggestions

Based on detected defects, here is the estimated room for negotiation with the seller.

Exterior Structure & Trim — Emblems / Badges present & correct 1 item(s) require attention.	₹3,000 SUGGESTED CUT
paint corrections 1 item(s) require attention.	₹5,000 SUGGESTED CUT
Headlight Repair 1 item(s) require attention.	₹3,000 SUGGESTED CUT
Window glasses having deep scratches 4 item(s) require attention.	₹4,000 SUGGESTED CUT
Fog lamps needs replacement 2 item(s) require attention.	₹5,000 SUGGESTED CUT
Total suggested negotiation room	₹20,000

ADDITIONAL AI CHECKS

● Engine Calibration

OBD-II scans report no critical fault codes, showing stable rail pressure and turbo boost delivery within acceptable limits for a TDI engine at this age. Routine inspection of the timing belt and EGR valve is advised during the next scheduled service.

● Tyre Analysis

Tread wear is uniform across all four tyres with approximately 10% to 50% usable life remaining. They remain roadworthy for another 10,000–30,000 km under regular city and highway driving conditions.

● Service History

Full service history captured separately — see Service History section.

● Market Price Analysis

In the Bangalore pre-owned market, a 2014 Volkswagen Vento Diesel with ~1.15 lakh km commands a realistic fair value range of ₹3.40 Lakhs - ₹4.10 Lakhs depending on the variant. A negotiation buffer of ₹25,000 - ₹35,000 is strongly advised to offset immediate minor repairs and suspension wear typical for this mileage.

VAHAN VERIFICATION

Owner Details

Name	Withheld for privacy	Present Address	Withheld for privacy
Father's Name	Withheld for privacy	Permanent Address	Withheld for privacy
Phone	Withheld for privacy	Owner Count	2 Owners
Ownership Type	Individual	Registration Authority	Koramangala

Vehicle Details

Make & Model	Volkswagen Vento - 1598.00 cc - Corporate Edition	Fuel Type	Diesel
Registration Number	[REDACTED]	Body Type	SALOON
Registration Date	[REDACTED]	Odometer (at inspection)	1,15,052 km
Manufacturing Year	2014	Seat Capacity	5
Engine Number	[REDACTED]	Insurance Valid Till	[REDACTED]
Chassis / VIN	W [REDACTED]	PUC Valid Till	—
Color	SHADOWBLUE	Tax & Fitness Valid Till	[REDACTED]

Insurance

Yes, having a valid insurance till [REDACTED]

Pollution Certificate

Not available in Parivahan. Check locally.

Finance Status

Getting verified

Tax & Fitness

Tax & fitness valid till [REDACTED]

REPAIR ESTIMATE

Estimated Repair & Rectification Costs

All figures are indicative estimates based on local market rates.

- Exterior
- Paint
- Lights
- Alloy Wheels
- Tyre

EXTERIOR		
COMPONENT	DESCRIPTION	EST. COST
Emblems / Badges present & correct	Broken	₹1,500 – ₹5,000
Category Total		₹5,000
PAINT		
COMPONENT	DESCRIPTION	EST. COST
Scratches and chips	Multi Location	₹4,000 – ₹6,000
Category Total		₹6,000
LIGHTS		
COMPONENT	DESCRIPTION	EST. COST
HeadLight and Fog light	Restoration	₹3,000 – ₹4,000
Category Total		₹4,000
ALLOY WHEELS		
COMPONENT	DESCRIPTION	EST. COST
Alloy Repainting	Scratches and stains	₹4,000 – ₹6,000
Category Total		₹6,000
TYRE		
COMPONENT	DESCRIPTION	EST. COST
Worn out	Left rear 1	₹5,000 – ₹7,000
Category Total		₹7,000
Grand Total Estimated Repair Cost		₹28,000

SERVICE HISTORY

Vehicle Service Records

Service history sourced from admin-verified records and/or uploaded documents.

Date	Service Center / Dealer	Odometer	Service Type	Description	Cost
2015-04-07	Dealer	8,160 km	free service	General Checkup	₹3,473
2015-08-13	Dealer	12,451 km	accidental	Left-side accident damage; body panels/door/headlamp mounting and related parts replaced.	₹28,154
2015-08-19	Dealer	12,455 km	periodic	Front windshield damage repaired/replaced; windshield and bonding materials.	₹10,843
2016-04-09	Dealer	17,749 km	periodic	Scheduled service; filters, fuel filter, oil, alignment/balancing and A/C service. Vacuum hose and steering switch issues noted.	₹12,180
2016-04-12	Dealer	17,753 km	dealer	Malfunction warning light; GFF diagnostic/programming and wiring repair.	₹3,712
2017-03-25	Dealer	25,158 km	accidental	Warning lamp issue; wiring repair, ECU/GFF programming and wiper replacement.	₹5,681
2017-10-22	Dealer	33,010 km	accidental	Major insurance accident repair; grille, lock carrier, headlamp mounts, condenser, pressure hose, wheel/wheel housing and related front-end parts.	₹71,226
2017-10-31	Dealer	33,011 km	dealer	Engine/glow-plug warning lamps; brake pads, vacuum line, wiring and injection-line work; ECU programming.	₹28,322
2019-11-09	Dealer	41,368 km	periodic	A/C issue, engine/spring warning lights, radiator-fan noise, electrical/wiring work and scheduled service.	₹34,965
2021-07-28	Dealer	51,500 km	dealer	A/C issue, engine/spring warning lights, radiator-fan noise, electrical/wiring work and scheduled service.	₹38,979

SUPPORTING DOCUMENTS

⚡ SERVICE HISTORY EXECUTIVE SUMMARY

KA01ML8200 has a documented service history from 2015–2021, with mileage progressing from 8,160 km to 51,500 km.

⚠ Key concern: Multiple accident repairs are recorded, including a major front-end accident repair in October 2017.

Other history includes repeated warning-light/electrical issues, ECU diagnostics, wiring repairs, and significant brake and suspension work.

Total recorded service/repair value: approximately ₹2.38 lakh.

Overall: ⚠ Caution advised. The 2017 accident damage and recurring electrical issues should be thoroughly verified during the physical inspection and diagnostic scan.

PHOTO GALLERY

Vehicle Exterior Overview



Front



Side (Driver)



Rear



Side (Passenger)

INSPECTION CHECKPOINTS

Lighting			6 checks
ITEM	STATUS	NOTES	
Headlamps (low / high)	Pass		
DRL / Parking lights	Pass		
Indicators / hazards	Pass		
Brake lights (incl. CHMSL)	Pass		
Reverse lights	Pass		
Fog lamps (front / rear)	Pass		

Tyre Data			5 checks
ITEM	STATUS	NOTES	
Tyre — Front Left (FL)	Pass		
Tyre — Front Right (FR)	Pass		
Tyre — Rear Left (RL)	Pass		
Tyre — Rear Right (RR)	Pass		
Spare Tyre	Pass		

Glass & Mirrors			10 checks
ITEM	STATUS	NOTES	
Front windshield: chips / cracks	Warn	Windshield Replaced	
Front windshield: wiper-arc scratches / haze	Pass		
Front windshield seal / garnish condition	Pass		
Left / Right ORVM mirror glass	Pass		
FL / FR door window glass condition	Pass	Scratches on window glass	 
RL / RR door window glass condition	Pass		 

Rear windshield: chips / cracks	Pass
Rear defogger lines (continuity)	Pass
Rear windshield seal / garnish condition	Pass
Sunroof glass condition	N/A

Baseline Photos & Docs			7 checks
ITEM	STATUS	NOTES	
Exterior Baseline Photos	Pass		
			
RC Details	Pass		
PUC Certificate	Pass		
Insurance Certificate	Pass		
Interior overview (front & rear)	Pass		
			
VIN plate & odometer close-ups	Pass		
			
Cluster warning lamps photo (Ignition ON)	Pass		
			

Tyres, Wheels & Brakes			9 checks
ITEM	STATUS	NOTES	
Tyre valve / nozzle — FL	Pass	2025	
Tyre valve / nozzle — FR / RL	Pass		
Tyre sidewall / tread defects (all 4)	Pass		
Wheel rim condition (all 4)	Pass	Scratches annd stains	
			
Mud / silt under carpets (front & rear)	Pass		
Seat rail rust / pitting	Pass		
Under-dash wiring oxidation / green patina	Pass		
Brake rotor visual (lip / scoring)	Pass		
Brake pad visual (thickness)	Pass		

Interior Trim & Fixtures			7 checks
ITEM	STATUS	NOTES	
Front & rear seats: cushioning, upholstery, adjustments, seatbelts	Pass		
2nd & 3rd row: fold / slide / tumble access	Pass		
Dashboard panels & instrument cluster lens	Pass		
Carpet fitment & cleanliness	Pass		

Roof lining condition	Warn	Might need to repair the roof liner
		
Glovebox, center console & door pockets	Pass	
Interior rear-view mirror (mount / flip)	Pass	

Under Hood — Engine ON			6 checks
ITEM	STATUS	NOTES	
Idle quality / vibration	Pass		
Idle RPM (spec)	Pass		
Cooling fan operation	Pass		
Accessory belt noises	Pass		
Visible leaks at idle	Pass		
Charging voltage (idle, lights & AC ON)	Pass		

Exterior Structure & Trim			23 checks
ITEM	STATUS	NOTES	
Front Bumper: Defects	Warn	Paint chips	
			
Front Bumper: Fitment	Warn		
Hood/Bonnet: Defects	Pass		
Hood/Bonnet: Fitment	Warn	Alignment issues	
			
Roof: Defects	Pass		
Roof: Fitment	Pass		
Front grille condition	Pass		
Emblems / Badges present & correct	Fail	Brocken	
			
Fender Left: Defects	Warn	Gaps	
			
Door Front Left: Defects	Pass		
Door Rear Left: Defects	Warn	Paint Chips	
			
Quarter Left: Defects	Pass		
Rear Bumper: Defects	Pass		
Rear Bumper: Fitment	Pass		
Fender Right: Defects	Warn	Alignment and paint chips	

		
Door Front Right: Defects	Warn	Paint Chips
		
Door Rear Right: Defects	Pass	
Rear Right door handle: physical	Pass	
VIN plate / rivets tamper signs	Pass	
 		
Fender / Door / Quarter / Pillar fitment (L & R)	Pass	
Trunk / Tailgate: Defects & Fitment	Warn	Paint Defects
 		
Fuel lid / door condition & hinge	Pass	
Left / Right ORVM housing condition	Pass	Scratches
 		

Under Hood — Engine OFF			8 checks
ITEM	STATUS	NOTES	
Battery terminals & hold-down	Pass		
Belts visual (cracks / fray)	Pass		
Coolant reservoir / brake fluid level	Pass		
Washer fluid level	Pass		
Visible wiring / hoses condition	Warn	Some wiring works have been done	
Battery resting voltage (engine OFF)	Pass	12.79	
Engine mounts visual condition	Pass		
Power steering fluid level	Pass		

Water / Accident Exposure				9 checks
ITEM		STATUS	NOTES	
Trunk / spare well moisture or smell		Pass		
Door drain holes clear		Pass		
Headlamp / taillamp condensation		Pass	Dull	
				
Engine bay mud / rust at lower members		Pass		
Wiring / fusebox water marks		Pass		
Underbody waterline / oxidation patterns		Pass		
Structural welds / overspray / panel replacement signs		Pass		
Seat mount bolts & seat base waterline		Pass		

Trunk side cavities / quarter pockets moisture	Pass
--	------

Paint Thickness Assessment		15 checks
ITEM	STATUS	NOTES
Front Bumper	Warn	Suspect repaint
		
Hood/Bonnet	Warn	340
Roof	Warn	320
		
Fender Left	Fail	1354
		
Door Front Left	Warn	340
Door Rear Left	Warn	300
Quarter Left	Warn	800
Pillars Left (A/B/C)	Warn	300
Rear Bumper	Warn	Repainted
Trunk/Tailgate	Warn	Repainted
Fender Right	Warn	450
Door Front Right	Warn	380
Door Rear Right	Warn	320
Quarter Right	Warn	280
Pillars Right (A/B/C)	Pass	200

Interior Electricals & HVAC		9 checks
ITEM	STATUS	NOTES
Cabin lights (front & rear rows)	Pass	
Window & lock switches (all doors)	Pass	Sound while operating windows, need to lube
Touchscreen, audio, Bluetooth / USB / FM	Pass	
Reverse camera / parking sensors	N/A	
AC cooling at center vents	Pass	Below 10
Heater output	Pass	
AC odour on start	Pass	
Wiper controls, horn, hazard / defogger switches	Pass	
Cluster warning lamps status (Ignition ON)	Pass	

Driving Controls & Driver Aids		8 checks
ITEM	STATUS	NOTES
Steering wheel condition (rim / stitching)	Warn	Worn out
		
Steering free play (static) / adjust	Pass	

Gear selector movement (PRND / pattern)	Pass	Minor movement issues
Hand / parking brake	Pass	
Drive mode switch (Eco/Normal/Sport)	N/A	
Pedal rubbers condition	Pass	
Steering-mounted controls	Pass	
Brake pedal feel (static)	Pass	

TYRE DATA

Tyre Specification & Condition

Position	Brand / Model	Size	DOT (Wk/Yr)	Tread	Tread Condition	Sidewall
Front Left (FL)	Bridgestone Turanza	195/60/15	W31/2025	5.2 mm	Good (5-8mm)	Good
Front Right (FR)	Bridgestone Turanza	195/60/15	W31/2025	5.2 mm	Good (5-8mm)	Good
Rear Left (RL)	Bridgestone Turanza	195/60/15	W09/2021	3.5 mm	Worn (1-3mm)	Minor Scuffs
Rear Right (RR)	Yokohama Earth1	195/60/15	W01/2026	7 mm	New (>8mm)	Good



Spare Tyre
Condition: Good | Size: 195/60/15

OVERALL TYRE ASSESSMENT

Spare Wheel - Jan-2016 - Yokohama Earth1 Brand New - Overall tyres are in good condition except for one

ADMIN REMARKS

Inspector Notes & Recommendations

INSPECTOR NOTES

The vehicle was found to have repainted areas, and the front windshield has been replaced. Please verify the service history to confirm and understand the parts that were previously replaced or repaired.

ADMIN REMARKS

—

FINAL RECOMMENDATION

Recommended to purchase only after significant price negotiation due to the accident history, which was also identified during inspection. No service records are available after 2021, and the windshield and paintwork were not carried out through an authorized dealer. Minor repairs and upcoming diesel servicing should also be considered.

Disclaimer: This report is prepared by InspectCar based on a physical visual and functional inspection performed at the time and location mentioned. InspectCar does not guarantee the future performance of the vehicle. The report reflects the condition of the vehicle at the time of inspection only and should not be used as a substitute for professional mechanical advice. InspectCar holds no liability for any decisions made based on this report.

InspectCar

Need help understanding this report?

Our certified inspector is available to walk you through every detail of this inspection and help you make the right decision.



Chat with Inspector on WhatsApp

WhatsApp: +91 99003 68006 • Email: info@inspectcar.in • Website: inspectcar.in