

Analogwert als Bargraph anzeigen Indicating an analog value as a bar graph



Creator:	ADBEJO0		Project:	Analogwert als Bargraph anzeigen	Customer:	SIEMENS AG
Checked:	Beyer	CIERAENIC	Installation:	Indicating an analog value as a bar graph	Diagram No.:	
Date:	3/22/10 4:37 PM/3/31/10 1:24 PM	SIEWIENS	File:	indicating_an_analog_value_as_bar_graph.lsc	Page:	1/5



Deutsch:

Im LOGO! Display sollen Analogwerte (Füllstand, Temperatur und Druck) als Bargraph angezeigt werden.

Dafür gibt es in der Funktion Meldetext ein Symbol "Balkendiagramm in Meldung einfügen".

Sie müssen den Funktionsblock auswählen der den Parameter enthält, den Sie als Bargraph darstellen möchten.

Im nächsten Schritt müssen Sie neben der Ausrichtung und der Größe des Bargraphen auch den Wertebereich definieren.

Beispiel 1 - Füllstand Al1:

Am Analogeingang Al1 wird in diesem Fall mit einem Füllstanssensor 0-10V der Füllstand eines Behälters ausgewertet.

An einer LOGO! mit integrierten Analogeingängen (DC-Varianten) kann der Sensor am Grundmodul angeschlossen werden.

Die vom Signalwandler ausgegebene Spannung entspricht in diesem Beispiel 0-2560L. Die Skalierung nehmen Sie im Block B012 vor.

Der gesamte Bereich (0...2560) wird als Bargraph in Meldetext B013 dargestellt.

Beispiel 2 - Temperatur Al3:

Mit dem Erweiterungsmodul AM2 PT100 erfassen Sie Temperaturen von -50,0°C bis +200,0°C. Die Skalierung nehmen Sie im Block B001 vor.

Damit der Wertebereich übereinstimmt, geben Sie auch für den Bargraphen -500 bis +2000 an (siehe B003).

Wenn Sie in der Realität allerdings nur kleine Temperaturschwankungen haben, werden diese auf der Bargraph-Anzeige nur schwer wahrgenommen.

Es ist also sinvoll den Wertebereich auf das zu reduzieren, was in der Realität von Interesse ist, z.B. 15,0°C bis 40,0°C (siehe B004).

Somit muss der Bargraph nur einen kleinen Bereich darstellen, die Anzeige wird dadurch genauer.

Beispiel 3 - Druck Al5:

Mit dem Erweiterungsmodul AM2 können Sie Sensorsignale 4-20 mA auswerten.

Der angeschlossene Drucksensor hat einen Messbereich von 0...12,00bar (skaliert in B002).

Der gesamte Bereich (0...1200) wird als Bargraph in B005 dargestellt.

In der Realität schwankt der Druck aber nur im Bereich von 3,00 bis 8,00 bar. Diesen Bereich stellt der Bargraph in B009 dar.

Verwendete Komponenten:

- LOGO! 12/24RC (integrierte 0-10V Eingänge)
- AM2 RTD (für Widerstandstemperatursensoren PT100/PT1000)
- AM2 (für 0-10V / 0-20mA / 4-20mA)
- LOGO! Power 24V
- LOGO! TD (optional)

Auch andere Konstellationen möglich.

Creator:	ADBEJO0		Project:	Analogwert als Bargraph anzeigen	Customer:	SIEMENS AG
Checked:	Beyer	CIERAENIC	Installation:	Indicating an analog value as a bar graph	Diagram No.:	
Date:	3/22/10 4:37 PM/3/31/10 1:24 PM	SIEMIEMS	File:	indicating_an_analog_value_as_bar_graph.lsc	Page:	3/5

English:

The LOGO! display shall indicate analog values (fill level, temperature and pressure) as a bar graph.

Therefore a symbol "Insert bar graph into message text" exists in the function message text.

You have to select the function block which contains the paramameter to be indicated as bar graph.

In the next step, additionally to the direction and size of the bar graph you have to define its value range.

Example 1 - Fill level Al1:

By using a fill level sensor 0-10V at the analog input Al1, in this case the fill level of a tank is evaluated.

The sensor can be connected to the integrated analog inputs (DC-versions) of the base unit.

The output voltage, generated by the signal converter, is equal to 0-2560L in this example. The scaling has to be done in block B012

The complete range (0...2560) is displayed as bar graph in message text B013.

Example 2 - Temperature Al3:

With the expansion module AM2 PT100 you can measure temperatures from -50.0°C to +200.0°C. The scaling has to be done in block B001.

To indicate the same value range, also define -500 to +2000 for the bar graph (see block B003).

But if the temperature in reality fluctuates within a small range, maybe it can hardly be recognized on the bar graph indication.

So it makes sense to reduce the value range to values which are of interest in reality, e.g. 15.0°C to 40.0°C (see B004).

Hence, the bar graph only has to indicate a small range, thus the indication is more accurate.

Example 3 - Pressure AI5:

With the expansion module AM2 you can evaluate sensor signals of 4-20mA.

The connected pressure sensor has a measuring range of 0...12.00bar (scaled in B002).

The complete range (0...1200) is displayed as a bar graph in B005.

But in reality the pressure only fluctuates within a rage of 3.00 to 8.00 bar. This range is represented by the bar graph in B009.

Used components:

- LOGO! 12/24RC (integrated 0-10V inputs)
- AM2 RTD (for resistance temperature sensors PT100/PT1000)
- AM2 (for 0-10V / 0-20mA / 4-20mA)
- LOGO! Power 24V
- LOGO! TD (optional)

Other combinations are also possible!

Creator:	ADBEJO0		Project:	Analogwert als Bargraph anzeigen	Customer:	SIEMENS AG
Checked:	Beyer	CIERAENIC	Installation:	Indicating an analog value as a bar graph	Diagram No.:	
Date:	3/22/10 4:37 PM/3/31/10 1:24 PM	SIEIVIENS	File:	indicating_an_analog_value_as_bar_graph.lsc	Page:	4/5

SIEMENS AG- Beispielprogramm

Warnung und Haftungsausschluss

Siemens AG Programmbeispiel ohne Gewähr

Warnung:

Steuerungen können bei unsicheren Betriebszuständen ausfallen und dadurch den unkontrollierten Betrieb der gesteuerten Geräte verursachen. Solche gefährliche Ereignisse können zu tödlichen und/oder schweren Verletzungen und/oder Sachschaden führen. Sorgen Sie daher für eine NOT-AUS-Funktion, elektrische oder andere redundante Sicherheitseinrichtungen, die von Ihrem Automatisierungssystem unabhängig sind.

Haftungsausschluss:

Jeder Anwender ist für den sachgemäßen Betrieb seines LOGO-Systems selbst verantwortlich. Dieses Programm enthebt Sie nicht der Verpflichtung zu sicherem Umgang bei Anwendung, Instalation, Betrieb und Wartung. Durch die Nutzung dieses von der Siemens AG erstellten Programm-Beispieles erkennen Sie an, daß die Siemens AG unter keinen Umständen für möglicherweise infolge der Nutzung auftretende Sach- und/oder Personenschäden haftbar gemacht werden kann.

SIEMENS AG- Example Program

Warning and Disclaimer of Liability

Siemens AG Example Program without Liability

Warning:

Unsafe operating conditions can cause controllers to fail, resulting in unchecked operation of controlled devices.


Such hazardous events can cause death and/or serious injury and/or material damage. You must therefore provide an emergency stop function and electric or other redundant safety devices that are independent of your automation system.


Disclaimer of Liability:

Users are solely responsible for the correct operation of their LOGO! systems. This program does not relieve you of the obligation to observe safe practices during implementation, installation, operation, and maintenance. By using this example program created by Siemens AG, you acknowledge that Siemens AG cannot under any circumstances be held liable for any possible personal injury or material damage resulting from the use of this program.

Creator:	ADBEJO0		Project:	Analogwert als Bargraph anzeigen	Customer:	SIEMENS AG
Checked:	Beyer	CIERAENIC	Installation:	Indicating an analog value as a bar graph	Diagram No.:	
Date:	3/22/10 4:37 PM/3/31/10 1:24 PM	DIEIVIEND	File:	indicating_an_analog_value_as_bar_graph.lsc	Page:	5/5

-	Creator: ADBEJO0 Project: Analogwert als B Checked: Beyer SIEMENS Installation: Indicating an and Date: 3/22/10 4:37 PM/3/31/10 1:24 PM File: Indicating, an, an	<pre>Line3.2 Param: B001 temp Ax, amplified Line4.3 Bar: B001 temp Ax, amplified; Max = 400; Min = 150; Dir = I</pre>	1 5 9 Bar: 25.3 10 4 0	n p e r a t u r e	B004 (Message texts): Größe des Bargraphen geht über einen Teilbereich des Sensors (150400) Bar graph size covers part of the range of the sensor (150400)	<pre>Line3.2 Param: B001 temp Ax, amplified Line4.4 Bar: B001 temp Ax, amplified; Max = 2000; Min = -500; Dir =</pre>	p e r a t u r e 001 temp Az, °C 25.3 A→ 8001 temp °C	B002 press.(Analog Amplifier): Sensor: 4-20mA Min: 4mA = 0bar Max: 20mA = 12.00bar	B001 temp.(Analog Amplifier): -50 +200°C Auflösung x0,1 (Anzeige mit einer Kommastelle) Resolution x0.1 (Indication with one decimal)	AI5(Analog input) : Drucksensor 0-12bar mit Signalwandler auf 4-20mA Pressure sensor 0-12bar with signal converter 4-20mA	AI3(Analog input) : PT100 Temperatursensor PT100 temperature sensor	AII(Analog input): Füllstandssensor 0-2560L mit Signalwandler auf 0-10V Fill level sensor 0-2560 with signal converter 0-10V	
L	Analogwert als Bargraph anzeige Customer: SIEMENS AG Indicating an analog value as a Diagram No.: 6	Hor; Len = 8	- Line4: N Message Destination - Both	aractne1: ne1: ne2: ne3:	Prio = 1 Quit = off Text1: ISO8859_1 Text2: disabled Ticker setting	= Hor; Len = 6	- Character by character - Line1: N - Line2: N - Line3: N - Line4: N Message Destination - Both	Gain =1.5+ Offset=-300 Point =2	Gain =2.5+ Offset=-500 Point =1				





ADBEJO0 Project: Analogwert als Bargraph anzeige Beyer SIEMS Installation: Indicating an analog value as a 3/22/10 4:37 PM/3/31/10 1:24 PM File: indicating_an_analog_value_as_1

Checked: Date:	Organi	×	X3	X	×	A	A	۵	۵	۵	Q13	Q12	Q11	۵	9	Q8	Q7	90	Q5	Q4	Q3	Q2	δ	AI8	AI7	Al6	AI5	AI4	AI3	AI2	AI1	S8	S7	S6	S5	S4	ç
		-	<u>س</u>		_	AQ2	AQ1	Q16	Q15	Q14	13	12	1 1 1	Q10	9	8	7	03	51	4	ω	2		σ	7	6	5	4	3	2		<u> </u>	,	0,	Oi.	+	Connection
Beyer 3/22/10 4:37	ADBE IO																																				<u> </u>
Beyer 3/22/10 4:37 PM/3/31/10 1:24 PM	5																																				Label
11/10 1:24 F																																					_
M																																					
SIE																																					
SIEMENS Installation: File:																																					
File	D 3																																				
allation: :	.																																				
Indicatin	Apalogi																																				
Indicating an analog value as a Diagram Nindicating_an_analog_value_as_t Page:	ort of																																				
y value as a	0000																																				
Diagrai s_b Page:																																					
P.																																					
10	O III																																				
	5																																				

	X16	X15	X14	X13	X12	X11	X10	X9	X8	X7	X6	X5	Connection
ADBEJO0 Beyer 3/22/10 4:37 PM/3/31/10 1:24 PM													Label
SIEMENS Project Installation:													
Analogwert als Bargraph anzeige Customer. Indicating an analog value as a Diagram No.: Indicating an_analog_value as begin an analog_value as be													
Customer: Diagram No.: Page:													
SIEMENS AG													