

PLAN — WICK SIDE UP
SCALE 2:1

34

68

7

100 x Ø2.6

WICK 0.20 THK

60 WICK ZONE

68

DETAIL E — POST LAND
SCALE 20:1

DIFFUSION BOND

1.0

0.20

Ø2.6

Ø2.0

DETAIL F — FILL PORT
SCALE 10:1

TUBE OD3.0 / ID2.0 x 25 LG

BAG-8 BRAZE FILLET

0.30

NOTES

1. MATL: Cu C1100 OFHC annealed, 1.0 sheet.
2. Flatness 0.02 over 68 x 68 after sintering.
3. Wick clearance holes keep post lands bare for metal-to-metal bond.
4. Braze tube before bake-out, after diffusion bonding.
5. Handle with gloves. No hydrocarbons on bond faces.

SCALE 20:1

1. MATL: Cu C1100 OFHC annealed, 1.0 sheet.
2. Flatness 0.02 over 68 x 68 after sintering.
3. Wick clearance holes keep post lands bare for metal-to-metal bond.
4. Braze tube before bake-out, after diffusion bonding.
5. Handle with gloves. No hydrocarbons on bond faces.

9:10:1

50:1

WICK SHOWN x4 THICKNESS FOR CLARITY

INSPECTION			
CHECK	REQUIREMENT	METHOD	
Flatness after sinter	0.02 max	CMM / optical flat	
Wick adhesion	no spall after 3 thermal cycles	visual 10x	
Post land bare area	Ø2.6 min clear	optical	
Braze joint	He leak < 1e-9 Pa.m3/s	mass spectrometer	

INDIA-VC THERMAL HARDWARE					ISO 128 / ISO 2768-mK	
TITLE CHAMBER LID Cu C1100 (OFHC) / 68 x 68 x 1.0 / WICK-LINED, FILL PORT			SCALE 2:1 THIRD ANGLE PROJECTION		UNITS mm	
DRAWING No. VC-102			REV A		SHEET 3 / 7	
DRAWN AI-ASSISTED DRAFT	CHECKED — PENDING —	MATERIAL SEE BOM	FINISH SEE NOTES		DATE 2026-09-09	