



(c) Reward

```
per 50 Hz step
  + 2.0 · progress toward target
  − 0.01 time penalty (be fast)
  + 0.05 · cos∠(camera axis, target)
  − small spin / stick-jerk penalties
  + 10 reached,  − 10 crash

episode ends on reach, crash
or 5 s timeout, so the
highest return = fastest
safe approach
```