PWM[ms]	Duty[%]	RPM	RPM2	Empuje [gr]	Empuje [N]	Rad/s	(Rad/s)^2
1	5	0	0	0	0	0	0
1,025	5,125	0	0	0	0	0	0
1,05	5,25	0	0	0	0	0	0
1,075	5,375	0	0	0	0	0	0
1,1	5,5	1380	1904400	0	0	144,5133	20884,08291
1,125	5,625	1680	2822400	0	0	175,9292	30951,0794
1,15	5,75	2050	4202500	0	0	214,6755	46085,56944
1,175	5,875	2280	5198400	12	0,1176	238,761	57006,83502
1,2	6	2525	6375625	15	0,147	264,4174	69916,55173
1,225	6,125	2786	7761796	35	0,343	291,7492	85117,61774
1,25	6,25	3020	9120400	60	0,588	316,2537	100016,3778
1,275	6,375	3250	10562500	76	0,7448	340,3392	115830,7739
1,3	6,5	3398	11546404	112	1,0976	355,8377	126620,4886
1,325	6,625	3678	13527684	129	1,2642	385,1593	148347,655
1,35	6,75	3905	15249025	150	1,47	408,9306	167224,2714
1,375	6,875	4180	17472400	171	1,6758	437,7286	191606,3066
1,4	7	4350	18922500	165	1,617	455,5309	207508,4325
1,425	7,125	4500	20250000	190	1,862	471,2389	222066,099
1,45	7,25	4690	21996100	250	2,45	491,1357	241214,2282
1,475	7,375	4970	24700900	300	2,94	520,4572	270875,6793
1,5	7,5	5263	27699169	381	3,7338	551,1401	303755,3781
1,525	7,625	5300	28090000	409	4,0082	555,0147	308041,3196
1,55	7,75	5390	29052100	426	4,1748	564,4395	318591,9267
1,575	7,875	5630	31696900	461	4,5178	589,5722	347595,4042
1,6	8	5805	33698025	550	5,39	607,8982	369540,1954
1,625	8,125	6030	36360900	572	5,6056	631,4601	398741,8874
1,65	8,25	6255	39125025	562	5,5076	655,0221	429053,9099
1,675	8,375	6455	41667025	623	6,1054	675,966	456930,0592
1,7	8,5	6590	43428100	641	6,2818	690,1032	476242,4077
1,725	8,625	6730	45292900	664	6,5072	704,764	496692,228
1,75	8,75	6880	47334400	712	6,9776	720,4719	519079,7806
1,775	8,875	7040	49561600	755	7,399	737,2271	543503,7617
1,8	9	7120	50694400	840	8,232	745,6047	555926,3037