PWM[ms]	Duty[%]	RPM	RPM2	Empuje [gr]	Empuje [N]	Rad/s	(Rad/s)^2
1	5	0	0	0	0	0	0
1,025	5,125	0	0	0	0	0	0
1,05	5,25	0	0	0	0	0	0
1,075	5,375	0	0	0	0	0	0
1,1	5,5	1400	1960000	0	0	146,6077	21493,80514
1,125	5,625	1724	2972176	0	0	180,5369	32593,55703
1,15	5,75	2045	4182025	0	0	214,1519	45861,03594
1,175	5,875	2313	5349969	20	0,196	242,2168	58668,9751
1,2	6	2554	6522916	24	0,2352	267,4543	71531,77829
1,225	6,125	2790	7784100	50	0,49	292,1681	85362,20847
1,25	6,25	3011	9066121	70	0,686	315,3112	99421,14191
1,275	6,375	3211	10310521	66	0,6468	336,2551	113067,5149
1,3	6,5	3408	11614464	75	0,735	356,8849	127366,85
1,325	6,625	3617	13082689	87	0,8526	378,7714	143467,7388
1,35	6,75	3818	14577124	92	0,9016	399,82	159856,0524
1,375	6,875	4042	16337764	158	1,5484	423,2773	179163,6305
1,4	7	4221	17816841	180	1,764	442,0221	195383,5248
1,425	7,125	4450	19802500	229	2,2442	466,0029	217158,7124
1,45	7,25	4647	21594609	249	2,4402	486,6327	236811,3867
1,475	7,375	4818	23213124	257	2,5186	504,5398	254560,3898
1,5	7,5	5011	25110121	327	3,2046	524,7507	275363,2897
1,525	7,625	5186	26894596	353	3,4594	543,0767	294932,2478
1,55	7,75	5352	28643904	380	3,724	560,4601	314115,5566
1,575	7,875	5521	30481441	410	4,018	578,1578	334266,4047
1,6	8	5710	32604100	428	4,1944	597,9498	357543,9654
1,625	8,125	5930	35164900	460	4,508	620,9881	385626,2798
1,65	8,25	6107	37295449	530	5,194	639,5235	408990,364
1,675	8,375	6213	38601369	524	5,1352	650,6238	423311,3793
1,7	8,5	6409	41075281	557	5,4586	671,1489	450440,8601
1,725	8,625	6518	42484324	613	6,0074	682,5634	465892,7457
1,75	8,75	6655	44289025	633	6,2034	696,91	485683,5067
1,775	8,875	6760	45697600	666	6,5268	707,9055	501130,2601
1,8	9	6890	47472100	720	7,056	721,5191	520589,8301