


4.4.2 Special case: n uncorrelated observations, 1 unknown value

$$\Sigma_{LLn \times n} = \begin{bmatrix} \sigma_{l_1}^2 & & & 0 \\ & \sigma_{l_2}^2 & & \\ & & \ddots & \\ 0 & & & \sigma_{l_n}^2 \end{bmatrix}$$

$$x = \Phi(\mathbf{l}) = \varphi(l_1, l_2, \dots, l_n)$$



$$c = \sqrt{a^2 + b^2 - 2ab \cos \alpha}$$

$$\sum_{LL} =$$

$$f(a, b, c, \alpha)$$

► Step 1:

Set up the functional model for one functional relation $\Phi(\mathbf{l})$ with n observations (measurements) l_i

$$x = \Phi(\mathbf{l}) = \varphi(l_1, l_2, \dots, l_n)$$

4.4.2 Special case: n uncorrelated observations, 1 unknown value

► Step 2: Set up the stochastic model for n uncorrelated observations

$$\Sigma_{LL} = \begin{bmatrix} \sigma_{l_1}^2 & & & 0 \\ & \sigma_{l_2}^2 & & \\ & & \ddots & \\ 0 & & & \sigma_{l_n}^2 \end{bmatrix}$$

Question: Functional model linear or nonlinear?

- if functional model linear, design matrix \mathbf{F} directly given
- if functional model nonlinear, proceed with step 3

► Step 3: Linearisation of the functional model

→ computation of partial derivatives $\frac{\partial \varphi}{\partial l_i} \quad i = 1, 2, \dots, n$

$$\mathbf{J}_{1 \times n} = \left[\frac{\partial \varphi}{\partial l_1} \quad \frac{\partial \varphi}{\partial l_2} \quad \frac{\partial \varphi}{\partial l_3} \quad \cdots \quad \frac{\partial \varphi}{\partial l_n} \right]$$

→ Insert elements of \mathbf{J} into matrix \mathbf{F}

4.4.2 Special case: n uncorrelated observations, 1 unknown value

► Step 4: Computation of „VCM“ for the unknowns

$$\Sigma_{xx} \underset{1 \times 1}{=} \left[\frac{\partial \varphi}{\partial l_1} \quad \frac{\partial \varphi}{\partial l_2} \quad \frac{\partial \varphi}{\partial l_3} \quad \dots \quad \frac{\partial \varphi}{\partial l_n} \right]_{1 \times n} \begin{bmatrix} \sigma_{l_1}^2 & & & & \\ & \sigma_{l_2}^2 & & & \\ & & \ddots & & \\ & & & 0 & \\ & & & & \sigma_{l_n}^2 \end{bmatrix}_{n \times n} \begin{bmatrix} \frac{\partial \varphi}{\partial l_1} \\ \frac{\partial \varphi}{\partial l_2} \\ \vdots \\ \frac{\partial \varphi}{\partial l_n} \end{bmatrix}_{n \times 1}$$

Σ_{ll}

- Theoretical variance:

$$\sigma_x^2 = \left(\frac{\partial \varphi}{\partial l_1} \right)^2 \cdot \sigma_{l_1}^2 + \left(\frac{\partial \varphi}{\partial l_2} \right)^2 \cdot \sigma_{l_2}^2 + \dots + \left(\frac{\partial \varphi}{\partial l_n} \right)^2 \cdot \sigma_{l_n}^2$$

- Empirical variance:

$$s_x^2 = \left(\frac{\partial \varphi}{\partial l_1} \right)^2 \cdot s_{l_1}^2 + \left(\frac{\partial \varphi}{\partial l_2} \right)^2 \cdot s_{l_2}^2 + \dots + \left(\frac{\partial \varphi}{\partial l_n} \right)^2 \cdot s_{l_n}^2$$

Variance propagation for uncorrelated observations

4.4.2 Special case: n uncorrelated observations, 1 unknown value

- Theoretical standard deviation:

$$\sigma_x = \sqrt{\sigma_x^2}$$

- Empirical standard deviation:

$$s_x = \sqrt{s_x^2}$$

→ σ_x respective s_x can easily be computed without applying matrix calculus

Please note: General case includes the special case, but the special case does not include the general case.

4.4.3 Variance – Covariance propagation: Some examples

Example 1:

- ▶ Angles α and β have been measured with a standard deviation of

$$s_\alpha = s_\beta = 1 \text{ mgon}$$


- ▶ Compute the standard deviation s_γ

- ▶ General or special case?

- ▶ Step 1: Functional model $\gamma = 200 \text{ gon} - \alpha - \beta$

Special

$$\gamma = [-1 \quad -1] \begin{bmatrix} \alpha \\ \beta \end{bmatrix} + 200 \text{ gon}$$
$$\begin{matrix} \alpha & \beta \\ f_{11} & f_{12} \end{matrix} \quad \begin{bmatrix} \alpha \\ \beta \end{bmatrix} \quad 200 \text{ gon}$$
$$\mathbf{f} \quad \mathbf{F} \quad \mathbf{l}$$



4.4.3 Variance – Covariance propagation: Some examples

► Step 2: Stochastic model

$$\mathbf{S}_{LL} = \begin{bmatrix} (1 \text{ mgon})^2 & 0 \\ 0 & (1 \text{ mgon})^2 \end{bmatrix}$$

► Steps 3 and 4:

$$s_\gamma^2 = (f_{11})^2 \cdot s_\alpha^2 + (f_{12})^2 \cdot s_\beta^2$$

with $f_{11} = -1$ and $f_{12} = -1$

$$\Rightarrow s_\gamma^2 = 1 \cdot (1 \text{ mgon})^2 + 1 \cdot (1 \text{ mgon})^2$$


$$s_\gamma = \sqrt{2} \text{ mgon}$$

$$s_\gamma = 1.41 \text{ mgon}$$

4.4.3 Variance – Covariance propagation: Some examples

Example 2:

- ▶ Given: $b = 20.29 \text{ m}$, $s_b = 1.0 \text{ cm}$
 $c = 75.75 \text{ m}$, $s_c = 2.0 \text{ cm}$
 $\alpha = 27.292 \text{ gon}$, $s_\alpha = 0.015 \text{ gon}$



- ▶ Wanted:

Special case a, s_a
 ↑ ↗
 1 STD
General or special case? *unknown*

- ▶ Step 1: Functional model

$$a = \sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha} \rightarrow \text{non-linear}$$

4.4.3 Variance – Covariance propagation: Some examples

► Step 2: Stochastic model

$$a = \sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}$$

$$\sigma_a^2 = \left(\frac{\partial a}{\partial b} \right)^2 \cdot \sigma_b^2 + \left(\frac{\partial a}{\partial c} \right)^2 \cdot \sigma_c^2 + \left(\frac{\partial a}{\partial \alpha} \right)^2 \cdot \sigma_\alpha^2$$

$$\frac{\partial a}{\partial b} = \frac{1}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}} \cdot (2b - 2c \cdot \cos \alpha) = \frac{b - c \cdot \cos \alpha}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}}$$

$$\frac{\partial a}{\partial c} = \frac{1}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}} \cdot (2c - 2b \cdot \cos \alpha) = \frac{c - b \cdot \cos \alpha}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}} = \frac{c - b \cos \alpha}{a}$$

$$\frac{\partial a}{\partial \alpha} = \frac{1}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}} \cdot (b c \cdot \sin \alpha) = \frac{b c \cdot \sin \alpha}{\sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}} = \frac{b c \cdot \sin \alpha}{a}$$

$$\sigma_a^2 = \left(\frac{b - c \cdot \cos \alpha}{a} \right)^2 \cdot \sigma_b^2 +$$

$$\left(\frac{c - b \cdot \cos \alpha}{a} \right)^2 \cdot \sigma_c^2 +$$

$$\left(\frac{b c \cdot \sin \alpha}{a} \right)^2 \cdot \sigma_\alpha^2 \Rightarrow \sigma_a^2 = 0.022 \text{ m}$$

- Attention: Units must coincide!

- Solution: Choose [m] and [rad] in \mathbf{S}_{LL}

— Connect everything
to m & gon

$$\begin{bmatrix} 0 \\ 0 \\ (s_\alpha)^2 \end{bmatrix} = \begin{bmatrix} (0.01)^2 & & 0 \\ & (0.02)^2 & \\ 0 & & \left(\frac{0.015}{\rho}\right)^2 \end{bmatrix}$$

$$\text{with } \rho = \frac{200}{\pi}$$

Radius = $2\pi r = 900 \text{ gon} \cdot 360^\circ = \text{full circle}$

$$= 360^\circ$$

4.4.3 Variance – Covariance propagation: Some examples

$$a = \sqrt{b^2 + c^2 - 2bc \cdot \cos \alpha}$$

► Steps 3 and 4:

$$s_a^2 = \left(\frac{\partial a}{\partial b} \right)^2 \cdot (s_b)^2 + \left(\frac{\partial a}{\partial c} \right)^2 \cdot (s_c)^2 + \left(\frac{\partial a}{\partial \alpha} \right)^2 \cdot (s_\alpha)^2$$

with:

$$\frac{\partial a}{\partial b} = \frac{1}{2\sqrt{}} \cdot (2b - 2c \cdot \cos \alpha) = \frac{b - c \cdot \cos \alpha}{\sqrt{}} = \frac{b - c \cdot \cos \alpha}{a}$$

$$\frac{\partial a}{\partial c} = \frac{1}{2\sqrt{}} \cdot (2c - 2b \cdot \cos \alpha) = \frac{c - b \cdot \cos \alpha}{a}$$

$$\frac{\partial a}{\partial \alpha} = \frac{1}{2\sqrt{}} \cdot (2bc \cdot \sin \alpha) = \frac{bc \cdot \sin \alpha}{\sqrt{}} = \frac{bc \cdot \sin \alpha}{a}$$

$$s_a^2 = \left(\frac{b - c \cdot \cos \alpha}{a} \right)^2 \cdot (s_b)^2 + \left(\frac{c - b \cdot \cos \alpha}{a} \right)^2 \cdot (s_c)^2 + \left(\frac{bc \cdot \sin \alpha}{a} \right)^2 \cdot (s_\alpha)^2$$

$$\Rightarrow s_a = 0.022 \text{ m}$$

4.4.3 Variance – Covariance propagation: Some examples

Example 3: Computation of Cartesian Coordinates

$$Y_p = Y_s + d \cdot \sin t$$

$$X_p = X_s + d \cdot \cos t$$

► Given:

$Y_s = 1000.000 \text{ m}$, $X_s = 1000.000 \text{ m}$
fixed values (error-free)

$t = 77.1234 \text{ gon}$, $\sigma_t = 3.0 \text{ mgon} \approx 1 \text{ radian}$


$d = 987.654 \text{ m}$, $\sigma_d = 20.0 \text{ mm} \approx 0.0002 \text{ radian}$

► Wanted:

Y_p , X_p and σ_{Y_p} , σ_{X_p} and ρ_{Y_p, X_p}

► General or special case?

More than 1 unknown = general case



4.4.3 Variance – Covariance propagation: Some examples

► Step 1: Functional model

$$\begin{bmatrix} Y_p \\ X_p \end{bmatrix} = \begin{bmatrix} \Phi_1(\mathbf{l}) \\ \Phi_2(\mathbf{l}) \end{bmatrix} = \begin{bmatrix} \varphi_1(d, t) \\ \varphi_2(d, t) \end{bmatrix}$$

$$\begin{bmatrix} Y_p \\ X_p \end{bmatrix} = \begin{bmatrix} Y_s + d \cdot \sin t \\ X_s + d \cdot \cos t \end{bmatrix} = \begin{bmatrix} 1924.5700 \text{ m} \\ 1347.3193 \text{ m} \end{bmatrix}$$


► Step 2:

- Observation vector

$$\mathbf{l} = \begin{bmatrix} d \\ t \end{bmatrix} = \begin{bmatrix} 987.654 \text{ m} \\ 77.1234 \text{ gon} \end{bmatrix}$$

- Stochastic model

$$\Sigma_{LL} = \begin{bmatrix} (\sigma_a)^2 & 0 \\ 0 & (\sigma_t)^2 \end{bmatrix} = \begin{bmatrix} (0.02)^2 & 0 \\ 0 & \left(\frac{0.003}{\rho}\right)^2 \end{bmatrix}$$



$$J = \begin{bmatrix} d & t \\ Y_p & X_p \end{bmatrix} \begin{bmatrix} \frac{\partial y_p}{\partial a} & \frac{\partial y_p}{\partial t} \\ \frac{\partial x_p}{\partial a} & \frac{\partial x_p}{\partial t} \end{bmatrix}$$

$$\begin{bmatrix} \sin t & d \cdot \cos t \\ \cos t & -d \cdot \sin t \end{bmatrix}$$

F

4.4.3 Variance – Covariance propagation: Some examples

- ▶ Step 3: Linearisation, computation of partial derivatives

$$\frac{\partial Y_P}{\partial d} = \sin t ; \quad \frac{\partial Y_P}{\partial t} = d \cdot \cos t$$

$$\begin{bmatrix} Y_P \\ X_P \end{bmatrix} = \begin{bmatrix} Y_S + d \cdot \sin t \\ X_S + d \cdot \cos t \end{bmatrix}$$

$$\frac{\partial X_P}{\partial d} = \cos t; \quad \frac{\partial X_P}{\partial t} = -d \cdot \sin t$$

Design matrix $\mathbf{F} = \mathbf{J}$:

$$\mathbf{J} = \begin{bmatrix} d & t \\ Y_P & \begin{bmatrix} \frac{\partial Y_P}{\partial d} & \frac{\partial Y_P}{\partial t} \\ \frac{\partial X_P}{\partial d} & \frac{\partial X_P}{\partial t} \end{bmatrix} \\ X_P & \end{bmatrix} = \begin{bmatrix} \sin t & d \cdot \cos t \\ \cos t & -d \cdot \sin t \end{bmatrix}$$

4.4.3 Variance – Covariance propagation: Some examples

► Step 4: VCM of the unknowns

$$\Sigma_{xx} = \mathbf{F} \cdot \Sigma_{LL} \cdot \mathbf{F}^T$$

...

$$\Sigma_{xx} = \begin{bmatrix} 618.4138 & -581.4212 \\ -581.4212 & 1947.7531 \end{bmatrix} [\text{mm}^2]$$

$$\sigma_{Y_P} = \sqrt{618.4138} = 24.8679 \text{ mm}$$

$$\sigma_{X_P} = \sqrt{1947.7531} = 44.1334 \text{ mm}$$

$$\rho_{Y_P, X_P} = \frac{-581.4212}{24.8679 \cdot 44.1334} = -0.53$$

← correlation
between Y & X

4.4.4 Variance – Covariance propagation for complex functional relationships

Example: Resection


► Given:

- Coordinates of points A, M, B as fixed values (error-free)
- Measurements: Horizontal directions $r_{N,A}, r_{N,M}, r_{N,B}$ with their standard deviations $\sigma_{r_{N,A}}, \sigma_{r_{N,M}}, \sigma_{r_{N,B}}$

► Wanted:

- Coordinates Y_N, X_N
- Standard deviations $\sigma_{Y_N}, \sigma_{X_N}$
- Correlation ρ_{Y_N, X_N}

$$\begin{aligned} Y_N &= Y_M + s \cdot \sin t_{M,N} \\ X_N &= X_M + s \cdot \cos t_{M,N} \end{aligned} \quad \begin{array}{l} \text{general} \\ \text{approach} \end{array}$$



4.4.4 Variance – Covariance propagation for complex functional relationships

► Functional relationships:

$$1. \alpha = r_{N,M} - r_{N,A}$$

$$2. \beta = r_{N,B} - r_{N,M}$$

$$3. \varepsilon = 2\pi - \alpha - \beta - (\mu) \text{— computed from coordinates} \\ (\varepsilon = \gamma + \delta)$$

$$4. a_1 = \frac{\sin \alpha}{\textcircled{a}}$$

$$5. a_2 = \frac{\sin \beta}{\textcircled{b}} \quad \text{distances computed from coordinates}$$

$$6. \gamma = \arctan \frac{a_1 \cdot \sin \varepsilon}{a_2 + a_1 \cdot \cos \varepsilon}$$


$$7. s = \frac{\sin \gamma}{a_1} \quad \text{computed from coordinates}$$

$$8. t_{M,N} = \textcircled{t_{M,A}} - \pi + \alpha + \gamma \quad (t_{M,N} = t_{M,A} - \omega)$$

$$9. Y_N = Y_M + s \cdot \sin t_{M,N}$$

$$10. X_N = X_M + s \cdot \cos t_{M,N}$$

Computation of Cartesian Coordinates



4.4.4 Variance – Covariance propagation for complex functional relationships


- ▶ Question: How can we compute σ_{Y_N} , σ_{X_N} ?
- ▶ First idea: Insert formulas into one another to obtain a formula for Y_N resp. X_N that depends only on the original measurements $r_{N,A}$, $r_{N,M}$, $r_{N,B}$
- ▶ We obtain:
$$Y_N = \varphi_1(r_{N,A}, r_{N,M}, r_{N,B})$$
$$X_N = \varphi_2(r_{N,A}, r_{N,M}, r_{N,B})$$
- ▶ Problem 1: We obtain very complicated equations, very complex part. derivatives
- ▶ Problem 2: Y_N, X_N are correlated! If we want to use Y_N, X_N for further computation, we need the full VCM → We have to apply the general case of VC propagation
- ▶ Solution: We keep the decomposition in partial steps and apply chain rule of matrix multiplication

Remark: If (and only if) we are only interested in σ_{Y_N} , σ_{X_N} and not in the correlation ρ_{Y_N, X_N} we can compute σ_{Y_N} , σ_{X_N} separately by applying the special case two times

4.4.4 Variance – Covariance propagation for complex functional relationships

We have to consider ten functional relationships

Flowchart



VC propagation: $\Sigma_{xx} = \mathbf{F} \cdot \Sigma_{LL} \cdot \mathbf{F}^T$


with $\mathbf{F} = \mathbf{F}_k \cdot \mathbf{F}_{k-1} \cdot \mathbf{F}_{k-2} \cdots \cdots \cdot \mathbf{F}_1$

in our example $\mathbf{F} = \mathbf{F}_5 \cdot \mathbf{F}_4 \cdot \mathbf{F}_3 \cdot \mathbf{F}_2 \cdot \mathbf{F}_1$

4.4.4 Variance – Covariance propagation for complex functional relationships

\mathbf{F}_1 :

- Functional model:



- Design matrix:

$$\begin{aligned}\alpha &= r_{N,M} - r_{N,A} \\ \beta &= r_{N,B} - r_{N,M}\end{aligned}$$

written 1st coefficient

$$\mathbf{F}_1 = \begin{bmatrix} \alpha & r_{N,M} & r_{N,A} & r_{N,B} \\ \beta & 1 & -1 & 0 \\ & -1 & 0 & 1 \end{bmatrix}$$


↑

*New
observation*

4.4.4 Variance – Covariance propagation for complex functional relationships

\mathbf{F}_2 :

- Functional model:



$$\alpha = \alpha \quad (\alpha \text{ needed for further computation})$$

→ we have to introduce "identity equation"

$$\varepsilon = 2\pi - \alpha - \beta - \mu$$

$$a_1 = \frac{\sin \alpha}{a}$$

$$a_2 = \frac{\sin \beta}{b}$$

- Design matrix:


$$\mathbf{F}_2 = \begin{bmatrix} \alpha & \beta \\ \alpha & 1 & 0 \\ \varepsilon & -1 & -1 \\ a_1 & \frac{\cos \alpha}{a} & 0 \\ a_2 & 0 & \frac{\cos \beta}{b} \end{bmatrix}$$

↑ New observations

4.4.4 Variance – Covariance propagation for complex functional relationships

\mathbf{F}_3 :

- Functional model:



$$\alpha = \alpha$$

$$a_1 = a_1$$

$$\gamma = \arctan \frac{a_1 \cdot \sin \varepsilon}{a_2 + a_1 \cdot \cos \varepsilon} = \text{Partiel der}$$

- Design matrix:


$$\mathbf{F}_3 = \begin{bmatrix} \alpha & \varepsilon & a_1 & a_2 \\ \hline 1 & 0 & 0 & 0 \\ a_1 & 0 & 1 & 0 \\ \gamma & \frac{\partial \gamma}{\partial \varepsilon} & \frac{\partial \gamma}{\partial a_1} & \frac{\partial \gamma}{\partial a_2} \end{bmatrix}$$

Neu oben *Bronnen XOXO*

4.4.4 Variance – Covariance propagation for complex functional relationships

F₄:

- Functional model:



$$s = \frac{\sin \gamma}{a_1}$$

$$t_{M,N} = t_{M,A} - \pi + \alpha + \gamma$$

- Design matrix:


$$\mathbf{F}_4 = \begin{bmatrix} \alpha & a_1 & \gamma \\ s & 0 & -\frac{\sin \gamma}{(a_1)^2} & \frac{\cos \gamma}{a_1} \\ t_{M,N} & 1 & 0 & 1 \end{bmatrix}$$

\mathcal{T}
New order

4.4.4 Variance – Covariance propagation for complex functional relationships

F₅:

- Functional model:



$$Y_N = Y_M + s \cdot \sin t_{M,N}$$

$$X_N = X_M + s \cdot \cos t_{M,N}$$

- Design matrix:

$$\mathbf{F}_5 = \begin{bmatrix} s & t_{M,N} \\ Y_N & \begin{bmatrix} \sin t_{M,N} & s \cdot \cos t_{M,N} \\ \cos t_{M,N} & -s \cdot \sin t_{M,N} \end{bmatrix} \\ X_N & \end{bmatrix}$$

4.4.4 Variance – Covariance propagation for complex functional relationships

VC propagation:

$$\mathbf{F} = \mathbf{F}_5 \cdot \mathbf{F}_4 \cdot \mathbf{F}_3 \cdot \mathbf{F}_2 \cdot \mathbf{F}_1$$

$$\boldsymbol{\Sigma}_{xx} = \mathbf{F} \cdot \boldsymbol{\Sigma}_{LL} \cdot \mathbf{F}^T$$

with $\boldsymbol{\Sigma}_{LL} = \begin{bmatrix} (\sigma_{r_{N,M}})^2 & 0 & 0 \\ 0 & (\sigma_{r_{N,A}})^2 & 0 \\ 0 & 0 & (\sigma_{r_{N,B}})^2 \end{bmatrix}$

→ Attention: Same order as columns in \mathbf{F}_1

Result:

$$\boldsymbol{\Sigma}_{xx \ 2 \times 2} = \begin{bmatrix} (\sigma_{Y_N})^2 & \text{Cov}(Y_N, X_N) \\ \text{Cov}(X_N, Y_N) & (\sigma_{X_N})^2 \end{bmatrix}$$

Correlation: $\rho_{Y_N, X_N} = \frac{\text{Cov}(Y_N, X_N)}{\sigma_{Y_N} \cdot \sigma_{X_N}}$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Scaling of an observation with a constant factor

- ▶ Given: measurement l , standard deviation s_l

- ▶ Functional model:

$$f(l) = \underbrace{a \cdot l}_{\text{factor?}} \quad \text{with} \quad a = \text{const.}$$

- ▶ Coefficient:

$$f_l = a$$

- ▶ VC propagation:

$$s_f^2 = f_l^2 \cdot s_l^2 \Rightarrow s_f^2 = a^2 \cdot s_l^2$$

$$\text{Standard deviation} \quad s_f = \sqrt{s_f^2} \Rightarrow s_f = a \cdot s_l$$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Addition or subtraction of observations

► Given:

n uncorrelated measurements l_1, l_2, \dots, l_n with their standard deviations $s_{l_1}, s_{l_2}, \dots, s_{l_n}$

► Functional model:

$$f(l_1, l_2, \dots, l_n) = l_1 \pm l_2 \pm \dots \pm l_n$$

► Coefficients: *Factors are ± 1*

$$f_{l_1} = +1, \quad f_{l_2} = \pm 1, \quad \dots, \quad f_{l_n} = \pm 1$$

► VC propagation:

$$s_f^2 = s_{l_1}^2 + s_{l_2}^2 + \dots + s_{l_n}^2 \quad (\text{for addition and subtraction!})$$

Standard deviation

$$s_f = \sqrt{s_{l_1}^2 + s_{l_2}^2 + \dots + s_{l_n}^2}$$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

► In the case that all observations have the same precision

→ Same standard deviation s_l for all observations l_i

$$s_l = s_{l_1} = s_{l_2} = \dots = s_{l_n}$$

→ Standard deviation

$$s_f = \sqrt{s_l^2 + s_l^2 + \dots + s_l^2}$$

$$s_f = \sqrt{n \cdot s_l^2}$$



$$s_f = \sqrt{n} \cdot s_l$$

Rule: Standard deviation grows with the square root if the number of summands.


4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Example:

practical application

► Given:

- Horizontal directions r_1, r_2 (observations)
- Standard deviations $s_{r_1} = 1 \text{ mgon}, s_{r_2} = 1 \text{ mgon}$



► Wanted:

- Horizontal angle α
- Standard deviation s_α

► Solution:

$$s_\alpha = \sqrt{2} \cdot 1 \text{ mgon}$$
$$s_\alpha = 1.41 \text{ mgon}$$

Prüfungsfall

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Arithmetic mean of observations

► Given:

- n uncorrelated measurements l_1, l_2, \dots, l_n
- Standard deviations $s_{l_1}, s_{l_2}, \dots, s_{l_n}$

► Functional model:

$$\bar{x} = f(l_1, l_2, \dots, l_n) = \frac{l_1 + l_2 + \dots + l_n}{n} = \frac{1}{n}l_1 + \frac{1}{n}l_2 + \dots + \frac{1}{n}l_n$$

► Coefficients:

$$f_{l_1} = \frac{1}{n} , \quad f_{l_2} = \frac{1}{n} , \quad \dots, \quad f_{l_n} = \frac{1}{n}$$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

► VC propagation:

$$s_{\bar{x}}^2 = \left(\frac{1}{n}\right)^2 s_{l_1}^2 + \left(\frac{1}{n}\right)^2 s_{l_2}^2 + \cdots + \left(\frac{1}{n}\right)^2 s_{l_n}^2 = \frac{1}{n^2} (s_{l_1}^2 + s_{l_2}^2 + \cdots + s_{l_n}^2)$$

In the case that all observations have the same precision
→ same standard deviations s_l for all observations l_i

$$\begin{aligned}s_l &= s_{l_1} = s_{l_2} = \cdots = s_{l_n} \\ s_{\bar{x}}^2 &= \frac{1}{n^2} (s_l^2 + s_l^2 + \cdots + s_l^2) \\ s_{\bar{x}}^2 &= \frac{1}{n^2} \cdot n \cdot s_l^2\end{aligned}$$

Standard deviation $s_{\bar{x}} = \frac{s_l}{\sqrt{n}}$


Rule: If we perform measurements for the same random variable n times,
the standard deviation for the arithmetic mean decreases by the factor $1/\sqrt{n}$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Example:

► Given:

- Distance $A - B$ has been measured 10 times
- Standard deviation $s_l = 1 \text{ cm}$



► Wanted:

- Standard deviation of the arithmetic mean

$$s_{\bar{x}} = 1 \text{ cm} \cdot \frac{1}{\sqrt{10}}$$
$$s_{\bar{x}} = 3.16 \text{ mm}$$

+1000 often
do we have
to measure
to get
 $s_{\bar{x}} = 2 \text{ mm}$
 $s_l = 10 \text{ mm} = 1 \text{ cm}$
 $s_{\bar{x}} = s_p \cdot \sqrt{n}$
 $s_{\bar{x}} = 10 \text{ mm} \cdot \frac{1}{\sqrt{10}} = 3.16 \text{ mm}$


$$\sqrt{n} \cdot 2 \text{ mm} = 10 \text{ mm} \quad 1: 2 \text{ mm}$$

$$\sqrt{n} = \frac{10 \text{ mm}}{2 \text{ mm}} = 5 = 25 = n$$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Some more remarks:

- ▶
$$\begin{aligned} Y_P &= Y_s + d \cdot \sin t \\ X_P &= X_s + d \cdot \cos t \end{aligned}$$
 General case, because we have two correlated unknowns



- ▶ If (and only if) we are interested in s_{Y_P} , s_{X_P} and not in the correlation r_{Y_P, X_P} , we can compute s_{Y_P} , s_{X_P} separately by applying the special case two times:

$$s_{Y_P}^2 = \left(\frac{\partial Y_P}{\partial d} \right)^2 \cdot s_d^2 + \left(\frac{\partial Y_P}{\partial t} \right)^2 \cdot s_t^2$$

$$s_{X_P}^2 = \left(\frac{\partial X_P}{\partial d} \right)^2 \cdot s_d^2 + \left(\frac{\partial X_P}{\partial t} \right)^2 \cdot s_t^2$$

- ▶ But: If we use our results (here Y_P, X_P) for further computations, we must consider the covariances and therefore apply the general case of VC propagation

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

Example:

► Given:

- Horizontal directions r_1, r_2, r_3, r_4 (observations)
- Standard deviations $\sigma_{r_1} = \sigma_{r_2} = \sigma_{r_3} = \sigma_{r_4} = 0.5$ mgon

► Wanted:


- Horizontal angles α, β, γ
- Standard deviations $\sigma_\alpha, \sigma_\beta, \sigma_\gamma$

► If we are only interested in $\sigma_\alpha, \sigma_\beta, \sigma_\gamma$ as a final result, we can apply the special case of VC propagation:

$$\alpha = r_2 - r_1 \Rightarrow \sigma_\alpha = \sqrt{2} \cdot 0.5 \text{ mgon} = 0.71 \text{ mgon}$$

$$\beta = r_3 - r_1 \Rightarrow \sigma_\beta = 0.71 \text{ mgon}$$

$$\gamma = r_4 - r_1 \Rightarrow \sigma_\gamma = 0.71 \text{ mgon}$$



4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

► If we want to use α, β, γ for further computation (which usually is the case), we have to apply the general case of VC propagation:

- Step 1: Functional model

$$\mathbf{X} = \begin{bmatrix} \alpha \\ \beta \\ \gamma \end{bmatrix} = \begin{bmatrix} \Phi_1(\mathbf{l}) \\ \Phi_2(\mathbf{l}) \\ \Phi_3(\mathbf{l}) \end{bmatrix} = \begin{bmatrix} r_2 - r_1 \\ r_3 - r_1 \\ r_4 - r_1 \end{bmatrix}$$

- Step 2: Observation vector and stochastic model

$$\mathbf{l} = \begin{bmatrix} r_1 \\ r_2 \\ r_3 \\ r_4 \end{bmatrix}, \quad \boldsymbol{\Sigma}_{LL} = \begin{bmatrix} 0.5^2 & & & 0 \\ & 0.5^2 & & \\ & & 0.5^2 & \\ 0 & & & 0.5^2 \end{bmatrix}$$

4.4.5 Variance – Covariance propagation: Standard cases that often occur in practice

- Step 3: Design matrix (coefficients of the linear functional model)

$$\mathbf{F} = \begin{matrix} & r_1 & r_2 & r_3 & r_4 \\ \alpha & -1 & 1 & 0 & 0 \\ \beta & -1 & 0 & 1 & 0 \\ \gamma & -1 & 0 & 0 & 1 \end{matrix}$$


- Step 4: VCM of the unknowns

$$\Sigma_{xx} = \mathbf{F} \cdot \Sigma_{LL} \cdot \mathbf{F}^T = \begin{bmatrix} 0.50 & 0.25 & 0.25 \\ 0.25 & 0.50 & 0.25 \\ 0.25 & 0.25 & 0.50 \end{bmatrix}$$

*← Covaried
and correlated*

Complete matrix Σ_{xx} must be considered for further computations!

Standard deviations: $\sigma_\alpha = \sigma_\beta = \sigma_\gamma = \sqrt{0.5} = 0.71$ mgon



Copyright notice:

This provided digital course material is protected by International copyright laws. All rights reserved.

Any reproduction and redistribution of the material without written permission is prohibited other than the following:
You may print or download to a local hard disk extracts for your personal use only while attending the Geodesy and Geoinformation Science master's programme.

You may not distribute or commercially exploit the content.
You may not transmit it or store it in any other website.

Adjustment Theory I

Chapter 4 – Propagation of Observation Errors

Prof. Dr.-Ing. Frank Neitzel | Institute of Geodesy and Geoinformation Science