FROM POWER SOURCE SYSTEM (SEE PAGE 134) 10A GAUGE J18 (LHD) , J35 (RHD) JUNCTION CONNECTOR R-L J 1 (LHD) , J25 (RHD) JUNCTION CONNECTOR В В J20 (LHD) , J43 (RHD) JUNCTION CONNECTOR  $\mathbb{F}$ R-B R-B N 1 BACK-UP LIGHT SW [NEUTRAL START SW] R-B R-B1 IC3 R12 BACK-UP LIGHT RH [REAR COMB. LIGHT RH] R10 BACK-UP LIGHT LH [REAR COMB. LIGHT LH] J3 (A), J4 (B) (LHD) , J27 (A), J28 (B) (RHD) JUNCTION CONNECTOR R–B J21 (LHD) , J44 (RHD) JUNCTION CONNECTOR W-B