PROBLEM SYMPTOMS TABLE

POWER MIRROR CONTROL SYSTEM

Symptom	Suspect Area	See page
Mirror retract system does not operate	Retract motor circuit Pssenger door ECU	DI-686

DI2EW-08