
## 30 CD magazine inserted, but no power.



5	Is power supplied to ACC terminal of CD auto changer?
	NO Radio receiver assembly faulty.
YES	

CD auto changer faulty.