PROBLEM SYMPTOMS TABLE

Power Mirror Control System:

Symptom	Suspect Area	See page
Mirror retract system does not operate (G.C.C countries)	1. Mirror retract motor circuit	DI-656
	2. Driver door ECU	IN-30

DI2BL-11