
■ FUEL FILLER CAP

A tether has been provided on the fuel filler cap to prevent the cap from being lost.



188IN07