
MULTIPLEX COMMUNICATION SYSTEM HOW TO PROCEED WITH TROUBLESHOOTING

DI2AT-12

Perform troubleshooting in accordance with the procedure on the following page.



★: LEXUS GS300 Repair Mamual Pub. No. RM588E

Step: Diagnostic: teps: permitting: he use of the LEXUS hand-held tester.