



- 1.未标注倒角 $1\times 45^\circ$.
- 2.调制处理 $24\sim 28\text{HRC}$.

传动机械厂