





## 7강\_PwmOut

- PwmOut 클래스



## 7-1. PwmOut 클래스



PwmOut Class Reference	
Public Me	ember Functions
	PwmOut (PinName pin)
	Create a PwmOut connected to the specified pin. More
	PwmOut (const PinMap &pinmap)
	Create a PwmOut connected to the specified pin. More
void	write (float value)
	Set the output duty-cycle, specified as a percentage (float) More
float	read ()
	Return the current output duty-cycle setting, measured as a percentage (float) More



