Laser laboratory qualification - historical edition

ARCHIVED 2024; superseded

ARCHIVED, SUPERSEDED: this 2024 edition is retained for historical record only and is not the current operating policy.

The retired 2024 qualification rule assigned a twelve-month laser practical renewal period.

The old edition covered the same operating activity. Its prior timing must not be treated as a forecast. Historic case records show how approvals were documented at the time; they do not authorise new work under that edition.

Laser laboratory qualification - historical edition

ARCHIVED 2024; superseded

Historical route register. These entries are examples of administrative queues in the retired edition, not current forms.

Registry LAS-448: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAS-459: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAS-470: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAS-481: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAS-492: record the request in the pending owner-verification queue; this entry is not the named exception route.