Process water sampling - operating guide

CURRENT 2026; effective 1 August 2026

Scope: Utilities laboratory and sample-chain custody. This is fictional Meridian Works guidance. The following responsibilities apply only to the named activity, not to other procedures with similar labels.

A water sample with an incomplete chain of custody is rejected for release testing even if the bottle seal is intact.

LAB-357 requests the conductivity confirmation panel; LAB-375 requests the endotoxin trend panel.

The coordinator records what actually happened, identifies the responsible owner and checks the applicable route. A similarly numbered form is not interchangeable with the recorded form. For a rejected submission, retain the original request and obtain corrected evidence rather than creating a replacement event.

Registry LAB-458: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-469: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-480: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-491: record the request in the pending owner-verification queue; this entry is not the named exception route.

Process water sampling - operating guide

CURRENT 2026; effective 1 August 2026

Eligibility and operational limits. Select the named cohort and activity before applying a period or amount; different entitlements in this section are not substitutes.

Microbiological water samples have a six-hour holding time; conductivity samples permit twenty-four hours.

A microbiological sample is transported between 2 and 8 degrees Celsius and must not be frozen.

A valid request contains its underlying event date and the scope used for the calculation. Reviewers distinguish acknowledgement, completion and storage periods. A deadline for submitting evidence is not a service restoration promise. If the activity or group is not stated, escalate the question rather than borrowing a nearby rule.

Registry LAB-502: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-513: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-524: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry LAB-535: record the request in the pending owner-verification queue; this entry is not the named exception route.

Process water sampling - operating guide

CURRENT 2026; effective 1 August 2026

Document control: this 2026 operating guide is CURRENT and effective from 1 August 2026. The 2024 edition is archived and superseded. No forecast for a later year is stated.

The active 2026 utilities sampling plan requires water-loop sampling twice per shift.

Collection frequency is a sampling-plan rule. Waste routing and release specifications are distinct references.

The reference annex has its own scope. Staff should distinguish operational permission from commercial price, evidence retention and service specifications. Publication of a code or a process owner does not create a missing technical limit or a financial guarantee.

Amendment log: this edition consolidates the current timing rule and ownership path. Historical examples remain in the archive for traceability. They are not exceptions to the current rule. A request citing an older edition must be checked against the effective document before execution.