

Q2 Q4

C13

C10 C8 C9 R17

C12 C11

C7 R16

R26 R27 R18 C14

R21 R22 R23 R24 C20 C21 C22 R20 C19 C18 C17 R19 C16 ferrite bead C15

R25 ■